Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR

OFFICIAL FILE COPY TION

FORM APPROVED OMB NO. 1004-0137

BI	JREAU OF LAND MANAGEME	ENT SUA OIL CO	NSCIOICI		nuary 31, 2018		
BUREAU OF LAND MANAGEMENT AND OIL CONSCIPLING OF LAND MANAGEMENT ARTESIA DISTRICT SUNDRY NOTICES AND REPORTS ON WELLS OCD Artesia 2018 Do not use this form for proposals to drill or to re-enter an JUN 2 2018 abandoned well. Use form 3160-3 (APD) for such proposals.				5. Lease Serial No. NMLC061616A  6. If Indian, Allottee or Tribe Name			
1. Type of Well				8. Well Name and No. POKER LAKE UNIT 348H			
☑ Oil Well ☐ Gas Well ☐ Oth							
2. Name of Operator Contact: TRACIE J CHERRY BOPCO LP E-Mail: tracie_cherry@xtoenergy.com				9. API Well No. 30-015-38669-00-S1			
3a. Address 6401 HOLIDAY HILL RD BLDG 5 SUITE 200 MIDLAND, TX 79707  3b. Phone No. (include area code) Ph: 432-221-7379				10. Field and Pool or Floratory Area POKER LAKE Farple Sass UNKNOWN Wolfcarp			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State			
Sec 3 T25S R30E SWSE 8145FSL 1630FEL 32.154556 N Lat, 103.865008 W Lon				EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, I	REPORT, OR OTH	IER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
	☐ Acidize	☐ Deepen	☐ Production	on (Start/Resume)	☐ Water Shut-	Off	
☐ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamat	,	☐ Well Integr	ity	
■ Subsequent Report	☐ Casing Repair	□ New Construction	☐ Recompl		Other	,	
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon		rily Abandon			
<b>..</b>	Convert to Injection	☐ Plug Back		☐ Water Disposal			
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final At determined that the site is ready for f BOPCO, LP respectfully submod/106/18 - MIRU. TIH to 8628'. Pump 45 04/11/18 - 104/13/18 PUH. Circ. salt gel mud from 8 - 5685'. WOQ. Tag TOC @ 56	ally or recomplete horizontally, give so the will be performed or provide the Bolloperations. If the operation results in an andonment Notices must be filed only inal inspection.  This this sundry notice for plug as sx Class H to 8405'. WOC. Talk 3240 to surface. PT csg to 500 to 577. RIH w/pkr to 3394', PT belate. Notify BLM. Pump 85 sx Carrelators.	ubsurface locations and measure and No. on file with BLM/BIA. a multiple completion or record after all requirements, including and abandonment of the game and abandonment of the game and abandonment of the part of the game and abandonment of the game an	red and true ver Required sub- impletion in a ne ng reclamation. referenced w Class C, 59 Perf 4080'.	tical depths of all pertin sequent reports must be sew interval, a Form 316, have been completed a rell.  IN ECL  OO'  RECLAMA	ent markers and zo filed within 30 day 0-4 must be filed or	nes. s nce	
, , , ,	O LP, sent to the Carlsbac by DEBORAH MCKINNEY	RAH MCKINNEY on 06/06/2018 (18PP1173SE)					
Signature (Electronic S	Submission)	Date 06/06/20	)18	LOOFOTED	FOR 5000		
	THIS SPACE FOR F	EDERAL OR STATE (	OFFICE US	FOULTED	FUR RECU	עא	
Approved By Conditions of approval, if any, are attache	Title		JUN 1	8 2078 <sup>te</sup>			
certify that the applicant holds legal or equ	ct lease	}	flm	b			
which would entitle the applicant to condu	Office		RIVERALL OF LAN	ID MANACEMEN	r		

## Additional data for EC transaction #422826 that would not fit on the form

## 32. Additional remarks, continued

RIH tag TOC @ 3637'. Call BLM, okay to continue. RIH set pkr @ 951', PT csg to 500 psi from 3637' - 951'. Shoot sqz holes at 1456'. Establish injection rate. Mix and pump 95 sxs Class C cmt. WOC

04/17/18
RIH and tag TOC 1110'. Perf sqz holes @ 60'. Set pkr at 15', establish injection rate. Mix and pump 35 sxs Class C to surface.

04/27/18 Cut off WH. Install DHM. Well P&A'd



# **United States Department of the Interior**

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

### **Reclamation Objectives and Procedures**

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612