

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons.
N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other Instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Bill & Patsy Rich

3a. Address

2401 MARTIN LN - CARLSBAD NM, 88505-8873

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 13 - T. 25S, R. 26E
1980 FNL & 1980 FWL

3b. Phone No. (include area code)

505-887-3928

5. Lease Serial No.

NM 29881

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Sulphate Sister

9. API Well No.

30-015-21029

10. Field and Pool, or Exploratory Area

11. County or Parish, State

Eddy, N.M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

SWD

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

ALL work Completed -- 5-7-03
Except Surface Cleanup
See Attached

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

ACCEPTED FOR RECORD

JUN 20 2003

LES BABYAK
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Patsy Rich

Signature

Patsy Rich

Title

Owner

Date

6-7-03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

BILLY & PATSY RICH

Lease: SULFATE SISTER # 1

Project: P & A – CEMENTING REPORT

05-02-2003 - SET CIBP @ 1900' – SPOT 25 SXS CEMENT ON TOP – 1650'

05-05-2003 – PULL 1130' OF CASING

05-05-2003 – SPOT 55 SXS @ 1181'-1068' TAG

05-05-2003 – SPOT 60 SXS @ 497'-402' & TAG

05-06-2003 - SPOT 35 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER

CIRCULATE 10# MUD

MAYO MARRS CASING PULLING INC.

BILL & PATSY RICH

Lease: SULFATE SISTER # 1

Project: P & A

JOB # 03-

5-01-03

NOTIFY BLM - MIRU - LEVEL LOCATION & DIG PIT- CUT CAP OFF WELLHEAD - NUBOP -
CLOSE IN WELL

5-02-03

COULD NOT RELEASE PACKER - WORK 3 HRS - DO MANUAL BACKOFF - POOH WITH 1080'
RIH WITH MMCPI WORKSTRING - SCREW BACK INTO FISH - WORK ANCHOR LOOSE - POOH
WITH FIBERGLASS TUBING(67 JOINTS) LAYING DOWN - RIH & SET 4 1/2" CIBP @ 1900' - RIH
WITH MMCPI WORKSTRING & CIR. 10# MUD - SPOT 25 SXS @ 1900'-1650' - PER HOMER
SAENZ BLM - POOH WITH TUBING CLOSE IN WELL
(7 HR RIG TO CHANGE OUT TUBING, FISH & WORK ANCHOR LOOSE)

5-05-03

RIH & TAG @ 1430' - WELD ON PULL NIPPLE - CUT CASING @ 1130' - LAY DOWN CASING -
RIH & SPOT 55 SX @ 1181' - POOH - WOC - RIH & TAG @ 1068' - POOH & SPOT 60 SXS @ 497'
POOH - CLOSE IN WELL

5-06-03

RIH & TAG @ 402' - POOH & SPOT 35 SXS @ 60' TO SURFACE - POOH & INSTALL DRY HOLE
MARKER - RIG DOWN CUT OFF WELLHEAD & ANCHORS - SUCK OUT CELLAR & PIT -
LEVEL PIT & CELLAR - MOVE OUT

MMCPI WORKSTRING

7 HRS RIG TIME

BID 60 SXS USED 175

BID \$ 7,820.00