Form 31(0-5 (June 2015)

UNITED STATES

FORM APPROVED

| I ORIGINATED |
|---------------------------|
| OMB NO. 1004-0137 |
| Expires: January 31, 2018 |
| |

OCT 8 2018


| א ועו | | anuary 31, 2018 | | | |
|--|------------------------------------|---|--|---------------------------------------|--|
| BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS OF WEST 301 Field Of Management (1998) 5. Lease Serial No. 5. Lease Serial No. 5. Lease Serial No. 6. Control of Management (1998) 6. Control of Management (1998) 6. Control of Management (1998) 6. Lease Serial No. 7. Lease Serial No. 7. Lease Serial No. 8. Lease Serial No. | | | | | |
| Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. A I 1 CSI 6. If Indian, Allottee or Tribe Name | | | | | |
| SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well Soil Well Gas Well Other Contrain DEBI CORDON | | | | ement, Name and/or No. | |
| Type of Well | 8. Well Name and No TURNER B 12 | 8. Well Name and No. TURNER B 12 | | | |
| 2. Name of Operator Contact: DEBI GORDON LINN OPERATING INCORPORATED E-Mail: DGORDON@LINNENERGY.COM | | | 9. API WEII NO. | 9. API Well No. 30-015-05284-00-S1 | |
| 3a. Address 600 TRAVIS STREET SUITE 5100 HOUSTON, TX 77002 | | 3b. Phone No. (include area code) Ph: 281-840-4010 Fx: 832-209-4340 | a code) 10. Field and Pool or Exploratory Area GRAYBURG JACKSON | | |
| 4. Location of Well (Footage, Sec., 7 | T., R., M., or Survey Description |) | 11. County or Parish, | State | |
| Sec 20 T17S R31E NWSW 2 | 080FSL 660FWL | | EDDY COUNT | EDDY COUNTY, NM | |
| 12. CHECK THE A | PPROPRIATE BOX(ES) | TO INDICATE NATURE OF | NOTICE, REPORT, OR OT | HER DATA | |
| TYPE OF SUBMISSION | TYPE OF ACTION | | | | |
| Notice of Intent | ☐ Acidize | Deepen | ☐ Production (Start/Resume) | ■ Water Shut-Off | |
| | ☐ Alter Casing | ☐ Hydraulic Fracturing | ☐ Reclamation | ■ Well Integrity | |
| ☐ Subsequent Report | ☐ Casing Repair | ■ New Construction | ☐ Recomplete | Other | |
| ☐ Final Abandonment Notice | ☐ Change Plans | ☐ Plug and Abandon | ☐ Temporarily Abandon | | |
| | Convert to Injection | Plug Back | ☐ Water Disposal | | |
| 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. LINN OPERATING, LLC IS RESPECTFULLY SUBMITTING A REQUEST TO PERFORM REMEDIAL OPERATIONS TO RETURN | | | | | |
| THE WELL TO INJECTION FOR THE REFERENCED WELL LOCATED IN EDDY COUNTY, NM. THIS WELL FAILED AN MIT AND CORRECTIVE ACTION NEEDS TO BE COMPLETED. | | | | | |
| THE PROPOSED REMEDIAL PROCEDURE AND WELLBORE DIAGRAMS ARE ATTACHED FOR REVIEW AND APPROVAL. | | | | | |
| A NEW MEXICO OCD C103 SUNDRY IS BEING FILED WITH THE ARTESIA FIELD OFFICE FOR LIKE APPROVAL | | | | | |
| Notify Bus when Performed work? TESTS A NEW MEXICO OCD C103 SUNDRY IS BEING FILED WITH THE ARTESIA FIELD OFFICE FOR LIKE APPROVAL RECEIVED NOTIFY Bus when Performed work? TESTS OCT 2 5 2018 14. I hereby certify that the foregoing is true and correct. | | | | | |
| NOTIFY BLM WHEN PERFORMING WOR | | WORK STESTS | OCT 2 | OCT 2 5 2018 | |
| 14. I hereby certify that the foregoing is true and correct. Electronic Submission #394962 verified by the BLM Well Information System For LINN OPERATING INCORPORATED, sent to the Carlsbad DISTRICT II-ARTESIA O.C.D. Committed to AFMSS for processing by DEBORAH MCKINNEY on 09/05/2018 (18DLM0650SE) | | | | | |
| Name (Printed/Typed) DEBI GO | Title REGULA | ATORY MANAGER | | | |
| Signature (Electronic | Submission) | Date 11/14/20 | 117 | | |
| THIS SPACE FOR FEDERAL OR STATE OFFICE USE | | | | | |


Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject ease which would entitle the applicant to conduct operations thereon. Carlsbad Field Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Approved By

/s/ Jonathon Shepard

Petroleum Engineer







TURNER B 12 API#: 30-015-05284 Eddy County, New Mexico

REMEDIAL PROCEDURE TO RETURN WELL TO INJECTION

- 1. MIRU WOR, Hold PJSM
- 2. ND WH, NU BOPs
- 3. Unset AD-1 Pkr @ 1,844', POOH w/ Pkr & stand back 59 jts 2-3/8" IPC tbg
- 4. Unload workstring
- 5. PU & RIH w/ RBP & Pkr on WS
- 6. Set RBP @ +/- 1,840'
- 7. Set Pkr @ pressure test RBP to 500 psi
- 8. Dump 10' sand on top of RBP
- 9. Isolate csg leak w/ Pkr
- 10. Obtain two separate pump-in rates and pressures
- 11. Plan squeeze job w/ cement company & engineers
- 12. MIRU cement company, Hold PJSM
- 13. Establish injection rate and squeeze csg leak
- 14. RD cement company & WO cmt
- 15. Release pkr & POOH w/ tbg
- 16. PU & RIH w/ 4-3/4" bit & drill collars
- 17. DO cmt & RIH to RBP @ 1,840', circ hole clean
- 18. Pressure test squeeze to 500 psi
- 19. POOH w/ tbg & LD bit & drill collars
- 20. RIH w/ retrieving tool and retrieve RBP @ 1,840'
- 21. POOH laying down WS & RBP
- 22. RIH w/ injection tubing as follows

59 jts 2-3/8" IPC Tbg 2-3/8" L-10 On/Off Tool w/ 1.87" ID Profile 5-½" AD-1 Pkr @ +/- 1,844' 6' x 2-3/8" IPC pup jt 2-3/8" WLRG

- 23. Circulate Pkr fluid & set Pkr @ +/- 1,844'
- 24. Pressure test backside to minimum of 350 psi
- 25. ND BOPs, NU WH
- 26. RDMO WOR
- 27. Notify OCD & Perform MIT test