Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM1372

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
bandoned well. Use form 3160-3 (APD) for such proposals.	

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ement, Name and/or No.		
Type of Well     Gas Well □ Other					8. Well Name and No. WARREN ANW FED 1			
Name of Operator Contact: TINA HUERTA     EOG Y RESOURCES INC E-Mail: tina_huerta@eogresources.com				9. API Well No. 30-015-27748-0	0-S1			
3a. Address 104 S 4TH STREET ARTESIA, NM 88210		3b. Phone No Ph: 575-74	. (include area code) 8-4168		10. Field and Pool or I PENASCO DRA			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	j			11. County or Parish,	State		
Sec 9 T19S R25E NWSW 198	30FSL 660FWL				EDDY COUNTY	′, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA		
TYPE OF SUBMISSION			TYPE OF	ACTION				
Notice of Intent	☐ Acidize	☐ Dee	реп	☐ Product	ion (Start/Resume)	■ Water Shut-Off		
Notice of Intent	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity		
☐ Subsequent Report	□ Casing Repair	☐ Nev	Construction	□ Recomp	olete	□ Other		
☐ Final Abandonment Notice	☐ Change Plans	🔀 Plug	g and Abandon	Tempor	arily Abandon			
	☐ Convert to Injection	Plug	g Back	☐ Water I	Disposal			
testing has been completed. Final Abdetermined that the site is ready for fit EOG Y Resources, Inc. plans  1. MIRU all safety equipment at 2. RIH with GR/JB to PBTD at 3. Set a CIBP at 2150 ft. Load 4. Spot a 25 sx Class C ceme over open perforations and Gl 5. Perforate at 1095 ft. Attemp 6. Spot a 25 sx Class C ceme across 9-5/8 inch casing shoe 7. Spot a 25 sx Class C ceme top.	to temporarily abandon to temporarily abandon to temporarily abandon to as needed. POOH with a 2170 ft.  hole with plugging mud. nt plug from 2000 ft - 215 or to establish circulation. nt plug from 965 ft - 1095 or the plug from 575 ft - 725 ft.	his well as fol all production 50 ft. WOC and	lows: equipment. d tag. This will pl tag. This will pla ace a plug across	ace a plug ce a plug	SEE ATTACH CONDITIONS NM OIL C ARTES NOV	ED FOR OF APPROVAL ONSERVATION STA DISTRICT 28 2018		
14. I hereby certify that the foregoing is	Electronic Submission #	RESOURCES	NC, sent to the C	arlsbad	n System	CEIVED		
Name (Printed/Typed) TINA HUE		,		ATORY SP	,			
Signature (Electronic S			Date 11/06/20					
	THIS SPACE FO	OR FEDERA	L OR STATE (	OFFICE U	SE 	<del> </del>		
Approved By  Conditions of approval, if any, are attached certify that the applicant holds legal or equivilient would entitle the applicant to conduct the second of the s	uitable title to those rights in the	e subject lease	Office CFC	16 T	also to any denoting the	Date Printed		
States any false, fictitious or fraudulent s	statements or representations as	s to any matter w	ithin its jurisdiction.	willing to ma	аке то апу пераптепі ог	agency of the United		

## Additional data for EC transaction #442886 that would not fit on the form

#### 32. Additional remarks, continued

32. Additional remarks, continued
8. Spot a 10 sx Class C cement plug from 10 ft up to surface.
9. Cut off wellhead. Install Dry Hole marker. Clean location.

Wellbore schematics attached

WELL NAME: Warren AN			Γ	CASING PROGRAM		
LOCATION: 1980' FSL & C	660' FVVL Sec. 9-198-	<u>25E</u>				
GL:_ZERO:KB:_	0.045.07740	<del></del>	9 5/8" 36# J-5	5 1,045'		
COMMENTS: API No.: 3	U-U15-21140					
<del></del>			7° 29# N-80	8,274'		
1.		10sx Class "C" cmt plug @	0 60' – Surface			
	\  \  \  \  \		9 00 04.1400			
	, (   /			After		
/				711661		
<b>}</b> \		25sx Class "C" cmt plug @	<b>2</b> ) 575' – 725'			
14 3/4"Hole	<u> </u>	(SA Top)		7000		
\/				TOPS		
<b>\</b> \		) 25sx Class "C" cmt plug @	D 965' –	San Andres 675'		
		1,095' (9 5/8" Csg Shoe)		Glorieta 2,105'		
9 5/8" Csg @ 1,045' Cmt'd w/ 930sx (	17)			Wolfcamp 5,525'		
<del></del>	T) ()			Canyon 7,650'		
		CIBP @ 2,150' w/ 25sx Class	s "C" cmt plua @	2.000' – 2.150' (Open		
8 3/4" Hole	/ P	Perfs & Glorieta Top)	, ,	, , , , , , , , , , , , , , , , , , , ,		
0 0/1 110/0		Perfs: 2,206' - 2,410'				
		, 5,10, 2,200				
	35sx cmt plug @ 3,094' – 3,365'					
DV @ 5,599'	4	0sx cmt plug @ 5,414' - 5,6	668'			
	1/ 1/	•				
	( )					
		CIBP @ 7,746' w/ 25sx Class	s cmt @ 7,616' -	7,746'		
	1 -	erfs: 7,796' – 7,839'	-			
				Not to Costs		
	7	Csg @ 8,274' Cmt'd w/ 1525sx (0	Circl	Not to Scale 11/2/18		
	PBTD: 8,274'	Oug to Oper + Child W 1020SX (C	onoj .	JE		

Total to the season seements

WELL NAME: Warren ANW Federal #1 FIELD: **CASING PROGRAM** LOCATION: 1980' FSL & 660' FWL Sec. 9-19S-25E GL:\_ZERO:\_\_\_\_\_KB:\_\_\_\_ 9 5/8" 36# J-55 1,045' **COMMENTS**: API No.: 30-015-27748 7° 29# N-80 8,274' **Before** 14 3/4"Hole / **TOPS** San Andres 675'~ Glorieta 2,105' 9 5/8" Csg @ 1,045' Cmt'd w/ 930sx (1") Wolfcamp 5,525' ~ 7,650'-Canyon 1" from 610' 8 3/4" Hole Perfs: 2,206' - 2,410' 35sx cmt plug @ 3,094' - 3,365' DV @ 5,599' ~ 40sx cmt plug @ 5,414' - 5,668' CIBP @ 7,746' w/ 25sx Class cmt @ 7,616' - 7,746' Perfs: 7,796' - 7,839' Not to Scale

7" Csg @ 8,274' Cmt'd w/ 1525sx (Circ)

PBTD: 8,274'

11/2/18

JE

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.