

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

Lease Serial No.
NMLC028784A

If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit or CA/Agreement, Name and/or No.
NMNM88525X

8. Well Name and No.
BURCH KEELY UNIT 387

9. API Well No.
30-015-33812-00-S1

10. Field and Pool or Exploratory Area
BURCH KEELY-GLORIETA-UPR YES

11. County or Parish, State
EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Venting and/or Flaring
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Burch Keely Sec. 13B Battery
Actual gas flared for this battery for 3/1/2018 TO 5/30/2018 is as follows:
(Permit approval: Electronic Submission (#404891)
March
Total for Battery = 0 MCF
April
Total for Battery = 0 MCF
May
Total for Battery = 1559 mcf

Number of wells to flare: (28)
BURCH-KEELY UNIT 32 30-015-20398

NM OIL CONSERVATION
ARTESIA DISTRICT
DEC 12 2018
Accepted for record
NMOCD
RECEIVED

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #445368 verified by the BLM Well Information System

For COG OPERATING LLC, sent to the Carlsbad

Committed to AFMSS for processing by PRISCILLA PEREZ on 11/30/2018 (19PP0471SE)

Name (Printed/Typed) SANDY BALLARD

Title SENIOR ADMINISTRATIVE ASSISTANT

Signature (Electronic Submission)

Date 11/28/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

NOV 30 2018

/s/ Jonathon Shepard

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #445368 that would not fit on the form

32. Additional remarks, continued

BURCH-KEELY UNIT 387 30-015-33812
BURCH-KEELY UNIT 391 30-015-33805
BURCH-KEELY UNIT 392 30-015-33809
BURCH-KEELY UNIT 537 30-015-40182
BURCH-KEELY UNIT 539 30-015-40319
BURCH-KEELY UNIT 540 30-015-40321
BURCH-KEELY UNIT 541 30-015-40662
BURCH-KEELY UNIT 542 30-015-39521
BURCH-KEELY UNIT 544 30-015-40322
BURCH-KEELY UNIT 545 30-015-40323
BURCH-KEELY UNIT 546 30-015-40324
BURCH-KEELY UNIT 577 30-015-39524
BURCH-KEELY UNIT 580 30-015-40270
BURCH-KEELY UNIT 581 30-015-40271
BURCH-KEELY UNIT 584 30-015-40273
BURCH-KEELY UNIT 588 30-015-40702
BURCH-KEELY UNIT 617 30-015-40704
BURCH-KEELY UNIT 625 30-015-40326
BURCH-KEELY UNIT 640 30-015-40328
BURCH-KEELY UNIT 652 30-015-40279
BURCH-KEELY UNIT 858 30-015-40382
BURCH-KEELY UNIT 906 30-015-40887
BURCH-KEELY UNIT 943H 30-015-39575
BURCH-KEELY UNIT 944H 30-015-44079
BURCH-KEELY UNIT 945H 30-015-39578
BURCH-KEELY UNIT 962H 30-015-44101
BURCH-KEELY UNIT 963H 30-015-39576

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT MAINTENANCE AND HLP