Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT 5. Lease Serial No.

<u> </u>	NOTICES AND REPORTS form for proposals to II. Use form 3160-3 (API		7 If Unit or Co	A/Agreement, Name and/or No.	
SUBMIT IN TRIPLICATE - Other instructions on page 2				NMNM88525X	
1. Type of Well ☐ Gas Well ☐ Other			8. Well Name a BURCH KE	ind No. EELY UNIT 387	
2. Name of Operator Contact: SANDY BALLARD			9. API Well No.	o. 8812-00-S1	
COG OPERATING LLC E-Mail: sballard@concho.com 3a. Address 3b. Phone No. (include area code)					
600 W ILLINOIS AVENUE MIDLAND, TX 79701		Ph: 432-686-4373	BURCH K	10. Field and Pool or Exploratory Area BURCH KEELY-GLORIETA-UPR YES	
4. Location of Well (Footage, Sec., T)	11. County or Parish, State			
Sec 24 T17S R29E NENE 330)FNL 330FEL		EDDY CO	DUNTY, NM	
12. CHECK THE A	PROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE, REPORT, OF	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resu	me)	
□ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturin	g Reclamation	■ Well Integrity	
Subsequent Report	□ Casing Repair	□ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon	Venting and/or Flari ng	
	☐ Convert to Injection	Plug Back	■ Water Disposal	-	
following completion of the involved testing has been completed. Final At determined that the site is ready for final Burch Keely Unit #387 Burch Keely Sec. 13B Battery Actual gas flared for this batte (Permit approval: Electronic S	pandonment Notices must be filinal inspection. ery for 5/31/2018 TO 8/29/	ed only after all requirements, incl	ecompletion in a new interval, a Fo	orm 3160-4 must be filed once pleted and the operator has	
May Total for Battery = 0 MCF			, , , a , a , a	· ACHOEDWATION	
June Total for Battery = 0 MCF			NM OI	L CONSERVATION RTESIA DISTRICT	
July Total for Battery = 1327 MCF			12/11/11/8/12	ner 1 9 2018	
August Total for Battery = 0 mcf		Λcc	cepted for record		
Total for Battery – O mor			NMOCD	RECEIVED	
14. I hereby certify that the foregoing is				.,	
0	For COG O	445360 verified by the BLM W PERATING LLC, sent to the	Carlsbad		
			on 11/30/2018 (19PP0468SE) OR ADMINISTATIVE ASSIS		
Name (Printed/Typed) SANDY F		J. J		·	
Name (Printed/Typed) SANDY E					
Name (Printed/Typed) SANDY E Signature (Electronic S	Submission)	Date 11/28	/2018		
		Date 11/28			
		R FEDERAL OR STAT			

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. /s/ Jonathon Shepard Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. LAND MANAGEMENT

Office

NOV 3 0 2018

Additional data for EC transaction #445360 that would not fit on the form

32. Additional remarks, continued

Number of wells to flare: (28)
BURCH-KEELY UNIT 32 30-015-20398
BURCH-KEELY UNIT 387 30-015-33812
BURCH-KEELY UNIT 387 30-015-33809
BURCH-KEELY UNIT 392 30-015-33809
BURCH-KEELY UNIT 537 30-015-40182
BURCH-KEELY UNIT 539 30-015-40319
BURCH-KEELY UNIT 540 30-015-40321
BURCH-KEELY UNIT 540 30-015-40321
BURCH-KEELY UNIT 544 30-015-40322
BURCH-KEELY UNIT 545 30-015-40322
BURCH-KEELY UNIT 545 30-015-40323
BURCH-KEELY UNIT 546 30-015-40324
BURCH-KEELY UNIT 546 30-015-40324
BURCH-KEELY UNIT 577 30-015-39524
BURCH-KEELY UNIT 580 30-015-40270
BURCH-KEELY UNIT 588 30-015-40271
BURCH-KEELY UNIT 588 30-015-40271
BURCH-KEELY UNIT 658 30-015-40273
BURCH-KEELY UNIT 677 30-015-40273
BURCH-KEELY UNIT 688 30-015-40702
BURCH-KEELY UNIT 689 30-015-40328
BURCH-KEELY UNIT 695 30-015-40328
BURCH-KEELY UNIT 695 30-015-40328
BURCH-KEELY UNIT 969 30-015-40382
BURCH-KEELY UNIT 943H 30-015-39575
BURCH-KEELY UNIT 944H 30-015-39575
BURCH-KEELY UNIT 945H 30-015-44079
BURCH-KEELY UNIT 945H 30-015-44079
BURCH-KEELY UNIT 945H 30-015-44079
BURCH-KEELY UNIT 945H 30-015-39578
BURCH-KEELY UNIT 945H 30-015-39578
BURCH-KEELY UNIT 945H 30-015-39578
BURCH-KEELY UNIT 945H 30-015-39578

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT MAINTENANCE AND HLP