Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-015-26670
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name Clifford ADD
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number
1. Type of Well: Oil Well	Gas Well Other	2
2. Name of Operator EOG Y Resources, Inc.		9. OGRID Number 025575
3. Address of Operator		10. Pool name or Wildcat
104 South Fourth Street, Artesia,	NM 88210	Dagger Draw; Upper Penn, North
4. Well Location Unit Letter 1 :	1980 feet from the South line and	660 feet from the <u>East</u> line
Section 35	Township 19S Range 24E	NMPM Eddy County
	11. Elevation (Show whether DR, RKB, RT, GR, et	c.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check	Appropriate Box to indicate Nature of Notice	e, Report of Other Data
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐	_	RILLING OPNS.□ PAND A □ NT JOB □
DOWNHOLE COMMINGLE	MOETIFLE COMFL GASING/CLIME	M1 30B
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
	oleted operations. (Clearly state all pertinent details, a ork). SEE RULE 19.15.7.14 NMAC. For Multiple C	
proposed completion or re-		ompletions. Attach wendore diagram of
EOG Y Resources, Inc. plans to ten	nporarily abandon this well as follows:	alor to
1 MIDII all cafety equipment as n	eaded TOU with production aguinment	othly OCD 24 hrs . prior to
<ol> <li>MIRU all safety equipment as needed. TOH with production equipment.</li> <li>Set an RBP at 7162' and dump 2 sx sand on top.</li> </ol>		
3. Conduct MIT and chart for the l		
4. NU WH and shut well in.		
Wellbore schematics attached	TA status may be granted arte ossful MIT test is perform	ra RECEIVED
.,	aus may be granted	ed.
	TA status may be granted after successful MIT test is perform successful MIT test is perform contact the OCD to schedule	the test DEC 1 7 2018
	Contact the OCD to seed.  so it may be witnessed.	DISTRICT II-ARTESIA O.C.D.
	50 10	•
	LAST Pr	01 4-2018
Spud Date:	Rig Release Date:	
· L		
I hereby certify that the information	above is true and complete to the best of my knowled	ge and belief.
SIGNATURE SIENATURE	TITLE Regulatory Special	ist DATE December 14, 2018
Type or print name Tina Hu		
For State Use Only	erta E-mail address: tina_huerta@eogresou	rces.com PHONE: <u>575-748-4168</u>
Tot State Coe only	erta E-mail address: tina_huerta@eogresou	rces.com PHONE: <u>575-748-4168</u>
	E-mail address: tina huerta@eogresou	rces.com PHONE: <u>575-748-4168</u>



