UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD ARRECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

IAN 1 0 2019

5.	Lease Serial No.	
	NMLC068282B	

	NOTICES AND REPO s form for proposals to			1 0 2013	NMLC068282B	
abandoned we	I. Use form 3160-3 (AP	D) for such pro	posals. DISTRICT II-	ARTESIA O	6. If Indian, Allottee of C.D.	or Tribe Name
SUBMIT IN	TRIPLICATE - Other ins	tructions on pa				ement, Name and/or No.
Type of Well ☐ Gas Well ☐ Other				8. Well Name and No. GOLDEN SPUR 25 FBS 3H		
Name of Operator CONOCOPHILLIPS COMPAN				ES.COM	9. API Well No. 30-015-41230-00-S1	
3a. Address MIDLAND, TX 79710 1810	-	3b. Phone No. (Ph: 432-563- Fx: 432-563-3			10. Field and Pool or WC 015 G 05 S	Exploratory Area 263125N
4. Location of Well (Footage, Sec., T	R. M. or Survey Description	<u> </u>	304		11. County or Parish,	State
Sec 25 T26S R31E SWSW 46		,			EDDY COUNT	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE,	REPORT, OR OTI	HER DATA
TYPE OF SUBMISSION			TYPE O	F ACTION		
S Nation of Intent	☐ Acidize	□ Deepe	n	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Hydra	ulic Fracturing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	□ New (Construction	Recomp	olete	□ Other
☐ Final Abandonment Notice	Change Plans	🔀 Plug a	☑ Plug and Abandon ☐ Tempo		arily Abandon	
	☐ Convert to Injection	Convert to Injection		□ Water I	Disposal	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) MIRU. ND WH, NU BOP 2) RIH Tbg - Tag BP @ 8797' 3) Spot 25sx cmt @ 8797'-867 4) Spot 45sx cmt @ 665'-658 5) Spot 25sx cmt @ 5104'-498 6) Spot 30sx cmt @ 4184'-394 7) Perf & Sqz 40sx cmt @ 278 8) Perf & Sqz 150sx cmt @ 49 9) Perf & Circ 25sx cmt @ 60' 10) POOH, top off well. RDMC	Andonment Notices must be final inspection. Circ hole w/ MLF. Press 17' 35' - WOC-Tag 4' - 5154' - 5004 2'. WOC-Tag - 4 2 3 14'-2691'. WOC-Tag - 17'-691'. WOC-Tag - 11' 3' Cut off WH & anchors,	sure test csg. Since test csg.	hould 7	ling reclamation	n, have been completed. 198 (1/27/1994) A 3. IF3 BLE ATTACH CONDITIONS	and the operator has 7). If Not ood tag on:
	mitted to AFMSS for proc	PHILLIPS COMP essing by PRISC	ANY, sent to th	e Carlsbad n 11/09/2018	•	
Name (Printed/Typed) GREG BR	YANI		fitle AGENT	·		
Signature (Electronic S	ubmission)	1	Date 11/09/2	018		
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE U	SE	
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equ	d. Approval of this notice does	not warrant or	Title SY	16T		12.14.18 Date
which would entitle the applicant to condu			Office (FC	7		

Title 18-U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

	RKS @ 3169'					į.	Date 10/9/2018
	DF @ 3169						
	GL @: 3144	= 171/2 hole		Subarea	Red Hills		
		Surface -13-3/8", 54.5#/ft to 10	167:	Lease & Well N		Golden Spur Federal FBS 25-3H	
	111 1		707 -	Legal Description County	Eddy	SEC 25, T-26-S, R-31-E 465 FE State Nov	w Mexico
		Circ'd to surface		Field	Wild Cat		W INEXICO
				Date Spudded		8/20/2013	
		12'4" hole		API Number	30-015-4	1230	
1137	WI I	Intermediate - 9.5/8" Apr to 6674	5'			Operator Number	
1191	$n \mid 1$	Cmt'd w/ 3435 SX	1st stage d	da deine		Lease ID	
		Circ d to surface	JUE CLARE	1.1.4.		Field Number	
		Stage Tool@ 3992' KB	2 71.5	0.,44,	., , ,		
	Ш						
4000		External Casing Packer@ 3995'	кв				
		Float Collar @ 6584'KB					
			6645				
			Q (2 -1,5				
		1					
		Production1 - 5-1/2", 17# to 14,127	· ~				
		Cmt'd w/ 1680 SX					
		TOC 3965'_ Vol Calc					
		-				12 67	7 2 1
						Karyle C	191
						Salado	1071
						Pastle r Salado Castile	2 7 C /
							• •
						1 1 1	() , , , ,
						Be. !! Cr.	4184
						•	·
	'					<i>n</i> (<i>a</i>	5101
						Chapter Ch	510.1
						\sim	7925 7925 9841
						Keus hy C	69/25
						70	-0-
						$\mathcal{D}^{0,2}$	1925
						Done 2p.	9841
		6742' KB_Mono-Fit X-SPAN System	n				
		21.6' long patch				ω \subset	11432
		10,000 psi rated					
		Stage Tool@ 6747' KB	•				
		External Casing Packer@ 6749' KB					
		7.6	@ 8498 SX Clas	3			
		CIBP @ 8797' - +30	SX Clas	s C			
	XIXIX	CIBF (g) 6797		•	Bone Sp	ring n Hoizontal Lateral 9822' - 14,072'	W.D.
		1				D) 9460.5' - Btm (TVD) 9473'	NB
					Frac stin	nulated w/ 20 stages	TD_ (TVD) 9471.61
		ik .					TD @ 14.160'.(MD)
		? I Ab		┸┵┸┸	11 11-14-		+11-12
	÷ .						ig Is
	× -			 	B1.1-19-		
	A	; — " " " " " " " " " " " " " " " " " "			1111		1.1.1.
						d/' = ±	1 , , , ,
						5/2 17	P.110
						5/2 17 ± 10 C	
						700	3965

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

RKB @ 3169'

Date: 10/9/2018

DF @ 3169 GL @: 3144 Subarea Red Hills West Lease & Well No Golden Spur Federal FBS 25-3H Surface -13-3/8", 54.5#/ft to 1067' Legal Description SEC. 25. T-26-S, R-31-E 465 FEL. 530 FWL Cmt'd w/ 920 SX County Eddy State New Mexico Circ'd to surface Field Wild Cat P&S 25sx cmt @ 60'-3' Date Spudded 8/20/2013 API Number 30-015-41230 P&S 150sx cmt @ 1117'-691' - Tag Intermediate - 9-5/8", 40# to 6635" Operator Number Cmt'd w/ 3435 SX Lease ID. Circ'd to surface Field Number P&S 40sx cmt @ 2751'-2631' - Tag Stage Tool@ 3992' KB External Casing Packer@ 3995' KB Spot 30sx cmt @ 4184'-3942' - Tag Production1 - 5-1/2", 17# to 14,127' Cmt'd w/ 1680 SX TOC 3965'_ Vol Calc Spot 25sx cmt @ 5104'-4984' Float Collar @ 6584'KB 6742' KB_Mono-Fit X-SPAN System 21.6' long patch 10,000 psi rated Stage Tool@ 6747' KB External Casing Packer@ 6749' KB Spot 45sx cmt @ 6955'-6585' - Tag Spot 251x cmt @ 8797" 167. XIXIX CIBP @ 6797' Bone Spring Perfed in Hoizontal Lateral 9822' - 14,072' KB Top (TVD) 9460.5' - Btm (TVD) 9473' Frac stimulated w/ 20 stages TD_ (TVD) 9471.6" TD @ 14,160' (MD) ाध 1

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.