Form	3160-5
(June	2015)

Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such DISTRICT II-ARTESIA O.C.C SUBMIT IN TRIPLICATE - Other instructions on page 2			FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM88139 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.			
21	1. Type of Well 2 Oil Well Gas Well Other			8. Well Name and No. WOOD DRAW 35 FEDERAL 3		
2. Name of Operator OXY USA INC	Contact: E-Mail: david_ste				9. API Well No. 30-015-35568	
3a. Address P.O. BOX 50250 MIDLAND, TX 79710		3b. Phone No. (include area code)10. Field and Pool or Explore CORRAL CANYON IPh: 432-685-5717CORRAL CANYON I		Exploratory Area YON DELAWARE,NW		
4. Location of Well (Footage, Sec. T., R., M., or Survey Description) Sec 2 T24S R29E NENW 150FNL 2310FWL 32.165905 N Lat, 103.956261 W Lon				11. County or Parish, State EDDY COUNTY, NM		
TYPE OF SUBMISSION		PPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION				
□ Notice of Intent	Acidize	 Deepen Hydraulic Fracturing 	- , ,		 Water Shut-Off Well Integrity 	
🛛 Subsequent Report	Casing Repair	New Construction	□ Recomplete □ Other			
Final Abandonment Not	ice 🔲 Change Plans	🛛 Plug and Abandon	Temporarily Abandon			
	Convert to Injection	•	UWater Disposal			
Attach the Bond under which following completion of the in	rectionally or recomplete horizontally the work will be performed or provide wolved operations. If the operation re inal Abandonment Notices must be fi	ent details, including estimated starting give subsurface locations and measur the Bond No. on file with BLM/BIA sults in a multiple completion or recor- led only after all requirements, includi	ed and true ver Required sub	rtical depths of all pertin sequent reports must be several a Form 316	ent markers and zones. filed within 30 days 0-4 must be filed once	
11/27/18 - MIRU PU			•	1-10-1	9	
11/28/18 - POOH & LD r	ods & pump.		Accep	ted for recerd - R	MOCD	


11/29/18 - NDWH, NU BOP, rel TAC, POOH & LD tbg.

11/30/18 - RIH w/ GR/junk basket to 5400', POOH. RIH & set CIBP @ 5397', POOH.

12/3/18 - RIH w/ 54jts tbg, rig broke down.

12/4/18 - Repl rigs

Accepted For R	lecord
NMOCD	196-19



14. I hereby certify that the foregoing is true and correct. Electronic Submission #449527 verified by the BLM Well information System For OXY USA INC, sent to the Carlsbad

Name (Printed/Typed) DAVID STEWART	Title SR. REGULATORY ADVISC	Title SR. REGULATORY ADVISOR			
Signature (Electronic Submission)	Date 01/07/2019				
THIS SPACE	FOR FEDERAL OR STATE OFFICE USE				
_Approved By	Title	Date			
Conditions of approval, if any, are attached. Approval of this notice certify that the applicant holds legal or equitable title to those rights i which would entitle the applicant to conduct operations thereon.	does not warrant or n the subject lease Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

لون

Additional data for EC transaction #449527 that would not fit on the form

32. Additional remarks, continued

Ï

12/5/18 - RIH w/ tbg & tag CIBP @ 5397', circ hole w/ 10# MLF, pressure test csg to 600#, held OK. M&P 25sx CL Cmt @ 5397' to calc TOC 5144'. PUH to 3894', M&P 25sx CI C cmt w/ 3% CaCl2, PUH, WOC. RIH & tag cmt @ 3617', PUH to 3294', M&P 40sx CI C cmt, PUH, WOC.

12/6/18 - RIH & tag cmt @ 2894', PUH to 2505', M&P 25sx CL C cmt w/ 3% CaCl2, BLM witnessed tag & plug, PUH, WOC. RIH & tag cmt @ 2188', PUH & perf @ 60', attempt to EIR, pressure up to 350#, no rate or loss. RIH to 925', M&P a total of 104sx CI C cmt, circ cmt to surf, remove all surface valves and risers, fill w/ cmt, top off csg.

12/7/18 - Verifiy cmt to surface on all strings, ND BOP, RD PU.