Submit 1 Copy District I – (575	To Appropriate District Office	State of New M		Re	Form C-103 vised July 18, 2013
1625 N. French	Dr., Hobbs, NM 88240 Eller	rgy, Minerals and Na	tural Resources	WELL API NO.	VI.Sou 7019 10, 2015
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVAT				30-005-64315	
District III - (5	05) 334-6178	1220 South St. Fr		5. Indicate Type of Lease	_
1000 Rio Brazo District IV – (5	ss Rd., Aztec, NM 87410 05) 476-3460	Santa Fe, NM		and the second se	
	ncis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BATES ADISTRICT DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH IN 0 0 2000 Huckleberry State					
PROPOSALS.) JAN 0 9 20 98. Well Number 1. Type of Well: Oil Well I Gas Well I Other 1					
2. Name of	Operator		RECEIVED	D 9. OGRID Number	
ARMSTRONG ENERGY CORPORATI			ON	1092 10. Pool name or Wildcat	
3. Address of Operator P.O. Box 1973, Roswell, NM 88202-1973					L
4. Well Location					
		from the <u>South</u>			<u>ast</u> line
Sec	tion 10 Townshi		nge 28E	NMPM Chaves	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM			REMEDIAL WOR		
			COMMENCE DRI	·· _	_
PULL OR A			CASING/CEMEN	ТЈОВ 🔲	·
DOWNHOL	E COMMINGLE				
	DOP SYSTEM				
CLOSED-LO					
OTHER:			OTHER:	Perf & Acidize	X
OTHER: 13. Descril date of	be proposed or completed operation starting any proposed work). SEE		rtinent details, and g	give pertinent dates, includi	ng estimated
OTHER: 13. Descril date of	be proposed or completed operation		rtinent details, and g	give pertinent dates, includi	ng estimated
OTHER: 13. Descril date of	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830	RULE 19.15.7.14 NM	rtinent details, and g AC. For Multiple (0' bailers of cemen	give pertinent dates, includi Completions: Attach wellbo	ng estimated ore diagram
OTHER: 13. Descril date of of prop	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and tb	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ	AC. For Multiple (AC. For Multiple (o' bailers of cemen erforators, SISD. 2% KCL. Pump and	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @	ng estimated ore diagram perforate 9 9080'. Set
OTHER: 13. Descril date of of prop 11/15/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2	ttinent details, and g AC. For Multiple (bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403	ng estimated ore diagram perforate 9 9080'. Set
OTHER: 13. Descril date of of prop 11/15/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma	tinent details, and g AC. For Multiple (o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descril date of of prop 11/15/18 11/16/18 11/17/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1st run. SISD.	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma	tinent details, and g AC. For Multiple (o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descril date of of prop 11/15/18 11/16/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma	tinent details, and g AC. For Multiple (o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descril date of of prop 11/15/18 11/16/18 11/17/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1st run. SISD.	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma	tinent details, and g AC. For Multiple (o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descril date of of prop 11/15/18 11/16/18 11/17/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1st run. SISD.	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma	tinent details, and g AC. For Multiple (o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descril date of of prop 11/15/18 11/16/18 11/17/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1st run. SISD.	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma	tinent details, and g AC. For Multiple (o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descril date of of prop 11/15/18 11/16/18 11/17/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1st run. SISD.	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma	trinent details, and g AC. For Multiple C o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B and scattered. Mad	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descrit date of of prop 11/15/18 11/16/18 11/17/18 11/18/18	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'-' SITP 0 psi. TIH w/packer and tb packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1 st run. SISD. SI, prep to move up hole.	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma swab, tag FL @ 8100' a	trinent details, and g AC. For Multiple C o' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B and scattered. Mad	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD e 3 runs, rec 2 BW total, sho	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descril date of of prop 11/15/18 11/16/18 11/17/18 11/18/18 Spud Date:	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and tb packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1 st run. SISD. SI, prep to move up hole. 08/30/2018	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma swab, tag FL @ 8100' a Rig Release Da	AC. For Multiple (AC. For Multiple (O' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B and scattered. Made	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD e 3 runs, rec 2 BW total, sho SISD 99/20/2018	ng estimated ore diagram perforate 9 9080'. Set 6#, 5min 2815#,
OTHER: 13. Descrit date of of prop 11/15/18 11/16/18 11/17/18 11/17/18 11/18/18 Spud Date: I hereby certif	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and tb packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1 st run. SISD. SI, prep to move up hole. 08/30/2018 fy that the information above is trace	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma swab, tag FL @ 8100' a Rig Release Da e and complete to the b	AC. For Multiple C AC. For Multiple C O' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B and scattered. Made ate:	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE (a reased to 3500#. ISIP 3403 W. SISD e 3 runs, rec 2 BW total, sho D9/20/2018	ng estimated pre diagram perforate 9 9080'. Set #, 5min 2815#, ow of
OTHER: 13. Descril date of of prop 11/15/18 11/16/18 11/17/18 11/17/18 11/18/18 Spud Date: I hereby certif SIGNATURE	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062' SITP 0 psi. TIH w/packer and tb packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1 st run. SISD. SI, prep to move up hole. 08/30/2018 fy that the information above is trace	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma swab, tag FL @ 8100' a Rig Release Da and complete to the b	ate: VP - Engineering	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD e 3 runs, rec 2 BW total, sho D9/20/2018 ge and belief.	ng estimated perforate 9 9080'. Set #, 5min 2815#, ow of
OTHER: 13. Descrit date of of prop 11/15/18 11/16/18 11/17/18 11/17/18 11/18/18 Spud Date: I hereby certif SIGNATURE Type or print	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1 st run. SISD. SI, prep to move up hole. 08/30/2018 fy that the information above is trace mame Kyle Alpers	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma swab, tag FL @ 8100' a Rig Release Da and complete to the b TITLE E-mail address:	AC. For Multiple C AC. For Multiple C O' bailers of cemen erforators, SISD. 2% KCL. Pump and 912#, gradually inc de 9 runs, rec 58 B and scattered. Made ate:	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD e 3 runs, rec 2 BW total, sho D9/20/2018 ge and belief. ng DATE mm.com PHONE:	ng estimated perforate 9 9080'. Set #, 5min 2815#, ow of 1/9/19 575-625-2222
OTHER: 13. Descrit date of of prop 11/15/18 11/16/18 11/17/18 11/17/18 11/18/18 Spud Date: I hereby certit SIGNATURE Type or print APPROVED	be proposed or completed operation f starting any proposed work). SEE posed completion or recompletion. TIH, tie in and set CIBP @ 9830' 9078'-9080', 6 holes, and 9062'- SITP 0 psi. TIH w/packer and th packer, test BS, pump down tbg (10min 2660#, 15min 2582#, blee SITP 1500psi. Blow down, RU s condensate on 1 st run. SISD. SI, prep to move up hole. 08/30/2018 fy that the information above is trace mame Kyle Alpers	RULE 19.15.7.14 NM '. TIH and dump two 4 9069', 16 holes. RD p g. RU acidizers. Circ @ 2.4bpm. Broke @ 2 d off. RU to swab. Ma swab, tag FL @ 8100' a Rig Release Da and complete to the b	ate: VP - Engineering	give pertinent dates, includin Completions: Attach wellbo at on CIBP. TIH, tie-in and d spot 500gal 15% NEFE @ reased to 3500#. ISIP 3403 W. SISD e 3 runs, rec 2 BW total, sho D9/20/2018 ge and belief. ng DATE mm.com PHONE:	ng estimated perforate 9 9080'. Set #, 5min 2815#, ow of

.

. . .