UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


-	Lease Serial No.
J.	Lease Serial No.
	NMLC067144
	INIVILCUO7 144

	SUNDF	YON YS	ICES AI	ND REPO	ORTS O	N WELLS	
Do	not use	this for	m for pro	oposals to	o drill or	to re-enter	r an
abar	ndoned v	well. Us	e form 3	3160-3 (ΔI	PD) for s	uch propo	sals

abandoned wel	6. If Indian, Allottee or Tribe Name								
SUBMIT IN 1	7. If Unit or CA/Agreement, Name and/or No.								
1. Type of Well	8. Well Name and No. INDIAN FLATS BASS FEDERAL 001								
Ø Oil Well ☐ Gas Well ☐ Oth Name of Operator		IE J CHERRY		9. API Well No.					
BOPCO LP	E-Mail: tracie_cherry@xto	oenergy.com		30-015-24968	····				
3a. Address 6401 HOLIDAY HILL RD BLD MIDLAND, TX 79707		Phone No. (include area code) 432-22147379_CONC ARTESIA DI		10. Field and Pool or E	xploratory Area DELAWARE				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, S	tate				
Sec 35 T21S R28E Mer NMP		JAN 3 1		EDDY COUNTY					
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	NDICATE NATURE OF	NOTICE,	REPORT, OR OTH	ER DATA				
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION								
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off				
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclam	ation	■ Well Integrity				
Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomp	olete	Other				
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon		arily Abandon					
	Convert to Injection	☐ Plug Back	☐ Water I	Disposal					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BOPCO, LP respectfully submits this sundry notice to report the plug and abandonment the referenced RECLAMATION well. 11/01/18 - 11/05/18 MIRU. POOH w/rods and pump. Remove wellhead, install BOP, PT/FT 300/1000. Set 5.5" CIBP @ 2650". 11/06/18 Tag CIPB to verify setting. Circulate salt gelled mud. PT to 500 psi (good). Spot 25.sx.'C' 2650-2409', WOC 4 hrs. Tag cmt @ 2396'. Per sqz hole @ 2300'. EIR, sqz 45 sx 'C' 2300'-2125'. RECLAMATION PROCEDURE Tag cmt @ 2131'. Perf sqz holes @ 500'. Set pkr @ 30', EIR. Sqz 140 sx 'C' 500'-surface. RECLAMATION PROCEDURE ATTACHED									
14. I hereby certify that the foregoing is Name (Printed/Typed) TRACIE J	Electronic Submission #45056' For BOPCC Committed to AFMSS for pro	DLP, sent to the Carlsbac ocessing by JAMES AMO	j S on 01/15/2	-					
Name (17 mieu/19peu) TRACIE J	CHERKI	Title REGOL	ATORT CO	ORDINATOR					
Signature (Electronic S	Submission)	Date 01/14/20)19						
Accepted for Recor	THIS SPACE FOR FE	DERAL OR STATE (OFFICE U	SE					
Approved By Conditions of approval, if any, are attache	d Approval of this notice does not wa	<u> </u>	ET		1-18-19 Date				
ertify that the applicant holds legal or equivinch would entitle the applicant to condu	itable title to those rights in the subjec	office CF	0						
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			willfully to m	ake to any department or	agency of the United				

(Instructions on page 2)





Additional data for EC transaction #450561 that would not fit on the form

32. Additional remarks, continued

11/20/18 Cut off wellhead. Install marker. Well P&A'd



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612