Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-015-33923
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE X FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	DIAID 1	1
	SWS Inv# 13695 ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Dease Name of One Agreement Name
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Spud 16 State
PROPOSALS:)		8. Well Number 4
1. Type of Well: Oil Well	Gas Well Othern SWIR CONSERVATION	-
2. Name of Operator	ARTESIA DISTRICT	9. OGRID Number
Devon Energy Production Comp		6137
3. Address of Operator	JAN 2 4 2019	10. Pool name or Wildcat
333 W. Sheridan Avenue, Okla	thoma City, OK 73102	2WD; Delaware
4. Well Location		
Unit Letter O :	960 feet from the RECEIVED line and	1800 feet from the East line
) (D) (
Section 16	Township 23S Range 29E	2007
	2978' KB	1
Lake the second		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
		SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	— I	
TEMPORARILY ABANDON		RILLING OPNS.□ PAND A 🛛
PULL OR ALTER CASING		NT JOB 🔲
DOWNHOLE COMMINGLE		
	_	
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
		ompicuous. Attach welloofe diagram of
proposed completion or re		ompletions. Attach we notice diagram of
		ompletions. Attach we notice diagram of
	completion.	ompletions. Attach we notice diagram of
proposed completion or re 1. 12/21/18 Notify OCD of intent	completion.	ompletions. Attach we notice diagram of
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4	completion. 9555'.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555	completion.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342'. Spot 25 so	completion. 1555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class	completion. i555'. i' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo 's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class	completion. 1555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo t's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class	completion. i555'. i' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo 's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class	completion. 1555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo t's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class	completion. 1555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo t's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class	completion. 1555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo t's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class	completion. 1555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo t's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class *6. 01/03/19 Cut off WH, anchors	completion. 1.555'. 1.555'. 1.5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spot's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. 1.5' cmt @ 100'-surf. Verify cmt @ surf. 1.5' and clear location, set hole marker. P&A completed.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class	completion. 1555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spo t's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class *6. 01/03/19 Cut off WH, anchors	completion. 1.555'. 1.555'. 1.5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spot's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. 1.5' cmt @ 100'-surf. Verify cmt @ surf. 1.5' and clear location, set hole marker. P&A completed.	
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342'. Spot 25 ax 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 6. 01/03/19 Cut off WH, anchors Spud Date:	completion. 15555'. 15 w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Sports class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf. a and clear location, set hole marker. P&A completed. Rig Release Date:	of 25 sx's class "c" cmt @ 4555-4455' tag TOC
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342'. Spot 25 ax 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 6. 01/03/19 Cut off WH, anchors Spud Date:	completion. 1.555'. 1.555'. 1.5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spot's class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. 1.5' cmt @ 100'-surf. Verify cmt @ surf. 1.5' and clear location, set hole marker. P&A completed.	of 25 sx's class "c" cmt @ 4555-4455' tag TOC
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342'. Spot 25 ax 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 6. 01/03/19 Cut off WH, anchors Spud Date:	completion. 15555'. 15 w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Sports class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf. a and clear location, set hole marker. P&A completed. Rig Release Date:	of 25 sx's class "c" cmt @ 4555-4455' tag TOC
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342'. Spot 25 ax 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 6. 01/03/19 Cut off WH, anchors Spud Date:	completion. 15555'. 15 w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Sports class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf. a and clear location, set hole marker. P&A completed. Rig Release Date:	at 25 sar's class "c" cmt @ 4555'-4455' tag TOC ENTERED J. 1. 30 . 19 Ige and belief.
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342'. Spot 25 ax 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 6. 01/03/19 Cut off WH, anchors Spud Date:	completion. 15555'. 15 w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Sports class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf. a and clear location, set hole marker. P&A completed. Rig Release Date:	of 25 sx's class "c" cmt @ 4555-4455' tag TOC
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342'. Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 6. 01/03/19 Cut off WH, anchors Spud Date: I hereby certify that the information SIGNATURE	Completion. 15:555'. 15: w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spots class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. 10 cmt @ 100'-surf. Verify cmt @ surf. 11 and clear location, set hole marker. P&A completed. Rig Release Date: TITLE Agent	t 25 sx's class "c" cmt @ 4555-4455' tag TOC ENTERED J (- 30 - 19) Ige and belief. DATE 01/07/19
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 se 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 6. 01/03/19 Cut off WH, anchors Spud Date:	completion. 2.555'. 5' w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spots class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. c" cmt @ 100'-surf. Verify cmt @ surf. a and clear location, set hole marker. P&A completed. Rig Release Date:	t 25 sx's class "c" cmt @ 4555-4455' tag TOC ENTERED J (- 30 - 19) Ige and belief. DATE 01/07/19
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 sx 4. 12/29/18 Spot 270 sx's class 5. 01/02/19 Spot 20 sx's class 5. 01/03/19 Cut off WH, anchors Spud Date: I hereby certify that the information SIGNATURE	Completion. 15:555'. 15: w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spots class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. 10 cmt @ 100'-surf. Verify cmt @ surf. 11 and clear location, set hole marker. P&A completed. Rig Release Date: TITLE Agent	t 25 sx's class "c" cmt @ 4555-4455' tag TOC ENTERED J (- 30 - 19) Ige and belief. DATE 01/07/19
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 set 4. 12/29/18 Spot 270 sets class 5. 01/02/19 Spot 20 sets class *6. 01/03/19 Cut off WH, anchors Spud Date: I hereby certify that the information SIGNATURE Type or print name Jimmy Bagley	Completion. 15:555'. 15: w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spots class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. 10 cmt @ 100'-surf. Verify cmt @ surf. 11 and clear location, set hole marker. P&A completed. Rig Release Date: TITLE Agent	to 25 sor's class "c" cmt @ 4555'-4455' tag TOC Company Compa
proposed completion or re 1. 12/21/18 Notify OCD of intent 2. 12/27/18 Set 5 1/2" CIBP @ 4 3. 12/28/18 Verify CIBP @ 4555 @ 4342". Spot 25 set 4. 12/29/18 Spot 270 sets class 5. 01/02/19 Spot 20 sets class *6. 01/03/19 Cut off WH, anchors Spud Date: I hereby certify that the information SIGNATURE Type or print name Jimmy Bagley	Completion. 15:555'. 15: w/2 3/8" tbg. Test well 500 psi. Good. Circ 110 bbl MLF. Spots class "c" cmt @ 3562'-3462'. Tag TOC @ 3352'. "c" cmt @ 2750'-328'. Tag TOC @ 325'. 10 cmt @ 100'-surf. Verify cmt @ surf. 11 and clear location, set hole marker. P&A completed. Rig Release Date: TITLE Agent	t 25 sx's class "c" cmt @ 4555-4455' tag TOC ENTERED J (- 30 - 19) Ige and belief. DATE 01/07/19

ENTERED