UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED

OMB NO. 1004-0137
Expires: January 31, 201
se Serial No.
41 COG/577A

SUNDRY N	OTICES AND REPORTS ON WELLS
Do not use this abandoned well.	form for proposals to drill or to re-enter an Use form 3160-3 (APD) for such proposals.

 141	Allottee or Tribe Nan	

abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well		8. Well Name and No. B I HANSON FED 2						
2. Name of Operator Contact: DILLON A SALAS PENROC OIL CORPORATION E-Mail: apollo.salas44@gmail.com				9. API Well No. 30-015-05724				
3a. Address PO BOX 2769 HOBBS, NM 88241 3b. Phone No. (include area code) Fx ₂ 575-492-1236 Fx ₂ 575-492-1237				10. Field and Pool or Exploratory Area SHUGART				
4. Location of Well (Footage, Sec., T. Sec 3 T19S R31E 2310FSL 1	., R., M., or Survey Description)	FEB 08 2010		11. County or Parish, State LEA COUNTY, NM Edd Y				
12. CHECK THE AF	PPROPRIATE BOX(ES) TO IN	DICATE NATURE OF	NOTICE, REPORT,	OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION							
☐ Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Deepen ☐ Hydraulic Fracturing	☐ Production (Start/R☐ Reclamation	esume)	f			
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other				
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	☐ Temporarily Aband	lon				
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1. RU. POH w/ rods and pump. LD same. 2. NU BOP. POH w/ 121 jts of 2 3/8" tbg. 3. RU wireline. Ran gauge ring, TiH to 3370'. TIH w/ CIBP, set 4 1/2" CIBP@3300'. Made 2 bailer runs 52' of cement Class "C". 4. After overnight SI, TIH w/ 2 3/8" tbg. Tagged, plug @ 3250'. 5. RU cement co. circ hole w/. 10lb gelled brine to surface. 6. Found bad nipple/connection @ wellhead. Replace nipple @ surface casing/wellhead. 7. Next day, re-circulated w/37bbl of 10lb gelled brine. Pressure tested to 400psi for 30min. POH to 2346', spotted 30sxs Class "C" cmt. POH w/30jts of 2 3/8". W.O.C. for 4								
14. I hereby certify that the foregoing is true and correct. Electronic Submission #450352 verified by the BLM Well Information System For PENROC OIL CORPORATION, sent to the Carlsbad Committed to AFMSS for processing by JAMES AMOS on 01/15/2019 () Name (Printed/Typed) MERCH MERCHANT Title PRESIDENT								
Signature (Electronic S	Submission)	Date 01/11/20	ACCE	PTFD FOR RECOR	וח			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By		Title		JAN 3 0 2019	I			
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	t lease Office	Lorr Burez CA	PLSBAD FIFT D OFFICE					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			willfully to make to any de	partment or agency of the United				

Additional data for EC transaction #450352 that would not fit on the form

32. Additional remarks, continued

hours.
8. TIH w/ 2.3/8" tbg to 1891' and tagged.
9. TOH w/tbg, perforated 2 holes @1017'. TIH w/30jts of 2 3/8" tbg to 945'.
10. Or(1/9/19) circ hole w/100bbl gelled brine.
11. Pump 407sxs Class "C" to surface.
12. ND BOP. Spotted 4sxs on surface.
13. RD cementers, Rig, empty pits(1/2 pit). Will move out all equipment, cut well head remove anchors.

head, remove anchors.

14. Install dry hole marker and clean location in the coming weeks. Will prepare location per BLM standard. SD 5pm. 1/9/19.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612