
Somi 3160-5 June 2015) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Se	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM7724		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Alloue or Tribe Name	
	SUBMIT IN T	RIPLICATE - Other inst	ructions on page 2	7. If Unit o	r CA/Agreement, Name and/or No.	
1. Type of Well 50 Oil Well	Gas Well 🗍 Oth		<u></u>		8. Well Name and No. SANTA ELENA 19 FEDERAL 1	
2. Name of Open					-40567	
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701			3b. Phom NP Offud DON OF Ph: 432-818 ARTESIA DIS			
4. Location of Well (Footage, Sec., T., R., M., or Survey Descriptio			FEB 28	2019 I *	11. County or Parish, State	
Sec 19 T16	S R30E Mer NMP	1650FNL 330FWL	12020	EDDY	COUNTY, NM	
			TO INDICATE NATURE C		OR OTHER DATA	
		PROPRIATE BOA(ES)		F ACTION		
TYPE OF SUBMISSION		m A - (1)		Production (Start/R	esume) 🔲 Water Shut-Off	
Notice of I	Intent	Acidize Alter Casing	Deepen Hydraulic Fracturing		Well Integrity	
🗖 Subsequer	nt Report	Casing Repair	New Construction	Recomplete	Other	
Final Aban	indonment Notice	Change Plans	Plug and Abandon	Temporarily Aband	on	
		Convert to Injection	Plug Back	Water Disposal		
	at the site is ready for frating LLC respectfo		te the Santa Elena 19 Federa			
Test. We are goi the plug to integrity. Please see	have our PBTD @	e 4,210°. We will then test	set a CIBP at 4,250' w/40' of the casing to 4,300 PSI and			
Test. We are goi the plug to integrity. Please see	have our PBTD @	4,210'. We will then test re and WBD. is true and correct.	\$4,500 FSI and \$456027 verified by the BLM W OPERATING LLC, sent to the	fell Information System		
Test. We are goi the plug to integrity. Please see	have our PBTD @	4,210'. We will then test re and WBD. is true and correct. Electronic Submission For COG	#456027 verified by the BLM W OPERATING L C, sent to the	Yell Information System		
Test. We are goi the plug to integrity. Please see 14. I hereby cer	have our PBTD @ e attached procedu rtify that the foregoing i ed/Typed) DANA KI	4,210'. We will then test re and WBD. is true and correct. Electronic Submission i For COG NG	\$456027 verified by the BLM W OPERATING LLC, sent to the Title PERM Date 02/26	Vell Information System Carlsbad AIT SPECIALIST II /2019		
Test. We are goi the plug to integrity. Please see 14. I hereby cer Name (Printe	have our PBTD @ e attached procedu rtify that the foregoing i ed/Typed) DANA KI	4,210'. We will then test re and WBD. is true and correct. Electronic Submission i For COG NG	s456027 verified by the BLM W OPERATING LLC, sent to the Title PERM Date 02/26	Vell Information System Carlsbad AIT SPECIALIST II /2019 E OFFICE USE	als will	
Test. We are goi the plug to integrity. Please see 14. I hereby cer Name (Printe Signature Approved By Conditions of app certify the the an	have our PBTD @ e attached procedu nify that the foregoing i ed/Typed) DANA KI (Electronic proval, if any, are attach	4,210'. We will then test re and WBD. is true and correct. Electronic Submission i For COG NG	s456027 verified by the BLM W OPERATING LLC, sent to the Title PERM Date 02/26	Vell Information System Carisbad AIT SPECIALIST II /2019	als will riewed	

(Instructions on page 2) ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Santa Elena 19 Federal #1H – Casing Test For Recompletion The Santa Elena 19 Fed 1H was originally drilled and completed by COG Operating in 2012. Due to its location and low production it is a candidate for up hole recompletion. We are going to run a CCL/GR to 4,250' to 2,700' and set a CIBP at ~4,250' w/ 40' of CMT on top of the plug to have our PBTD @ 4,210'. We will then test the casing to 4,300 psi and chart to verify integrity.



<u>WBD</u>

PERFS 4,511–8,426' Paddock

Equipment Pull / Casing Test Procedure

- MIRU WSU, NU BOP
- Unset pump and POOH with rods / pump and laydown
- ND WH, NU BOP and POOH with Tubing standing back
- PU scraper and scrape down to 4,300'
- POOH and laydown all tubing
- RU Wireline

Page 1 of 2

- Make gauge ring/ junk basket run
- Run CCL/GR to 4,250' to 2,700'
- Set CIBP @ 4,250' @ 53 degrees
- Wireline truck dump 40' Class C cement of top of CIBP
- Load casing with fresh water and test casing to 4,300 psi and chart for 30mins report back to engineering if the pressure holds.
- Secure wellbore
- RDMO WSU

. . .