

UNITED STATES DEPARTMENT OF THE INTERIOR DOOR FILE OF BUREAU OF LAND MANAGEMENT BUREAU OF LAND MANAGEMENT APTERIOR DOOR APTERIOR

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS AND ACCOUNT					NMLC028784B		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM88525X		
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. BURCH KEELY UNIT 411		
2. Name of Operator Contact: SANDY BALLARD COG OPERATING LLC E-Mail: sballard@concho.com					9. API Well No. 30-015-36263-00-S1		
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	. (include area code) 6-4373		10. Field and Pool or Exploratory Area BURCH KEELY-GLORIETA-UPR YESC				
4. Location of Well (Footage, Sec., T			11. County or Parish, State				
Sec 18 T17S R30E Lot 2 1910FNL 990FWL					EDDY COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR C	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	dize		☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing ☐		☐ Reclama	ation	■ Well Integrity	
Subsequent Report	1		Construction	☐ Recomplete		☑ Other Venting and/or Flari	
☐ Final Abandonment Notice	☐ Change Plans	e Plans 🔲 Plug and		□ Temporarily Abandon		ng	
	Convert to Injection	ert to Injection Plug Back Water		☐ Water D	Disposal		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Burch Keely Unit 18A Battery (Permit approval: Electronic Submission #431996 Actual gas flared for this battery for 8/30/2018 TO 11/28/2018 is as follows: Aug Total for Battery = 0 MCF Sept Total for Battery = 4884 MCF Oct Total for Battery = 228 MCF Nov Total for Battery = 228 MCF Nov Total for Battery = 0 MCF							
Electronic Submission #455349 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 02/22/2019 (19PP1098SE) Name (Printed/Typed) SANDY BALLARD Title SENIOR ADMINISTATIVE ASSISTANT							
Name (17 mear 1 ypear) SANDT L	THE SENIOR ADMINISTRATIVE ASSISTANT						
Signature (Electronic S	Date 02/20/2	019					
	THIS SPACE FO	OR FEDERA					
Approved By			AUCEP I	EU FUR	KECUKU	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			- Office	EB 2 2 20		nathon Shepard	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any poto any matter w	erson knowingly and ithin its jurisdiction;	willfully to ma 正 LAND MA	ake to any departmen	at or agency of the United	
-					encrasse I		

.

Additional data for EC transaction #455349 that would not fit on the form

32. Additional remarks, continued

NUMBER OF WELLS TO FLARE: (27)
BURCH-KEELY UNIT 411 30-015-36263
BURCH-KEELY UNIT 412 30-015-36182
BURCH-KEELY UNIT 417 30-015-36181
BURCH-KEELY UNIT 548 30-015-39442
BURCH-KEELY UNIT 549 30-015-39522
BURCH-KEELY UNIT 550 30-015-39523
BURCH-KEELY UNIT 552 30-015-39523
BURCH-KEELY UNIT 555 30-015-39755
BURCH-KEELY UNIT 555 30-015-39566
BURCH-KEELY UNIT 556 30-015-39907
BURCH-KEELY UNIT 557 30-015-39316
BURCH-KEELY UNIT 557 30-015-39317
BURCH-KEELY UNIT 563 30-015-39317
BURCH-KEELY UNIT 563 30-015-39318
BURCH-KEELY UNIT 563 30-015-39869
BURCH-KEELY UNIT 565 30-015-39568
BURCH-KEELY UNIT 566 30-015-39568
BURCH-KEELY UNIT 570 30-015-40267
BURCH-KEELY UNIT 578 30-015-40267
BURCH-KEELY UNIT 578 30-015-40267
BURCH-KEELY UNIT 578 30-015-40268
BURCH-KEELY UNIT 578 30-015-40268
BURCH-KEELY UNIT 578 30-015-40268
BURCH-KEELY UNIT 578 30-015-40272
BURCH-KEELY UNIT 582 30-015-40272
BURCH-KEELY UNIT 934H 30-015-42788
BURCH-KEELY UNIT 934H 30-015-42788
BURCH-KEELY UNIT 938H 30-015-42788

Reason for flare: UNPLANNED MIDSTREAM CURTAILMENT PLANT SHUT DOWN DUE TO HLP OR PLANT MAINTENANCE