Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED OMB NO. 1004-0137

	Expires:	January	
Lease S	erial No.		


5. L NMNM63757

วบทบเ	KY NUII	CES ANI	リ ベミアしゃ	(15 UN	WELLS	
Do not use	this forn	n for prop	osals to d	drill or to	re-enter a	n
					_	

abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

	·	<u> </u>	NICT CILC		DVATE ON			
SUBMIT IN	TRIPLICATE - Other inst	tructions on	page 2 ARTES	SIA DIS	TRICT. If Unit or CA/Agr	eement, Name and/or No.		
1. Type of Well Oil Well Gas Well Oth	ner	<u> </u>	MAR	112	8. Well Name and No LOTOS C FEDE			
2. Name of Operator CHEVRON USA INCORPORA	Contact: ATED E-Mail: nglann@cl	NICK GLANN hevron.com		CEIVE	9. API Well No. 30-015-30043-	00-S1		
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		3b. Phone No. Ph: 661-59	(include area code 9-5062)	10. Field and Pool or SAND DUNES			
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description	,			11. County or Parish	, State		
Sec 9 T24S R31E SENE 1980	EDDY COUNT	Y, NM						
12. CHECK THE A	PROPRIATE BOX(ES)	TO INDICA	ΓE NATURE O	F NOT	CE, REPORT, OR OT	HER DATA		
TYPE OF SUBMISSION			TYPE O	F ACTIO	N			
☑ Notice of Intent	☐ Acidize	□ Deep	oen	☐ Pro	oduction (Start/Resume)	■ Water Shut-Off		
_	□ Alter Casing	🗀 Hyd	raulic Fracturing	☐ Re	clamation	■ Well Integrity		
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Re	complete	☐ Other		
☐ Final Abandonment Notice	Change Plans	🛭 Plug	and Abandon	☐ Te	mporarily Abandon			
	☐ Convert to Injection	Plug	Back	□ Wa	iter Disposal	Disposal		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ah determined that the site is ready for final Provide 24 hour notification to 1. MIRU, test tubing, pull rods 2. Set CIBP @ 8100', circulate 3. Spot 25 sx CL H cmt f/ 8100', do not WOC & tag. If casin 4. Based off CBL results, eithe (Delaware, Shoe, B. Salt). Wo 5. Perf & squeeze 325 sx CL 6. Verify cement to surface and the complete state of the surface and the surface and the surface and the surface and the surface state of the surface and the surface	operations. If the operation repandonment Notices must be fill in all inspection. BLM prior to MIRU, as p., N/U BOPE, pull tubing e. 9.5 ppg MLF, test casing did not pass the pressuer perf & squeeze 145 sx DC & tag if perf & squeeze C cmt f/ 920' t/ surface (T d turn over to site reclam	sults in a multipled only after all rear applicable of the property of the pro	completion or receptive and the completion of the complete and the complet	ed for i	in a new interval, a Form 31 nation, have been completed Secretary NMOCD Provide Toc Add - (Speech) 6' 970. SOZ 60' SQZ 60' SQZ	60-4 must be filed once and the operator has 's Potash'. 51/2' 6560-6360. if to 820.		
Comm	# Electronic Submission For CHEVRON t itted to AFMSS for process	JSA INCORPÓ	RATED, sent to RAH MCKINNEY	the Carls on 02/14	sbad /2019 (19DLM0317SE)			
Name (Printed/Typed) NICK GLA	<u>NN</u>		Title WELL		ONMENT ENGINEER			
				ì	SEE ATTACHED	FOR		
Signature (Electronic S	Submission)		Date 02/14/2	2019	CONDITIONS OF	<u> </u>		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFIC	ÉUSE	MINUVAL		
Approved By	Q. amos	, :	Title St	OCT		2-23-19 Date		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive th	itable title to those rights in the	not warrant or e subject lease	Office <i>QF</i>	-0				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe	rson knowingly and thin its jurisdiction.	d willfully	to make to any department of	r agency of the United		



CURRENT WELLBORE DIAGRAM

Lease: Lotos Location:	Well No: 903 Sec: 31 Blk:	API: 30-015-3 Survey: TS			Chev No.: B	S6895	_				
County: EDDY Field: Ingle Wells Directions to Wellsite:	State: New Mexico LAT: WBS:	32,2335600 LON	łG: -103,7755800		Cost Center: U	JCRI30100	-				
Surface CASING Size: 11 3/4 WL: 42# Set @: 550 Sxs cmt 590 sks Cmt Date: 3/4/98 Circ: Yes			Toc 2		KB: _ GL: _ Spud Date: _ Compl. Date: _	3,458.0 3,445.0 2/28/98 5/14/1998	<u>-</u>				
12 4 lede	41		Tubing Detail				1				
17.4 mus	11	1 11	k	Equipment	i	Size	EUE Plain	Threads	No. Joints	E.	at
Intermediate CASING	i [1 11	TUBING 6.5# J-55			2 7/8	EUE	8RD	239	7,5	
Size: <u>8 5/8</u>		1 11	TAC			2 7/8	EUE	8RD	1		3
Wt.: 24# Set @: 4163	<u> </u>		TUBING 6.5# J-55			2 7/8	EUE	8RD	14		65
Sxs Cmt: 1525 sks	1. 1	1 11	Seat Nipple Mud Anchor	<u>-</u>		2 7/8 2 7/8	EUE	8RD 8RD	1 1		2
Cmt Date: 4/9/98	! !	1 1 1	Bull Plug		+	2 7/8	EUE	8RD	 		11
Circ: yes		1 11							Total	807	
	i i	1 14								·	
7 1/8 how	{ 1	1 11	Rod Detail						1		
1 18 mg	11		Size			lanufacturer			No. of Rods	Length	Grade
		_ 1 _ [}	1 1/4			OLISHROD			11	26	N-96
Size: 5 1/2 WL: 17#	• , 11	1 11	7/8 3/4			TEEL RODS EEL RODS			78	1912	N-96
Size: 5 1/2 Wt.: 17# Set @: 8400	7 Stage		7/8		<u> </u>	TEEL RODS			231	5775 300	N-96 N-96
Sxs Cmt: 1225 sks	201		1 1/2			RNER PUMP		-	1	20	11.00
Cmt Date: 5/10/98	20 (55)	i I i							Total	8033	
Circ: no	Circl	1 11									
	2 Stage Circ 155 2 Stage Toc?	3	38. 0	SEOLOGIC MARKER							
		<u> </u>	NAN		OP TRUE VERT. DEPT	гн					
					SubSeaDept						
PBTD: 8,358 TD: 8,700			Rustler Salado Salt Base Salado Salt Delaw Mtn. Grp.	870 4076 4340	518' 870' 4076' 4340'						
Remarks:			Cherry Canyon Brushy Canyon Bone Spring Lm.	5270° 6510°	5270' 6510' 8228'						
			<u> </u>	i							

CURRENT WELLBORE DIAGRAM

Lease Location	e: Lotos	Well No: 903	Bik:	API: 30-015-3	30043		Chev No.: BS6895
County	y: EDDY d: Ingle Wells	State: New Mexico	LAT: WBS:	Survey: <u>TS</u> 32.2335600 LON	NG: <u>-103.7755800</u>		Cost Center: UCRI30100
Surface CAS Size: Wt.: Set @: Sxs cmt: Cmt Date: Circ:	11 3/4 42# 650 590 sks 3/4/98 Yes				Perf & squeeze 325 sx (CL C cmt f/ 920' t/ si	KB: 3,458.0 GL: 3,445.0 Spud Date: 2/28/98 Compl. Date: 5/14/1998 urface (T. Salt, Shoe, Fresh Water)
Intermediate Size: Wt.: Set @: Sxs Cmt: Cmt Date: Circ:	8 5/8 24# 4163 1525 sks 4/9/98 yes				Based on CBL results, e t/ 3976' (Delaware, Shoe		or spot 45 sx CL C cmt f/ 4390' ag if P&S
Production C Size: Wt.: Set @: Sxs Cmt: Cmt Date: Circ:	5 1/2 17# 8400 1225 sks 5/10/98						
		8146' -	8204' =	XXXXXXXXX	1		asing t/ 1000 psi/10 min, run CBL
			=	=======================================	NAME		OP TRUE VERT. DEPTH SubSeaDepth
PBTD: TD:	8,358 8,700				Rustler Salado Salt Base Salado Salt Delaw Mtn. Grp. Cherry Canyon	518 870 4076 4340' 5270'	518' 870' 4076' 4340' 5270'
Remarks:					Brushy Canyon Bone Spring Lm.	8510' 8228'	6510 [°] 8228 [°]

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted