Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED

a	Expires: January 31, 20
5.	Lease Serial No. NM 21767

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or property ation abandoned well. Use Form 3160-3 (APD) for such proposals DISTRICT 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Well Name and No. Worth Federal No. 5 Oil Well Gas Well Other 2. Name of Operator Stephens & Johnson Operating Co. 9. API Well No. 30-015-30986 RECEIVED 3a. Address P.O. Box 2249, Wichita Falls, TX 76307 3b. Phone No. (include area code) Field and Pool or Exploratory Area (940) 723-2166 Brushy Draw, Delaware 4. Location of Well (Footage, Sec., T.R., M., or Survey Description) 11. Country or Parish, State 660' FSL, 990' FWL, Sec 14, T26S, R29E Eddy County, New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Hydraulic Fracturing Reclamation Well Integrity Casing Repair New Construction Recomplete Other Subsequent Report Change Plans ✓ Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.) 11-17-2018: Set CIBP @ 5060 11-18-2018:

11-19-2018**)**

Circulated hole with mud laden fluid and dump 25 sx Class "C" cmt on top of CIBP @ 5060". Move end of tbg to 4468 and spot 25 sx cmt. WOC. Tag plug @ 4300". Move end of tbg to 3117 and spot 30 sx cmt.

Tag plug @ 2775'. Perforate 5 1/2" csg @ 865'. Pump 300 sx Class "C" cmt out holes @ 865 and back to

surface leaving 5 1/2" csg full of cmt. Cut off bradenhead, weld steel plate on top of 8 5/8" collar. Erect P&A marker.

Accepted for record NMOCD

RECLAMATION PROCEDURE ATTACHED

RECLAMATION DUE 5-19-19'

FEB 25 2019



.

Petroleum Engineer Title	Carlebau :			
Oli W. Kincaid Date		PEPTED FOR RECORD		
RAL OR STATE OFICE	USE			
Title		MAR - 4 2019 Date		
or ase Office	BU	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE		
	Title Date ERAL OR STATE OFICE Title or	Date ACE ERAL OR STATE OFICE USE Title	Petroleum Engineer Cario Cario Date ACCEPTED FOR RECORD ERAL OR STATE OFICE USE MAR - 4 2019 Title Date BUREAU OF LAND MANAGEMENT	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction



Worth Federal No. 5 Brushy Draw, Delaware 2-18-2019
WELL FIELD DATE DATE Plug + Abandonment KB ELEVATION ____ 2944 GL ELEVATION _ 2929' DF ELEVATION PERMANENT WELL BORE DATA DATA ON THIS COMPLETION 85/8" 24 * csq set @ 815 cmt w/440 sx - Cmt circ Circulate cement out Squeeze holes @ 865'

Dack to surface

between 5/2' Csg and

\$ 5/8" Csg. Leave 5/2"

Csg full of Cement to surface (\$9 tull 0.) 300 5x to Perf 4 Way Squeeze holes @ 865'0 TOC @ 2750' by CBL Co Carro Sair 30 sk cmt 2775'-3117' 25 5x Cmt 4300'-4468' CIBP@ 5060'W/25 SX Cement on top 51/2" 15.5 + csq set @ 5268' Stage 1: 200 sx cmt Perfs: 5112-5152 2000 gals 7/2 % Fercheck Acii 18,000 gals Delta Frac 140 (254) 63,000 lbs 16/30 Sand Stage a: 350 sk cut TOC @ 2750' by CBL DV Tool @ 4467 PBTD - 5245 TD - 5270'

Stephens + - Dunson Operating W.



united States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612