Form 3160-5 (June 2015)	UNITED STATES		arlsbad	Field	Office AB NO	APPROVED D. 1004-0137	
В	EPARTMENT OF THE INTERIOR UREAU OF LAND MANAGEMENT NOTICES AND REPORTS ON WELLS				Expires: January 31, 2018 Expires: January 31, 2018 Expires: January 31, 2018 Expires: January 31, 2018		
Do not use th abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ment, Name and/or No.	
1. Type of Well					8. Well Name and No.		
S Oil Well Gas Well Other					9. API Well No.		
2. Name of Operator Contact: DANA KING COG OPERATING LLC E-Mail: dking@concho.com				30-015-40448-00-S1			
3a. Address 3b. Phone No. (include area code) 600 W ILLINOIS AVENUE Ph: 432-818-2267 MIDLAND, TX 79701 Ph: 432-818-2267					10. Field and Pool or Exploratory Area WILDCAT		
4. Location of Well (Footage, Sec., 7	", R., M., or Survey Description))		:	11. County or Parish, State		
Sec 30 T16S R30E Lot 4 380FSL 330FWL					EDDY COUNTY, NM		
12. CHECK THE AJ	PPROPRIATE BOX(ES)	TO INDICA	ATE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent		Dea	ереп	Product	ion (Start/Resume)	U Water Shut-Off	
-	Alter Casing	🗖 Hy	draulic Fracturing	🗖 Reclam	ation	Well Integrity	
Subsequent Report	🗂 Casing Repair	🗆 Ne	w Construction	🛛 Recomp	olete	🗂 Other	
Final Abandonment Notice	Change Plans	🗖 Plu	g and Abandon	Tempor	arily Abandon		
	Convert to Injection	🗖 Plu	g Back	U Water D	Disposal		
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f COG Operating LLC respectfu	d operations. If the operation res bandonment Notices must be file inal inspection.	ults in a multip ed only after all	ele completion or reco requirements, includi	mpletion in a r	new interval, a Form 316	0-4 must be filed once	
We plan to have our top perfs of rat hole below our bottom p getting stuck with sand. In ado re-enter the paddock formatio	erfs to give our bottom ho dition to having desired rat	le assembly	room and preven	it tubing from	· .		
Please see the attached procedure, current and proposed wellbore diagrams.					NM OIL CONSERVATION ARTESIA DISTRICT		
Accepted for record - NMOCD APR 0.1 2019						R 0.1 2019	
				······································	R	ECEIVED	
 I hereby certify that the foregoing is Con 	s true and correct. Electronic Submission #4 For COG O nmitted to AFMSS for proce	156323 verific PERATING L Issing by PR	d by the BLM Well LC, sent to the Ca SCILLA PEREZ or	l Information Irisbad 1 02/28/2019) System (19PP1204SE)		
Name (Printed/Typed) DANA KIN				TING CON			
Cianatana (Plantana) (2. k		Data 00/20/20				
Signature (Electronic S	THIS SPACE FO		Date 02/28/20				
<u></u>						MAR 2 9 2019	
	thon Shepard				ngineer	MAIN Z J LUIS	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu- which would entitle the applicant to condu-	Carlsbad Field Office						
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent :	U.S.C. Section 1212, make it a c statements or representations as	crime for any p to any matter w	erson knowingly and vithin its jurisdiction.	willfully to ma	ke to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED	** BLM R	EVISED ** BLM	I REVISED	** BLM REVISE) **	

Blue Duck Federal #1H Proposed Recompletion Plan 30-015-40448

We plan to have our top perfs from 3,450' - 3,650'. Ideally, we like to have the additional space of rat hole below our bottom perfs to give our bottom hole assembly room and prevent tubing from getting stuck with sand. In addition to having desired rat hole space, this gives COG the option to re-enter the paddock formation at a later time.

Equipment Pull Procedure


- RIH w/ perforating guns and perforate San Andres Zone from 3,450'-3,650', w/ 3 spf, 120° phasing, 54 holes
- Dump bail acid in the perf interval
- NU 5K frac valve
- Secure wellbore
- RDMO WSU

Tentative Recompletion Procedure

- RU Elite Well Services Frac Crew
- Acidize w/ 3,000 gals of 15% HCl.
- XL Frac zone w/ 200,000 # of sand.
- Record ISIP and FG, Get 5, 10, 15 min SIP
- RDMO Elite

Return to Production Procedure

- MIRU WSU
- RIH with bit and bailer to drill
- Clean out fill to new PBTD @ 4,260'
- RIH with production tubing as follows:
 - o (101) jts 2-7/8" J55 6.5# tbg
 - o (1) 2' marker joint
 - o (2) jts 2-7/8" J55 6.5# tbg
 - o TAC @3,300'
 - o (12) jts 2-7/8" J55 6.5# tbg
 - o SN @ 3,680'
 - o (1) 20' MSMA
 - EOT @ 3,700'
- ND BOP, set TAC, flange up WH
 - RIH w/ rod design as follows:
 - (1) 26' × 1-1/2" SMPR
 - (1) 6' x ¾" rod sub
 - o (2) 8' x ¾" rod subs
 - o (140) 3/4" D rods
 - o (7) 1-5/8" K bars
 - o (1) 25-150 RHBC-20' Pump
- Hang on, load tubing and note pump action and alignment
- Clean location
- Update rod and tubing detail in Well View
- All charges will hit recompletion AFE (800/500) code
- PWOP
- RDMO, TOTP




CONCHO

Author:	Tower			
Well Name	BLUE DUCK	Well No.	#1H	
Field	WILDCAT	API #:	30-015-40448	
County	EDDY	Prop #:		
State	NM	Zone:		
Date	7/23/2012			
ĠL	3711'		· · · · · · · · · · · · · · · · · · ·	
кв	3728'			

Description	0.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8	H40	48	395	1050	Surface
Inter Csg	9 5/8	J55	36	2,705	1155	Surface
Prod Csg	7"X5 1/2"	L80	26	3758 8450	900	Surface
Liner	5 1/2	L80	17	3760 4047		

5 1/2" Liner tied into 7"

PROPOSED WELLBORE DIAGRAM



Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Workover/Deepening of a Well

- 1. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. <u>Cement</u>: Notify BLM if cement fails to circulate.
- Subsequent Reporting: Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. Show date work was completed. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.