Form 3160-5 (June 2015)

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137

SUNDRY NOTICES AND REPORTS

Field Office case Serial No. KIMNM29276 Do not use this form for proposals to drill or fo 6. If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 NMNM100181 Well Name and No. HAMMOND 17 FED 1 1. Type of Well Oil Well Sas Well Other ALICIA FULTON API Well No. Name of Operator Contact: APACHE CORPORATION 30-015-29450-00-S1 E-Mail: ALICIA.FULTON@APACHECORP.COM 10. Field and Pool or Exploratory Area 3b. Phone No. (include area code) 303 VETERANS AIRPARK LANE SUITE 3000 Ph: 432.818.1088 **RED LAKE** MIDLAND, TX 79705 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec 17 T18S R27E NWSE 1992FSL 1796FEL EDDY COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION □ Acidize □ Deepen □ Production (Start/Resume) ■ Water Shut-Off Notice of Intent ☐ Alter Casing ☐ Hydraulic Fracturing □ Reclamation ■ Well Integrity ☐ Subsequent Report Casing Repair □ New Construction □ Recomplete □ Other ☐ Final Abandonment Notice ☐ Change Plans □ Plug and Abandon ▼ Temporarily Abandon ☐ Convert to Injection ☐ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. apache is requesting approval to TA the wellbore 1. POOH w/ rods, packer and pump while laying down, TOOH w/ tubing and BHA
2. MIRU wireline, RIH w/ gauge ring, POOH, RIH w/ CIBP, set @ 9423? (top of perfs 9473?), POOH
3. RIH w/ dump bailer and spot 4 sxs (35?) of cement on top of CIBP, POOH 4. RIH and tag TOC. Record depth of TOC. RD WL 5. TIH w/ tubing (testing in) 6. Test casing. If tests good, circulate hole w/ packer fluid and biocide Note: If casing does not test, TA operations will be postponed and the well evaluated for P&A. 7. TOOH w/ tubing while scanning. Perform MIT TA well 14. I hereby certify that the foregoing is true and correct Electronic Submission #453537 verified by the BLM Well Information System
For APACHE CORPORATION, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 02/07/2019 (19PP1000SE) Name (Printed/Typed) ALICIA FULTON Title SR. REGULATORY ANALYST Signature (Electronic Submission) 02/06/2019 THIS SPACE FOR FEDERAL OR STATE OFFICE USE FEB /s/ Jonathon Shepard etroleum Engineer Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant fr certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

### Additional data for EC transaction #453537 that would not fit on the form

32. Additional remarks, continued

procedures and wellbore diagrams attached



Well name:

Hammond 17 Fed Com #1

API Number:

30-015-29450

County, State:

Eddy, NM

Legals:

SEC-17 TWP-18S RGE-27E

Depths:

MD ·

PBTD

**Producing Interval** 

9473-9494'

9680'

9633'

CSG Surface OD Wt/Ft 9.625" 36#

:/Ft Cap (bbl/ft) 6# 0.0773 Тор 0' Set @ 1550'

Production

5.500"

17# 0.0232

Ū

9680'

Engineer:

Assistant Foreman:

Alex Hernandez David Pedroza 432-818-1694 (o) 575-910-3283 (c) alex.hernandez@apachecorp.com
david.pedroza@apachecorp.com

Production Foreman

Javier Berdoza

575-441-5755 (c)

javier.berdoza@apachecorp.com

#### What's New:

- 1) Lay down packer and lay down rods and tubing for inspection
- 2) Set CIBP, cap w/ cement, and test casing integrity
- 3) TA well

#### **WELL HISTORY**

The well is currently shut in. Last production date was on 2/2018, yielding 0 BO, 0 BW, 1 MCF.

#### **OBJECTIVE:**

TA well. This well is currently producing from the Morrow formation. It is recommended that this well be TA'd for evaluation of uphole potential requiring geological and engineering review. Without the proper geological analysis, we stand a chance to lose valuable resources by prematurely plugging the well at this time.

#### PROCEDURE:

- 1. POOH w/ rods, packer and pump while laying down, TOOH w/ tubing and BHA
- 2. MIRU wireline, RIH w/ gauge ring, POOH, RIH w/ CIBP, set @ 9423' (top of perfs 9473'), POOH
- 3. RIH w/ dump bailer and spot 4 sxs (35') of cement on top of CIBP, POOH
- 4. RIH and tag TOC. Record depth of TOC. RD WL
- 5. TIH w/ tubing (testing in)
- 6. Test casing. If tests good, circulate hole w/ packer fluid and biocide
  Note: If casing does not test, TA operations will be postponed and the well evaluated for P&A.
- 7: TOOH w/ tubing while scanning. Perform MIT
- 8. TA well

Note: Please contact NMOCD 24 hours prior to performing MIT test.

## Apache Corp. Actual

GROUP:

Permian North

FIELD:

COUNTY:

Red Lake (BP)

LEASE/UNIT:

API NUMBER:

Hammond 17 FED COM

Eddy

30-015-29450

DATE:

Feb. 05, 2019 Alex Hernandez

BY:

WELL:

STATE:

New Mexico

Spud: 3/24/1997

**KB**= 3,442'

12-1/4"



8-3/4"

2-3/8" L-80 TBG w/ Pkr @ 9,386"

5/19/1997: Perf Morrow from 9,473-94', 2 SPF, 44 Holes

10/2/2006: Re-Perf Existing Sand. Pump N2 Foamed Acid w/ 1,500 gals & 104,00 sef N2

5-1/2" 17# Set @ 9,680' CMT W/ 650 SXS

TD = 9.680'**PBTD** = 9,633'

## Apache Corp. **Proposed**

GROUP:

Permian North

FIELD: LEASE/UNIT: Red Lake (BP)

30-015-29450

Hammond 17 FED COM

COUNTY:

Eddy

DATE:

BY:

Feb. 05, 2019 Alex Hernandez

WELL:


STATE:

New Mexico

Spud: 3/24/1997

API NUMBER:

**KB**= 3,442'



9-5/8" 36# Set @ 1,550' TOC @ Surf, Circ

CIBP @ 9,423' w/ 35' Cmt

'5/19/1997: Perf Morrow from 9,473-94', 2 SPF, 44 Holes

10/2/2006: Re-Perf Existing Sand. Pump N2 Foamed Acid w/ 1,500 gals & 104,00 sef N2

5-1/2" 17# Set @ 9,680' CMT W/ 650 SXS

TD = 9.680'**PBTD** = 9,633'

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Temporary Abandonment of Wells on Federal Lands Conditions of Approval

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

**Note:** TA status "will be effective for a period up to 1 year from the date of NOI approval and can be renewed annually thereafter" per IM NM-2016-017.

- A bridge plug (CIBP) or packer must be installed 50 to 100 feet above any open perforations or open hole. A CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 3. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 4. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 5. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 6. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.