	S NTERIOR GEMENT	OCD Arte	sia	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
	NOTICES AND REPORTS ON WELLS			5. Lease Serial No. NMLC028775B		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agre 8910123980	ement, Name and/or No.
1. Type of Well					8. Well Name and No. RJ UNIT 125	
2. Name of Operator COG OPERATING LLC Contact: ABIGAIL MONTGOMERY E-Mail: Abbym@bcmandassociates.com					9. API Well No. 30-015-03783-00-S1	
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-580-7161			10. Field and Pool or Exploratory Area GRAYBURG		
4. Location of Well (Footage, Sec.,	η)			11. County or Parish, State		
Sec 35 T17S R29E NENW T	L			EDDY COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	C Acidize	🗖 Dee	pen	Product	ion (Start/Resume)	□ Water Shut-Off
—	Alter Casing		Hydraulic Fracturing		Reclamation Well Integrit	
Subsequent Report	Casing Repair	🗖 Nev	v Construction	🗖 Recom	olete	D Other
☐ Final Abandonment Notice .	Change Plans		g and Abandon g Back	 Temporarily Abandon Water Disposal 		
2. Perf & Sqz 50 sx cmt @ 1 3. Perf & Sqz 190 sx cmt @ 5 4. Cut off well head, verify cn Top-off & S	548?-Surface.	,		•		
10p-0(1 8	G C Acce	- 4/15 pted for rec	M. NMOCD		E ATTACHED NDITIONS OF	• • •
		ole n	LacKer	(qui	red	
 I hereby certify that the foregoing Comn Name (Printed/Typed) ABIGAIL 	# Electronic Submission For COG nitted to AFMSS for proces	DPERATING L	LC, sent to the Ca	arisbad	-	
Signature (Electronic Submission)			Date 06/21/2018			
	THIS SPACE FO				SE	
		CAK-T			4-6-19	
Approved By onditions of approval, if any, are attach typy that the applicant holds legal or ec nich would en the the applicant to cond		at or			Date	
tle 18 U.S.C. Section 1001 and Title 43 States my false, fictitious or fraudulent	3 U.S.C. Section 1212, make it a	crime for any p s to any matter w	erson knowingly and	willfully to m	ake to any department or	agency of the United
nstructions on page 2)	/ISED ** BLM REVISE			I REVISEI) ** BLM REVISE	D **
*** 	• •					


ĉ

COG Operating LLC Lease & Well # RJ Unit #125 30-015-03783 Spud: 1/4/51 Elevation - 3549 ' KB gTop of cmt est @ 120' 8 5/8" H-40 28# csg @ 498'. 100 sx cmi. App of cmt est @ 1,500 T/Salt 420 B/Salt 780 SA 2811 San Andres 2476-80, 2438-50, 2 spi - 1-100 AFIG Acidized w/750 gal 15% HCL, frac w/20,000 gal gbw , 23,000 # sd. Lov , 2932 2646/2656 - 2600/-2618 Mater 7" 20# csg @ 3025". Cmt w/100 sx. -San Andres OH 3025 - 3188'. Acidized w/12.000 gal HCL, 6 treatments TD 3188 6" OH to 3288' 32.7947426 -104. 0496292

6/11/2018

RJ Unit # 125 Wellbore diagram

SH



SH

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/Condition of Approval for Lesser Prairie-Chicken:</u> From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted