Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	WELL API NO. 30-015-45368
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
<u>District IV</u> – (505) 476-3460 Santa Fe, NIVI 8/303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	SST 6 STATE COM
PROPOSALS.) 1. Type of Well: Oil Well	8. Well Number 121H
Name of Operator Matador Production Company	9. OGRID Number 228937
3. Address of Operator	10. Pool name or Wildcat
5400 LBJ Freeway, Ste. 1500, Dallas, TX 75240	PALMILLO; BONE SPRING, EAST (49553)
4. Well Location Unit Letter D 960 feet from the N line and	320 feet from the W line
Section 6 Township 19S Range 29E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	1
12. Check Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTENTION TO: SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOL	
·	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	NT JOB
DOWNHOLE COMMINGLE	• •
CLOSED-LOOP SYSTEM Design	•
OTHER Pend	rate, fracture treat, produce.
OTHER: OTHER: Performance 13. Describe proposed or completed operations. (Clearly state all pertinent details, a	
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test.
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped.	nd give pertinent dates, including estimated date completions: Attach wellbore diagram of ed to 5720 psi. Good test. 21 lbs sand.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 01/19 - 01/27/19 Mill plugs. Perform cleanout. 01/28/19 Install 2 7/8 L-80 tbg and GLVs. Packer @ 7017', tbg on packer 02/02/19 Open well to flowback.	at 7017'.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 01/19 - 01/27/19 Mill plugs. Perform cleanout. 01/28/19 Install 2 7/8 L-80 tbg and GLVs. Packer @ 7017', tbg on packer	nd give pertinent dates, including estimated date completions: Attach wellbore diagram of ed to 5720 psi. Good test. 21 lbs sand.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 01/19 - 01/27/19 Mill plugs. Perform cleanout. 01/28/19 Install 2 7/8 L-80 tbg and GLVs. Packer @ 7017', tbg on packer 02/02/19 Open well to flowback.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of d to 5720 psi. Good test. 21 lbs sand. at 7017'.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 01/19 - 01/27/19 Mill plugs. Perform cleanout. 01/28/19 Install 2 7/8 L-80 tbg and GLVs. Packer @ 7017', tbg on packer 02/02/19 Open well to flowback.	at 7017'.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 01/19 - 01/27/19 Mill plugs. Perform cleanout. 01/28/19 Install 2 7/8 L-80 tbg and GLVs. Packer @ 7017', tbg on packer 02/02/19 Open well to flowback.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. APR 2 9 2019
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 01/19 - 01/27/19 Mill plugs. Perform cleanout. 01/28/19 Install 2 7/8 L-80 tbg and GLVs. Packer @ 7017', tbg on packer 02/02/19 Open well to flowback.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of d to 5720 psi. Good test. 21 lbs sand. at 7017'.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. RECEIVED APR 2 9 2019 DISTRICT II-ARTESIA O.C.D.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19 Open well to test casing to 5907 psi for 30 min. Pressure dropped 01/13 - 01/18/19 Perforate & fracture treat Bone Spring 7495 - 12167' w/11,072,7 01/19 - 01/27/19 Mill plugs. Perform cleanout. 01/28/19 Install 2 7/8 L-80 tbg and GLVs. Packer @ 7017', tbg on packer 02/02/19 Open well to flowback.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. RECEIVED APR 2 9 2019 DISTRICT II-ARTESIA O.C.D.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. RECEIVED APR 2 9 2019 DISTRICT II-ARTESIA O.C.D.
13. Describe proposed or completed operations. (Clearly state all pertinent details, are of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. APR 2 9 2019 DISTRICT II-ARTESIA O.C.D.
13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. APR 2 9 2019 DISTRICT II-ARTESIA O.C.D.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. APR 2 9 2019 DISTRICT II-ARTESIA O.C.D.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. APR 2 9 2019 DISTRICT II-ARTESIA O.C.D.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. RECENED APR 2 9 2019 DISTRICT II-ARTESIA O.C.D. 18 Ige and belief. DATE 4/26/19 Ladorresources. PHONE: 972-371-5218
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. APR 2 9 2019 DISTRICT II-ARTESIA O.C.D. 18 Ige and belief. DATE 4/20/19
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 01/06/19	and give pertinent dates, including estimated date completions: Attach wellbore diagram of ad to 5720 psi. Good test. 21 lbs sand. at 7017'. RECENED APR 2 9 2019 DISTRICT II-ARTESIA O.C.D. 18 Ige and belief. DATE 4/26/19 Ladorresources. PHONE: 972-371-5218