Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised August 1, 2011 District I - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 WELL API NO. District II - (575) 748-1283 30-015-32806 **OIL CONSERVATION DIVISION** 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Mands 02019 District III - (505) 334-6178 STATE **FEE** 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 DISTRICT II-ARTESIA O.C.D. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH CRAWFORD 27 PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well X Other 004 2. Name of Operator 9. OGRID Number CIMAREX ENERGY CO. OF COLORADO 162683 3. Address of Operator 10. Pool name or Wildcat 600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701 WHITE CITY; PENN (GAS) 4. Well Location feet from the NORTH line and **WEST** Unit Letter D 660 1310 feet from the line 27 **NMPM** Section **Township 24S** Range 26E EDDY County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.602' - GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ P AND A **TEMPORARILY ABANDON** \Box CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING П MULTIPLE COMPL \Box CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: PLUG AND ABANDONED 05/07/19. OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 04/28/19: SET 7" CIBP @ 9,000'; CIRC.WELL W/ M.L.F.; PUMP 25 SXS @ 9,000'-8,900'; PUMP 110 SXS. CMT. @ 8,463'. 04/29/19: TAG CMT. PLUG @ 7,957'; PUMP 45 SXS. CMT. @ 5,361'-5,211'; CUT 7" CSG. @ 3,832' – NOT FREE. 05/02/19: SQZ. OUT CSG. CUT 50 SXS. CMT. @ 3,832' (PER OCD); WOC. 05/03/19: TAG CMT. PLUG @ 3,736'; PERF. X SQZ. 45 SXS. CMT. @ 1,885'-1,775'; PERF. X SQZ. 45 SXS. CMT. @ 1,209'; WOC X TAG CMT. PLUG @ 1,085'. 05/04/19: PERF. X SOZ. 40 SXS. CMT. @ 480'; WOC C TAG CMT. @ 368'; PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 25 SXS. CMT. @ 63'-3'. 05/07/19: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.: VERIFY CMT. TO SURF, ON ALL ANNULI; WELD ON STEEL Approved for plugging of well bore only. PLATE TO CSGS. X INSTALL DRY HOLE MARKER. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under forms, www.cmnrd.state.nm.ue/ocd. RDMO PXA RIG: 05/04/19 MIRU PXA RIG: 04/26/19 I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE: AGENT DATE: 05/08/19 E-mail address: DEYLER@MILAGRO-RES.COM PHONE: 432.687.3033 Type or print name: DAVID A. EYLER

For State Use Only