	•
Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office District I MAY 1 3 20th ergy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 811 S. First St., Artesia, NOSTRICT II-ARTESIA QIS CONSERVATION DIVISION	30-0 1 5-38957
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	G. State SA Co Can State State
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	QUALIFIER BQX STATE
PROPOSALS.) 1. Type of Well: Oil Well ⊠ Gas Well □ Other	8. Well Number #1H
2. Name of Operator	9. OGRID Number
EOG RESOURCES, INC	7377
3. Address of Operator PO BOX 2267 MIDLAND, TEXAS 79702	10. Pool name or Wildcat SAND TANK; BONE SPRING
	SAND TANK, BOND BIRDING
4. Well Location	er line
Unit Letter M: 660 feet from the SOUTH_line and 330 feet from the WE Section 32 Township 17S Range 30E NMPM County LEA	
Section 32 Township 178 Range 50E NNIPM County EEA 2	
3546' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other	Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	RILLING OPNS. P AND A
OTUED:	ready for OCD inspection after P&A
OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Op	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been	n properly abandoned.
A steel marker at least 4" in diameter and at least 4' above ground level has been set	in concrete. It shows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
	ON HAS BEEN WELDED OR
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and ha other production equipment.	s been cleared of all junk, trash, flow lines and
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. ☐ The location has been leveled as nearly as possible to original ground contour and has other production equipment. ☐ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground contour and has other production equipment.	s been cleared of all junk, trash, flow lines and
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and ha other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below growing if this is a one-well lease or last remaining well on lease, the battery and pit location(s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown if this is a one-well lease or last remaining well on lease, the battery and pit location OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, pro	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with oduction equipment and junk have been removed
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with oduction equipment and junk have been removed
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.)	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with oduction equipment and junk have been removed
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules.	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with duction equipment and junk have been removed noved. (Poured onsite concrete bases do not have
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines.	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with oduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles at	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with oduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles a location, except for utility's distribution infrastructure.	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with duction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. ☐ The location has been leveled as nearly as possible to original ground contour and has other production equipment. ☐ Anchors, dead men, tie downs and risers have been cut off at least two feet below grown of this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. ☐ All metal bolts and other materials have been removed. Portable bases have been removed.) ☐ All other environmental concerns have been addressed as per OCD rules. ☐ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines. ☐ If this is a one-well lease or last remaining well on lease: all electrical service poles at the content of the	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with duction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grown of this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles a location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to so	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with duction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below growing of the It is is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles a location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to so the complete of the proposition of the appropriate District office to so the complete of the proposition of the appropriate District office to so the proposition of the appropriate District office to so the proposition of the appropriate District office to so the proposition of the appropriate District office to so the proposition of the appropriate District office to so the proposition of the appropriate District office to so the proposition of the appropriate District office to so the proposition of	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with duction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well chedule an inspection. PECIALIST DATE 04/01/2019
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below grows if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles a location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to so SIGNATURE TITLE: REGULATORY S TYPE OR PRINT NAME: KAY MADDOX E-MAIL: kay maddox@eogresource For State Use Only.	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with eduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well chedule an inspection. PECIALIST DATE 04/01/2019 s.com PHONE: _432-686-3658
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below growing if this is a one-well lease or last remaining well on lease, the battery and pit location (OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMA retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles a location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to so SIGNATURE MAULUM TITLE: REGULATORY STAME TYPE OR PRINT NAME: KAY MADDOX E-MAIL: kay maddox@eogresource.	s been cleared of all junk, trash, flow lines and bund level. s) have been remediated in compliance with eduction equipment and junk have been removed noved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- and lines have been removed from lease and well chedule an inspection. PECIALIST DATE 04/01/2019 s.com PHONE: _432-686-3658