Form 3160-5 (June 2015) DI	UNITED STATE EPARTMENT OF THE I	S NT KRIGR	chad D	- 11 - 12 - 14 - 14	FORM OMB N	APPROVED (O. 1004-0137 anuary 31, 2018
B SUNDRY	UNITED STATE EPARTMENT OF THE I UREAU OF LAND MANA NOTICES AND REPO	RTS ON W	OFD A	leia () rtogia	NMNM36975	anuary 51, 2016
abandoned we	NOTICES AND REPO is form for proposals to II. Use form 3160-3 (AP	D) for such p	proposals.	i CC219	6. If Indian, Allottee	or Tribe Name
SUBMIT IN	TRIPLICATE - Other ins	tructions on	page 2	- ,	7. If Unit or CA/Agre	ement, Name and/or No.
1. Type of Well	her	1 <u>-</u>			8. Well Name and No. KANSAS 21/28 V	V1LM FED COM 1H
2. Name of Operator MEWBOURNE OIL COMPAN	Contact:	JACKIE LAT			9. API Well No. 30-015-45763-0	00-X1
3a. Address P O BOX 5270 HOBBS, NM 88241		3b. Phone No Ph: 575-39	. (include area code) 3-5905		10. Field and Pool or WOLFCAMP	Exploratory Area
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description	l			11. County or Parish,	State
Sec 21 T24S R28E SWNW 26 32.203335 N Lat, 104.100136					EDDY COUNT	Y, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION		
□ Notice of Intent	□ Acidize	🗖 Dee	pen	D Producti	on (Start/Resume)	□ Water Shut-Off
Subsequent Report	Alter Casing		raulic Fracturing	🗖 Reclama		U Well Integrity
	Casing Repair	-	Construction	Recomp		🛛 Other Well Spud
Final Abandonment Notice	□ Change Plans □ Convert to Injection	📋 Plug	and Abandon Back	☐ Tempora	arily Abandon isposal	-
determined that the site is ready for f 4/12/19 Spud 17 1/2" hole @ 455'. Ra w/additives. Mixed @ 14.2#/g w/1.74 yd. Tail w/200 sks Class Plug down @ 11:15 PM 04/12 survey indicating ToC @ 90'. 0 stages w/75 sks Class C w/6% 5000# & Annular to 3500#. At	n 439' of 13 3/8" 54.5# J5 w/1.67 yd. Followed w/27 ss C w/2% CaCl2. Mixed v /19. Did not circ cmt to su Cmt w/1" pipe to surface. 6 CaCl2. Mixed @ 14.8#/ 9:00 P.M. 04/15/19, téste	75 sks Class (@ 14.8#/g w/ urface. Lift pre PU 1" pipe & g w/1.34 yd. (C w/additives. Mi 1.34 yd. Displace ssure 800# @ 3 tagged @ 83'. R Circ 13 sks to cel	xed @ 13.5# ed w/40 bbls BPM. Ran te an 1" pipe in lar. Test BO	#/g of FW. emp i 3 PE to	Ned
to 10.0 PPG EMW. Drilled out			,	alia		
Copy of chart & schematic atta	ached.	G (Accept	ed for record.	NMOCD	JUN 2	5 2019
14. I bencher endigt ab 44 e Generation in	4	,				TESIAOGD.
14. I hereby certify that the foregoing is	Electronic Submission #4	RNE OIL COM	PAŃY, sent to the	e Carlsbad	•	
Name (Printed/Typed) JACKIE L	ATHAN		Title REGUL/	ATORY	<u>. </u>	
Signature (Electronic S	Submission)		Date 05/30/20)19		
	THIS SPACE FC	OR FEDERA	L OR STATE (OFFICE US	E	
Approved By			Title Acce	epted fo	r Record	MAX 3 0 2019
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to condu	itable title to those rights in the			onathon S arisbad Fiel	•	
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to mal	ke to any department or	agency of the United
Instructions on page 2) ** BLM REVI	SED ** BLM REVISED	D ** BLM RE	VISED ** BLM	REVISED	** BLM REVISE	D **

Additional data for EC transaction #467047 that would not fit on the form

ţ


32. Additional remarks, continued


Copy of temperature attached.

t

Ŧ

Bond on file: NM1693 nationwide & NMB000919





 0	TE	EMP (degF)		250
0 GR (GAPI)	100	-5	DTMP (degF)	5
TEMP		1		
(degF)	;			

· · · · ·

x

WEDL
MARY WEAR
Company MEUNDORNE Date 4-14-19
Lease KANSAS 21/28 WILLM FED POM HOUNTY Eddy
Drilling Contractor PAHERSON 231 Plug & Drill Pipe Size 12" (22 41/618 - CET 39
Accumulator Pressure: 3000 Manifold Pressure: 1500 Annular Pressure: 1100
Accumulator Function Test - 00&G0#2
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)
 Make sure all rams and annular are open and if applicable HCR is closed.
• Ensure accumulator is pumped up to working pressure! (Shut off all pumps)

ING SERTING

- 1. Open HCR Valve. (If applicable)
- 2. Close annular.

Ø

- 3. Close all pipe rams.
- 4. Open one set of the pipe rams to simulate closing the blind ram.
- 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
- 6. Record remaining pressure 1600 psi. Test Fails if pressure is lower than required.
- a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system }
- 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 a. {800 psi for a 1500 psi system}
 b. {1100 psi for 2000 and 3000 psi system}
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop <u>975</u> psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}


To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular


Q


- 3. With pumps only, time how long it takes to regain the required manifold pressure.
- 4. Record elapsed time TAN JEC Test fails if it takes over 2 minutes.
- **a**. {950 psi for a 1500 psi system} **b**. {1200 psi for a 2000 & 3000 psi system)


L P	oquirod	WELDING SERVICES : MEWBOURNE WEBOURNE WEBOURNE WELDING SERVICES : MEWBOURNE WELDING SERVICES : MEWBOURNE : MEWBOUR	Lor	UP SERVIC MUD AND G Alegesa, NM Dete: Dete: Detilling (///	AS SEPARA 878-9 <u>4</u> Contractor	rs • TANDEM TORS 88-4549 Pg of -14-19 Invoctors @ B092502
BLM D		Annulor #15 Pipe Roms #13 Pipe Roms #13 Pipe Roms #14 Pipe Roms #14	#25 #2 #2 #3 #1 #25 Suppor Ch	#5 #98 Mud Gaug Valva	₩	Image: stand Pipe Stand Pipe Valve 019 Stand Pipe Valve 180P 10 917 10 180P 10 916 Pump Valve 820 121
	TEST #	TTEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
				A	THUTTU	
		TRUCK TECH	10/10	250		
4/218	-1-2	TRUCK TECH	io lio Idlio			
4/21F		12,10,8,20,21	. //	250	5000 5000 5000	FAIL-WARDEDVALLE FAIL-WARDEDVALLE
4/21F		12,10,8,20,21	idia	250	5000 5000 5000	FAIL - WHERE VALUE
4/21F		12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24	10/10 10/10 20/10 50/10	250 255 251)	5000 5000 5000	Pass FAIL-WHRVEDVALVE FAZC FASS FASS
4/21F	24	12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24 12,121,M,1,2,10,88,19 14,110	Idlia 10/10 Inlia	250 257) 257) 257 257	5000 5000 5000 5000	Pass Fail-unaber value Faic Fass Fass
4//21F V	N- 4 - 5 7	12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24 12,121,M,1,2,10,88,19 14,110	10/10 10/10 20/10 50/10	250 257 257 257 250 250	5009 5000 5001 5000	Pass FAIL-WHRVEDVALVE FAZC FASS FASS
Ч/21F ↓ √ .ET39	N-2 4 -9 7	12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24	10/10 10/10 20/10 50/10	250 251) 251) 252 250 250 250	5000 5000 5000 51000 51000 51000	Pass FA:1WAVED VALVE FASS FASS
\checkmark	N-2 4 -9 7	12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24 12,121,M,1,2,10,88,19 14,110	10/10 10/10 20/10 50/10	250 257 251) 257 250 250 250	5000 5000 5001 5100 5102 5102 3570	FA:1WARDEDVALLE FA:1WARDEDVALLE FAXE FAXE FAXE FASS FASS
\checkmark	N- 4 - 7 1- 80	12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24 12,11,7,24 12,10,8,1,2,10,88,14 14,110 15,9,7,110 12,9,8	10/10 10/10 20/10 50/10	250 257 257 257 250 250 250 250	5009 5000 5000 5000 5000 5000 5000 5000	Pass FAIL-UNRVEDVALLE FAXE FAXE FAXE FASS FASS FASS FASS
\checkmark	N-7 4 4 7 200	12, 10, 8, 20, 21 18, 10, 8, 20, 21 12, 11, 7, 24 12, 12, 10, 1, 2, 10, 88, 14 14, 110 15, 9, 7, 110 12, 9, 8 14	10/10 10/10 20/10 50/10	250 257 257 257 250 250 250 250	5009 5000 5000 5000 5000 5000 5000 5000	Pass FA:1WARDEDVALLE FAXE FAXE FAXE FASS FASS FASS
\checkmark	1 1 1 1 1 1 2 C C	12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24 12,10,1,2,10.88,14 14,110 15,9,7,110 12,9,8 14 15,9,8	10/10 10/10 20/10 50/10	250 251) 251) 250 250 250 250 250 250	5000 5000 5000 5000 5000 5000 5000 500	Pass FA: 1 - a half = 2 value FA: c FA: c
.ет39		12, 10, 8, 20, 21 18, 10, 8, 20, 21 12, 11, 7, 24 12, 12, 10, 1, 2, 10, 88, 14 14, 110 15, 9, 77, 110 12, 9, 8 14 15, 9, 8 19	10/10 10/10 20/10 50/10	250 250 251 250 250 250 250 250 250 250 250 250 250	5000 5000 5000 5000 5000 5000 5000 500	Pass FA:1andbez value FA:2 FA:2 FA:5 FA:5 FA:5 FA:5 FA:5 FA:5 FA:5 FA:5
.ет39		12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24 12,11,7,24 12,10,8,20,21 12,10,8,20,21 12,10,8,20,21 14,110 15,9,7,110 12,9,8 14 15,9,8 19 18	$ \frac{10110}{1010} $ $ \frac{1010}{1010} $	250 250 250 250 250 250 250 250 250 250	5000 5000 5000 5000 5000 5000 5000 500	Pass FA:1andbez value FA:2 FA:2 FA:5 FA:5 FA:5 FA:5 FA:5 FA:5 FA:5 FA:5
.ет39		12, 10, 8, 20, 21 18, 10, 8, 20, 21 12, 11, 7, 24 12, 12, 10, 88, 14 14, 110 15, 9, 7, 110 12, 9, 8 14 15, 9, 8 19 18, 9, 3, 4, 5	$ \frac{10}{10} $	250	5000 5000 5000 5000 5000 5000 5000 500	Pass FA: 1and be D value FA: 2 FA: 2 FA: 2 FA: 5 FA:
.ет39		12,10,8,20,21 18,10,8,20,21 12,11,7,24 12,11,7,24 12,11,7,24 12,10,8,20 12,10,8,20 12,10,8,20 14,110 15,9,7,110 12,9,8 14 15,9,8 19 18 19	$ \frac{10}{10} $	250	5 6 6 9 5 7 8 9 5 7 8 9 5 7 8 9 5 7 8 9 5 7 7 8 5 7 7 7 8 5 7 7 7 8 5 7 7 7 8 5 7 7 7 8 7 7 7 7 7 7 7 8 7 7 7 7 7 7 7 7	Pass FA: 1and be D value FA: 2 FA: 2 FA: 2 FA: 5 FA:
\checkmark		12, 10, 8, 20, 21 18, 10, 8, 20, 21 12, 11, 7, 24 12, 12, 10, 88, 14 14, 110 15, 9, 7, 110 12, 9, 8 14 15, 9, 8 19 18, 9, 3, 4, 5	$ \frac{10}{10} $	250	5 6 6 9 5 7 8 9 5 7 8 9 5 7 8 9 5 7 8 9 5 7 7 8 5 7 7 7 8 5 7 7 7 8 5 7 7 7 8 5 7 7 7 8 7 7 7 7 7 7 7 8 7 7 7 7 7 7 7 7	Pass FA: 1and be D value FA: 2 FA: 2 FA: 2 FA: 5 FA:
.ет39		12, 10, 8, 20, 21 18, 10, 8, 20, 21 12, 11, 7, 24 12, 12, 10, 88, 14 14, 110 15, 9, 7, 110 12, 9, 8 14 15, 9, 8 19 18, 9, 3, 4, 5	$ \frac{10}{10} $	250	5 6 6 9 5 7 8 9 5 7 8 9 5 7 8 9 5 7 8 9 5 7 7 8 5 7 7 7 8 5 7 7 7 8 5 7 7 7 8 5 7 7 7 8 7 7 7 7 7 7 7 8 7 7 7 7 7 7 7 7	Pass FA: 1and be D value FA: 2 FA: 2 FA: 2 FA: 5 FA:





· · · · ·











ជ