Submit 1 Copy To Appropriate District Office		State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised July 18, 2013	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	25 N. French Dr., Hobbs, NM 88240         strict II - (575) 748-1283         1 S. First St., Artesia, NM 88210         strict III - (505) 334-6178         00 Pio Reverse Pd. Artec NM 87410    OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		WELL API NO. 30-005-62596		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease		
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE STATE FEE		
Santa Fe, NM 87505 $\frac{1000}{100}$ Santa Fe, NM 87505 220 S. St. Francis Dr., Santa Fe, NM 7505		505	5. State Oil & Gas Lease	No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			<ol> <li>Lease Name or Unit Agreement Name</li> <li>Abbey State SWD</li> </ol>		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 1		
2. Name of Operator D.W.R. Oil Properties, Inc.			9. OGRID Number 32864		
3. Address of Operator PO Box 657, Merkel TX 79536			10. Pool name or Wildcat 9664- SWD Fusselman		
4. Well Location Unit Letter H 2290 feet from the N line and 1200 feet from the E line					
Unit Letter H : Section 36			00 feet from the	<u>E</u> line	
Section 30	11. Elevation (Show whether DR,			ty	
3698 GR					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
·	ITENTION TO:		EQUENT REPORT		
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK       ALTERING CASING         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       P AND A					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
CLOSED-LOOP SYSTEM		OTHER: Perforate,	Acidize and run Packer	· 🖄	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
6/27-28/19: MIRU pulling unit, RIH w/ bit, collars and workstring. Drill out DV tool @ 6287'. RIH and tag PBTD @ 7193'.					
Circulate well					
7/1/19: MIRU wireline and run CBL and CNL logs. Found PBTD @ 7192, DV tool @ 6275 and good cement from bottom to top. Perforate: 6816-28, 6855-60, 6880-89, 6901-12, 6924-31, 6986-92, 7038-50 and 7061-86', 2 shots/foot					
7/2/19: Acidize perforations with 10,000 gallons 15% NEFE acid, ISDP 0					
7/3/19: LD workstring				JUL <b>1 2</b> 2019	
7/4/19: RIH w/ nickel coated	packer and 2 3/8" IPC tubing. Circu	late packer fluid and	Set packer @ 6770'.	JUL 1 4 2019	
Spud Date: June 12, 2019	Rig Release Da	te: 6/24/19	DIST	RICT/I-ARTESIAO.C.D.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
				· .	
SIGNATURE	TITLECo	onsultant	· · · · ·	<u>7/1</u> 0/19	
Type or print name Phelps Whit For State Use Only	E-mail address	pwiv@zianet.com	n PHONE:	575 626 7660	
APPROVED BY: Doda	TITLE Com	pliance of	Jicer DATE 7	-16-19	
Conditions of Approval (if any):					