Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No.
NMLC063136A

SUNDRY Do not use thi abandoned we	1 NIMILO	S. Well Name and No.  POKER LAKE 577  NMLC063136A  6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.							
SUBMIT IN	7. If Unit o	7. If Unit or CA/Agreement, Name and/or No.							
1. Type of Well	8. Well Nat	8. Well Name and No. POKER LAKE 57							
○ Oil Well									
XTO PERMIAN OPERATING		9. API Well No. 30-015-24269-00-S1							
3a. Address 6401 HOLIDAY HILL ROAD E MIDLAND, TX 79707	3b. Phone No. Ph: 432-22	(include area code) 1-7379		10. Field and Pool or Exploratory Area DELAWARE					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	)			11. County	11. County or Parish, State			
Sec 28 T25S R31E SESW 33			EDDY	EDDY COUNTY, NM					
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICI	E, REPORT,	OR OTH	ER DATA		
TYPE OF SUBMISSION TYPE OF ACTION									
☐ Notice of Intent	☐ Acidize	Acidize Deepen		☐ Produ	ction (Start/R	tion (Start/Resume)		■ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing ☐ Recla			mation		☐ Well Integrity		
Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recor	nplete		□ Other		
☐ Final Abandonment Notice	☐ Change Plans	Change Plans   Plug and A			rarily Abandon			•	
	☐ Convert to Injection	Plug	Back	☐ Water Disposal					
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  XTO Permian Operating, LLC respectfully submits the sundry notice of intent to plug and abandon the referenced well. In reviewing the file, no record of sundry being filed at time of P&A could be  **RECLAMATION PROCEDURATION PROCEDURATI									
11/28/18-12/03/18 MIRU plugging equipment. PC POOH w/tbg.  12/04/18 Set 4.5" CIBP @ 8170', tag to		e salt gelled m	nud. contact BLI	: M. Dumo b	ail		AMAT) 6-11-19		
3 <u>5' cmt on</u> CIBP		A.	repted for rec	ord KM	OCD				
	Electronic Submission #	AN OPERATII	IG LLC, sent to t CILLA PEREZ or	the Carlsba 1 06/10/2019 _ATOR <u>Y_C</u>	d 9 (19DLM0012 OORDINAT	OR .			
Signature (Electronic S	Submission)	·	Date 06/08/2	A(	CEPTEL	FOR	RECORD		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE	USE IIIN	1.3.20	110		
Approved By			Title		MICHI		Date		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the		Office		BUREAU OF L	AND MAN D FIELD OI	AGEMENT			
Title 18 U.S.C. Section 1001 and Title 43	IISC Section 1212 make it a	oring for any no	rean knowingly and	l willfully to	maka ta any da	nortment or	aganay of the II-	itad	

### Additional data for EC transaction #468216 that would not fit on the form

#### 32. Additional remarks, continued

12/05/18

RIH w/second CIBP @ 6421', tag to verify. Circulated salt gelled mud. PT csg to 500 (good). Spot 25 sx C 6421'-6043'.

12/06/18

Tg cmt @ 6035'. Set pkr @ 5547', perf sqz holes @ 5980'. Could not EIR. Contact BLM. Drop pkr down to 6030'. Spot 25 sx C 6030'-5650'. WOC 4 hrs. Tag cmt @ 5640'. Set pkr @ 3624'. Perf szq holes 4230'. EIR and sqz 150 sx C 4230'- 3890'. SDFWE

12/10/18

Tag cmt @ 2555'. Set pkr @ 693', perf sqz holes 1300'. EIR and sqz 150 sx C 1300'-950'.

12/11/18

Tag cmt @ 930'. Perf sqz holes at 60'. EIR and sqz 40 sx C to surface.

01/21/19

Cut off WH below surface. Install marker. Well P&A'd

# Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD Form 3160-3). Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filting the Well Completion or Recompletion Report and Log (Form 3:60-4). For final reclamation, the appropriate time for submittal would be when filting the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3:60-5), is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment Form 3160-5 following the plugging of a view.
- 4. Previous instruction had you making for a BLM specialist to inspect the location and provide you with reciamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Motice I ou are free to proceed with reciamation as per approved APD If you

- work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Evinconmental Protection Specialist 575-234-5996

Trishia Bad Bear Hobbs Field Station Natural Resource Specialist 575-393-3612