Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No. NMLC028775B

SUNDRY NOTICES AND REPORTS ON WELLS].
Do not use this form for proposals to drill or to re-enter an	6

If Indian. Allottee or Tribe Name

abandoned wei	I. Use form 3160-3 (APD)	TOY SUSTISTIFICE THARTES	AO.C.D.	·	
SUBMIT IN 1	7. If Unit or CA/Agr 8910123980	7. If Unit or CA/Agreement, Name and/or No. 8910123980			
Type of Well ☐ Gas Well ☐ Oth	8. Well Name and No RJ UNIT 101).			
Name of Operator COG OPERATING LLC	9. API Well No. 30-015-03155-	-00-S1			
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701 3b. Phone No. (include area code) Ph: 432-580-7161			10. Field and Pool of GRAYBURG	Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish	11. County or Parish, State	
Sec 27 T17S R29E NENW Tra	EDDY COUNT	Y, NM			
12. CHECK THE AP	PROPRIATE BOX(ES) T	O INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☑ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	 □ Deepen □ Hydraulic Fracturing □ New Construction ☑ Plug and Abandon □ Plug Back 	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1. Set 7" CIBP @ 2600'. Spot 25 sx cmt on top. Circulate hole w/ MLF. 2. Set 7" CIBP @ 2300'. Spot 25 sx cmt on top. Pressure test csg. to 500 psi. Circulate hole w/ MLF. 3. Perf & Sqz 300'. Spot 25 sx cmt on top. Pressure test csg. to 500 psi. Circulate hole w/ MLF. 4. Perf & Sqz 45 sx @ 60' to surface. 5. Cut off wellhead and weld on Below Ground Dry Hole Marker. SEE ATTACHED FOR CONDITIONS OF APPROVAL					
14. I hereby certify that the foregoing is true and correct. Electronic Submission #463512 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by DEBO RAH MCKINNEY on 04/30/2019 (19DLM0449SE) Name (Printed/Typed) ABIGAIL ANDERSON Title AGENT					
Signature (Electronic S	ubmission)	Date 04/30/20) 19		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By James	a. a. amos	 1100	16T	5-26-15 Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to condu	itable title to those rights in the sect operations thereon.	ubject lease Office CFC	<i>D</i>		
Title 18 U.S.C. Section 1001 and Title 43 U States any faise, fictitious or fraudulent s	U.S.C. Section 1212, make it a cr tatements or representations as to	ime for any person knowingly and any matter within its jurisdiction.	willfully to make to any department of	or agency of the United	

COG Operating LLC

Lease & Well # RJ Unit #101

Spud: 5/31/50

Elevation - 3537'

J-50.H 240

Rel Sd 1760 66 2430

GR- KILLY 32-15

PBTD 3254'

KB-

3 470 8 5/8" 28# @ 345', 50 sx cmt.

Top of cmt calc 1,000' fs.

Grayburg

2326-2334

Acidized w/500 gal 15% NE

Cmt w/100 sx.

TOC calc @ 1,000' from surface

7" 23# csg @ 2621'. こんの

San Andres

OH 2621 - 32581.

Acidized w/5000 gal 15%

Fraced w/10,000 gal oil, 10,000 # sd

6 /1/8" OH to 3258'

COG Operating LLC

Lease & Well # RJ Unit #101

Spud: 5/31/50

Elevation - 3537'

1 Palisez 45 smo

60 - 5 m/Ace

3 P-1 : Sp2 55 54

C 395-295 TAG

KB -

8 5/8" 28# @ 345', 50 sx cmt.

Top of cmt calc 1,000' fs.

(1) 7" CIBPO 2300 W/

2**-5** 5 x

OTCIBLE SEEDY

PBTD 3254'

Grayburg

2326-2334

Acidized w/500 gal 15% NE

Cmt w/100 sx.

TOC calc @ 1,000' from surface

7" 23# csg @ 2621'.

San Andres

OH 2621 - 3258'.

Acidized w/5000 gal 15%

Fraced w/10,000 gal oil, 10,000 # sd

6 /1/8" OH to 3258

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.