Form 3160-5 (June 2015)

(Instructions on page 2)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

# **NMOCD** Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

	OMB No. 1004-0137 Expires: January 31, 2018	
ase Serial	No. M-50415	

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2	7. If Unit of CA/Agreement, Name and/or No.
1. Type of Well	
✓ Oil Well Gas Well Other	8. Well Name and No. McClellan Federal #1
2. Name of Operator Primero Operating, Înc.	9. API Well No. 30-005-63076
3a. Address PO Box 1433, Roswell, NM 88202-1433 3b. Phone No. (include area code)	10, Field and Pool or Exploratory Area
(575) 622-1001	South Lone Wolf Devonian
4. Location of Well (Footage, Sec., T.R.,M., or Survey Description) 182' FNL & 507' FWL, Sec 26, T13S, R29E	11. Country or Parish, State. Chaves, New Mexico
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTIO	
TYPE OF SUBMISSION TYPE OF ACT	
Notice of filteric	uction (Start/Resume) Water Shut-Off
	umation Well Integrity
	mplete Other
	orarily Abandon r Disposal
MI Wireline truck and set CIBP @ 9500', RIH w/ tubing and displace hole with plug mud Pump Plug 1: 40 sx class H @ 9500'; 9160-9500' to cover top of CIBP and Mississippian @ 9160 Perforate 7130' and squeeze plug 2: 40 sx class H @ 7130'; 7030-7130' to cover top of Wolfcamp Perforate 6195' and squeeze plug 3: 40 sx class C @ 5195'; 5095 to 5195 to cover top of Tubb for Perforate 2376' and squeeze plug 4: 40 sx class C @ 2376'; 2276 to 2378' to cover top of San Anderson Perforate 350' and squeeze plug 5: 100 sx to load inside and outside of 5 1/2" casing as surface plugging the casing head will be cut off and a plate and dry hole marker will be welded on. Tremediated to BLM standards.	subsequent reports must be filed within 30 days following new interval, a Form 3160-4 must be filed once testing has been been completed and the operator has determined that the site seen completed and the operator h
4. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Phelps White President	APPROVED AUG 2 8 2019
Signature Date  THE SPACE FOR FEDERAL OR STATE OF	05/06/2019 <b>DISTRICTI/-ARTESIAO.C.</b> C
Approved by BUREAU	OF LAND MANAGEMENT SWELL FIELD OFFICE

Plug 5: 100 sx C Surface to 350' Perforate 350'

Plug 4: 40 sx @ 5195' 5095 to 5195' Perforate5195'

24.20

Plug 3: 40 sx Class C @ 5195' 5095-5195' Perforate 5195'

Plug 2; 40 sx Class H @ 7130' 7030 to 7100' . Perforate 7130'

Plug 1: 40 sx Class H @ 9500' 9050-9160 CIBP @ 9500' McClellan Federal #1 API # 30-005-63076 Sec 26, T13S, R29E

Wellbore

13 3/8" 48# H40 @ 304' 310 sx, circulate 60 sx

8 5/8" 24# @ 2328' 1500 sx, circulate 110 sx

Formation Tops

San Andre 2347 Tubb 5140 Wolfcamr 7088 Mississipp 9160

Est TOC 8400'

Whipstock @ 9540'

TD 9862'
5 1/2" 17# N-80 @ 9847'
300 sx, est TOC 8400'

#### McClellan Federal 1 30-005-63076 Primero Operating, Inc. August 26, 2019 Conditions of Approval

- 1. Operator shall place CIBP at 9,500' and place 40 sxs of Class H cement on top as proposed. WOC and TAG.
- 2. Operator shall perf and squeeze at 7,130'. Operator shall place a balanced Class C cement plug from 7,130'-6,960' to seal the top of the Wolfca,p formation. WOC and TAG.
- 3. Operator shall perf and squeeze at 6,036. Operator shall place a balanced Class C cement plug from 6,036'-5,876' to seal the top of the Abo formation. WOC and TAG.
- 4. Operator shall perf and squeeze as proposed at 3,784'. Operator shall place a balanced Class C cement plug from 3,784'-3,644' to seal the Glorietta Formation. WOC and TAG.
- 5. Operator shall perf and squeeze as proposed at 2,378'. Operator shall place a balanced Class C cement plug from 2,378'-2,278' to seal the 8-5/8" casing shoe. WOC and TAG.
- 6. Operator shall perf and squeeze at 1,050°. Operator shall place a balanced Class C cement plug from 1,050°-850° to seal the top of the Yates and bottom of the Salt formation. WOC and TAG.
- 7. Operator shall perf and squeeze at 500'. Operator shall place a balanced Class C cement plug from 500'-254' to seal the top of the Salt formation and the 13-3/8' casing shoe. WOC and TAG.
- 8. Operator shall perf and squeeze as proposed at 100'. Operator shall place a balanced Class C cement plug from 100'-surface as proposed.
- 9. See Attached for general plugging stipulations.

JAM 082619

### BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

## Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations.</u> For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. <u>Engineer on call during office hours phone (575) 627-0237 or phone (after hours) call (575) 626-5871.</u>
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.