Form 3160-5 (June 2015)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROV	Ŀυ
OMB NO. 1004-0	137
Expires: January 31	, 2018

₽.	Deade Dellar 110.	
	NMLC028731A	

SUNDRY NOTICES AND REPORTS ON WELLS OF Artesia Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NMNM111789X		
Type of Well					8. Well Name and No. DODD FEDERAL	UNIT 95
2. Name of Operator COG OPERATING LLC	ABIGAIL ANDERS cmandassociates.com			9. API Well No. 30-015-26535-0	00-S1	
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701	3b. Phone No. (inch Ph: 432-580-710	ide area code) 31		10. Field and Pool or DODD-GLORIE	Exploratory Area ETA-UPPER YESO	
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description)			11. County or Parish,	State
Sec 22 T17S R29E SESW 99				EDDY COUNT	Y, NM	
12. CHECK THE AI	PROPRIATE BOX(ES)	TO INDICATE N	ATURE O	F NOTICE	REPORT, OR OT	HER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION		
Notice of Intent	☐ Acidize	Deepen		☐ Produc	tion (Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Hydraulic	Fracturing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	Casing Repair	☐ New Con	ew Construction		plete	Other
☐ Final Abandonment Notice	□ Change Plans	Plug and .	g and Abandon		rarily Abandon	
•	☐ Convert to Injection	Plug Back Water		■ Water I	Disposal	
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final structure of the complete of	k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. irculate hole w/ MLF. Pre 20'. WOC & Tag (DV Too WOC & Tag (B/Salt)	the Bond No. on file vesults in a multiple comed only after all requires essure test csg. Sp. 1)	vith BLM/BIA pletion or reco ements, include ot 25 sx cm	x. Required submpletion in a ling reclamation if a 3921-3	bsequent reports must be new interval, a Form 310 n, have been completed	e filed within 30 days 60-4 must be filed once
	Accepted for reco	/23/19 rd · NMOCD		SE CO	E ATTACHED NDITIONS OI	FOR FAPPROVAL
14. I hereby certify that the foregoing is	Electronic Submission #	475054 verified by t			n System	
Committed to AFMSS for processing by DEBO Name (Printed/Typed) ABIGAIL ANDERSON			MCKINNEY (on 07/25/201 ATORY	9 (19DLM0580SE)	
Signature (Electronic S	Submission)	Date	07/24/2	019	,	
	THIS SPACE FO	OR FEDERAL O	R STATE	OFFICE U	SE	· · · · · · · · · · · · · · · · · · ·
Approved By Conditions of approval, if any, are attache		s not warrant or	e SPL	ア		7.26-19 Date
certify that the applicant holds legal or equ which would entitle the applicant to condu		e subject lease Off	ice <i>CFO</i>			

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

COG Operating, LLC

Lease & Well # Dodd Federal Unit #95 3001526535 Sec 22 T 17S R 29E, 990 FSL & 2360 FWL UNIT N Spud date 12-3-90 Completion date 12-28-90 Dodd-Glorieta-Upper Yeso (97917) Elevation - 3543 GL T/Salt - 295 17 1/2" hole B/Salt - 830 13 3/8" 48 & 54# @ 213' w/225 sx. Circ 70 sxs." Vates - 930 TOC @ 640'. CBL Qu - 1815 SA - 2440 G-C-3902 Yesu - 3968 DV Tool @ 2243' San Andres 2658'-3253' *according to OCD Files, pg.12, these perfs are fictitious Perf'd PDK @ 3971'-4246', A/7,000 gals 15% A/ 32K gals heated 20%. 12-27-90 IP P 60 BO, 47 MCF & 100 BW 01-01-91 PBTD - 4460° 5 1/2" 17# csg @ 4461' w/2500 sx. Circ 50 sxs @ DVT. -TD @ 4520'

32.8155289 -104.0635452

COG Operating, LLC

Lease & Well

Dodd Federal Unit #95

3001526535 Spud date 12-3-90 Completion date 12-28-90 Elevation - 3543 GL

Sec 22 T 17S R 29E, 990 FSL & 2360 FWL UNIT N EDDY CO., NM



17 1/2" hole

13 3/8" 48 & 54# @ 213' w/225 sx. Circ 70 sxs.

4. Perf & Sqz 65 sx cmt @ 295'-Surface. (T/Salt & 13 3/8" Shoe)

3. Spot 25 sx cmt @ 880-680'. WOC & Tag (B/Salt)

DV Tool @ 2243'

2. Spot 25 sx cmt @ 2293-2090'. WOC & Tag (DV Tool)

San Andres

2658'-3253' *according to OCD Files, pg.12, these perfs are fictitious

1. Set 5 1/2" CIBP @ 3921'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 3921-3720'.

Perf'd PDK @ 3971'-4246', A/7,000 gals 15% A/ 32K gals heated 20%, 12-27-90

IP P 60 BO, 47 MCF & 100 BW 01-01-91

7 7/8" hole

5 1/2" 17# csg @ 4461' w/2500 sx. Circ 50 sxs @ DVT.

TD @ 4520

PBTD - 4460'

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.