Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**OCD** Artesia

FORM APPROVED OMB NO. 1004-0137


Expires	: Jan		
ease Serial No			

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Seriai No. NMNM20965 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well     Gas Well □ Other			8. Well Name and N RDX FEDERAL		
Name of Operator Contact: ABIGAIL ANDERSON WPX ENERGY PERMIAN LLC E-Mail: abbym@bcmandassociates.com			9. API Well No. 30-015-41088	9. API Well No. 30-015-41088-00-S1	
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172		Phone No. (include area code): 432-580-7161		or Exploratory Area AW-WOLFCAMP	
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description)		11. County or Paris	sh, State	
Sec 17 T26S R30E NESE 208	30FSL 330FEL		EDDY COUN	TY, NM	
. 12. CHECK THE AI	PROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION	·	
Notice of Intent	☐ Acidize☐ Alter Casing	☐ Deepen ☐ Hydraulic Fracturing	☐ Production (Start/Resume) ☐ Reclamation	<ul><li>□ Water Shut-Off</li><li>□ Well Integrity</li></ul>	
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☑ Plug and Abandon ☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal		
determined that the site is ready for from 544 2 1. Set 5 1/2" CIBP @ 5460". Ci Tag (DV Tool) **  2. Spot 25 sx cmt @ 3490-328 3. Perf & Sqz 50 sx cmt @ 40 4. Perf & Sqz 50 sx cmt @ 15 5. Cut off well head, verify cmi	rc hole w/ MLF. Pressure test 90'. WOC & Tag. (9 5/8" Shoe 70-870'. WOC & Tag (13 3/8" 0'-Surface. to surface, weld on Above G	csg. Spot 25 sx cmt @ 64 ) (B/so H) Shoe) 13 0 2 (7) round Dry Hole Marker.  RE REPERMENT	SEE ATTACHED	FOR FAPPROVAL	
	Electronic Submission #4729	PERMIAN LLC, sent to the	Carlsbad 07/11/2019 (19PP2784SE)	IL CONSERVATION ARTESIA DISTRICT AUG 2 1 2019	
Signature (Electronic S	Submission)	Date 07/11/20	19	RECEIVED	
	THIS SPACE FOR F	EDERAL OR STATE (	OFFICE USE		
Approved By James	a. Pomos_	Title SPE	7	7.28-19 Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to conditions.	uitable title to those rights in the subject operations thereon.	ect lease Office CFC			
Title 18 U.S.O. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime statements or representations as to an	e for any person knowingly and y matter within its jurisdiction.	willfully to make to any department	t or agency of the United	

## WELLBORE DIAGRAM



4. Perf & Sqz 50 sx cmt @ 150'-Surface.

(13 3/8" Shoe) (13 3/8" @ 1019 MD |

WELL:	ROX FEDERAL 17-21			SPUD DATE:	3/11/2013	1
COUNTY:	EDDY	EU NUMBER:	62428657	TD:	7,440	MD (KB)
STATE: .	NM:	OPERATOR:	WPX Energy	TVD:	7,420	TVD (KB)
API:	30-015-41088	WI:	100%	PBTD:	7,390	MD (KB)
LOCATION:	17-26S-30E	NRI:	75%	KB ELEVATION:		(-3093' KB)
FIELD / AREA:	STATELINE NORTH	T		GL ELEVATION:	3,093.0	
FORMATION:	DELAWARE MTN GROU	JP.		SURFACE LAT/LONG:	32.040798	-103.895502

2. Spot 25 sx cmt @ 3490-3290'. WOC & Tag. (9 5/8" Shoe)

DV Tool @ 5463'

1. Set 5 1/2" CIBP @ 5480'.Circ hole w/ MLF. Pressure test csa. Spot 25 sx cmt @ 5480-5280'. WOC & Tag (DV Tool)

Top Perf @ 5492' MD

Bottom Perf @7084' MD

TD @ 7,440' (MD)
PBTD @ 7,390' (MD)

Date: 7/10/2019 Updated: BKN CURRENT

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.