Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137

	Expir	es:	Januar	<u>y</u>
5.	Lease Serial N	o.		
	NIMI COGAS	റ്പ	D	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter DISTRICT abandoned well. Use form 3160-3 (APD) for sull proposals DISTRICT	וכ
Do not use this form for proposals to drill or to re-enter an DISTRICT	
- ababdonod Woll - Lico form 3160-3 / AND for comprisionocate) 1/4·/	

	6.	If Indian,	Allottee	or	Tribe Name	
--	----	------------	----------	----	------------	--

		2019	•	
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. 8910085010			
Type of Well Oil Well	her	RECEIVED	8. Well Name and No. INDIAN HILLS UNIT 38	
Name of Operator OXY USA WTP LIMITED PTI	Contact: NRSHIP E-Mail: david_stev	DAVID STEWART vart@oxy.com	9. API Well No. 30-015-32770-00-S1	
3a. Address HOUSTON, TX 77210		3b. Phone No. (include area code) Ph: 432-685-5717	10. Field and Pool or Exploratory Area INDIAN BASIN-UPPER PENN ASSOC	
4. Location of Well (Footage, Sec., 2	T., R., M., or Survey Description))	11. County or Parish, State	
Sec 29 T21S R24E NWSE 20	333FSL 2020FEL		EDDY COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTIO	CE, REPORT, OR OTHER DATA	
TVPE OF SUBMISSION		TVPE OF ACTION	N	

☐ Notice of Intent	Acidize		☐ Production (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	Other
☐ Final Abandonment Notice	Change Plans	☑ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	□ Plug Back	☐ Water Disposal	
13. Describe Proposed or Completed Op			g date of any proposed work and appro	

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

6/24/19 - MIRU PU, NDWH, NU BOP

6/25/19 - POOH & scan & LD prod tbg. Start to RIH w/ bit & scraper

6/26/19 - Continue to RIH w/ bit & scraper to 7716', POOH.

RECLAMATION PROCEDURE ATTACHED

6/27/19 - RIH w/ CIBP & pkr, attempt to set CIBP @ 7640', notify BLM, rec appr to set further uphole, attempt to set @ 7590', still wouldn't set. Push CIBP down to 8075', PUH and set pkr different depths to test csg. Set @ 6613', test to 500#, lost 40# in 5min, SION.

7/1/19 - Attempt to rel pkr, work pkr loose & POOH w/ tbg, plr and top part of CIBP.

RECLAMATION DUE 1-12-20

14. I hereby certify that the	For	Submissi OXY US	A WTP LIMIT	ED PT	NRSHIP.	sent to t	he Cai	nation System rlsbad /2019 (19PP1767SE)		-	
Name (Printed/Typed)	DAVID STEWART				Title S	R. REG	ULAŢ	ORY ADVISOR			
Signature	(Electronic Submission)	ACC	EPTED	FOR	RECC Date 0) RD 7/16/20	19	MANAGEMENT ELD OFFICE	IREAU OF LAND	n 8	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE											
Approved By			DACK	0.40	Title JE			0,000	D D	ate	
certify that the applicant not	ny, are attached. Approval of ds legal or equitable title to the licant to conduct operations the	this notice ose rights	me subbalan	MaSim	ANAGEIVIE	NT		OR RECORD	FPTED F	ACE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #473615 that would not fit on the form

32. Additional remarks, continued

7/2/19 - RIH w/ bit, drill collars, tbg CIBP @ 6611', nu stripper hd, start to drill out.

7/3/19 - ND stripper hd, POOH w/ bit & drill collar. Rlh w/ bear claw/metal muncher, drill collar, RlH & tag up @ 6613', MU stripper hd, start drilling.

7/5/19 - Continue to drill out to 6616' & fell through, RIH to 8355', POOH.

7/8/19 - RIH & set pkr @ 6613', test csg to 500#, held OK. RIH & set pkr @ 7117', test csg to 500#, held OK. RIH & set pkr @ 7620', attempt to test, PUH to 7526', test to 500#, held OK.

7/9/19 - Notify BLM, rec appr to set CIBP @ 7526', POOH w/ tbg & pkr. RIH & set CIBP @ 7526', POOH. RIH w/ tbg & tag CIBP @ 7526', M&P 35sx CI H cmt, PUH. WOC.

7/10/19 - RIH & tag cmt @ 7341' notify BLM. Circ hole w/ 10# MLF. PUH to 6795', M&P 60sx CL C cmt, PUH, WOC. RIH & tag cmt @ 6474', BLM witnessed tag. PUH to 4907', M&P 45sx CL C cmt, PUH, WOC.

7/11/19 - RIH & tag_cmt @ 4684', notify BLM. PUH to 2476', M&P 50sx CL C cmt w/ 2% CaCl2, PUH, WOC. RIH & tag_cmt @ 2208', notify BLM. PUH to 1270', M&P 35sx CL C cmt w/ 2% CaCl2, PUH, WOC.



7/12/19 RIH & tag cmt @ 1067', notify BLM. POOH w/ tbg, ND BOP, RIH to 800' M&P 160sx CL C cmt w/ 2% CaCl2, circ cmt to surface, BLM witnessed. Top off well w/ cmt, NU flange, RDPU.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612