N. 30 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	
Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
Office District I Freegy, Minerals and Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88246/ 200	WELL API NO.
District II 811 South First, Artesia, NM 2018 CEIL CONSERVATION DIVISION	30-005-63297
	5. Indicate Type of Lease
District IV Santa Fe, NM 8741065/4 Santa Fe, NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 CSS 1777 10°	VA-2066
SUNDRY SEFECTS AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Wager AWC State Com
PROPOSALS.)	Wager AWG State Com
1. Type of Well:	
Oil Well Gas Well X Other 2. Name of Operator	7. Well No.
•	7. Well No.
Yates Petroleum Corporation 3. Address of Operator	8. Pool name or Wildcat
105 S. 4th Street Artesia, NM 88210	Undesignated Foor Ranch Pre-
105 5. 4" SHEEL ALESIG, NW 60210	Permian
4. Well Location	I CITIIQII
4. Well Education	
Unit Letter <u>J: 1500</u> feet from the <u>South</u> line and <u>1500</u> feet from the <u>East</u> line	
Section 34 Township 9S Range 26E NMPM Chaves County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.	c.)
3808' GR	
11. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	X ALTERING
PERFORM REMEDIAL WORK	— CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	LLING OPNS. PLUG AND ABANDONMENT
MULTIPLE CASING TEST AN	
PULL OR ALTER CASING COMPLETION CEMENT JOB	
OTHER: OTHER:	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
6/23/03 – Acidize current Cisco perfs with 500g 20% IC acid.	
6/30/03 – Acidize with 10,000g 15% gelled acid and 300# rock salt.	
7/1/03 – Set AS-1 10K packer with 2.25" on/off tool at 5680'.	
	dge and belief.
7/1/03 – Set AS-1 10K packer with 2.25" on/off tool at 5680'. I hereby certify that the information above is true and complete to the best of my knowledge.	
7/1/03 – Set AS-1 10K packer with 2.25" on/off tool at 5680'.	
I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE	upervisor DATE July 9, 2003
I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Type or print name Ting L. Huerta	
I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Type or print name Tiria L. Huerta (This space for State use)	upervisor DATE July 9, 2003
I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Type or print name Ting L. Huerta	upervisor DATE July 9, 2003