

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.  
NMNM0251099A

6. If Indian, Allottee or Tribe Name

**SUBMIT IN TRIPLICATE - Other instructions on page 2**7. If Unit or CA/Agreement, Name and/or No.  
NMNM85354

## 1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other8. Well Name and No.  
SMITH FEDERAL GAS COM 42. Name of Operator  
EOG Y RESOURCES INCContact: JEREMY HAASS  
E-Mail: jeremy\_haass@eogresources.com9. API Well No.  
30-015-32470-00-S13a. Address  
104 S 4TH STREET  
ARTESIA, NM 882103b. Phone No. (include area code)  
Ph: 575-748-431110. Field and Pool or Exploratory Area  
INDIAN BASIN-STRAWN  
INDIAN BASIN-UPPER PENN ASSOC

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 12 T22S R23E NWSW 1980FSL 1250FWL

## 11. County or Parish, State

EDDY COUNTY, NM

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

1. JSA
2. MIRU WOR
3. NU Rod BOP
4. TOOH w/ Rod String and pump.
5. ND Tree/NU BOPs.
6. POOH with tubing
7. Run Casing scraper, Gauge ring with Junk Basket to top perf

Plug as follows

Set CIBP at 7430 ft with 35 ft of CLS H on top. *Dump Ball on spot 25 SX. Class C.**Gc 10/10/19*  
*Accepted for record - NMOC***SEE ATTACHED FOR  
CONDITIONS OF APPROVAL****NM OIL CONSERVATION  
ARTESIA DISTRICT**

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #481712 verified by the BLM Well Information System  
For EOG Y RESOURCES INC, sent to the Carlsbad  
Committed to AFMSS for processing by PRISCILLA PEREZ on 09/04/2019 (19PP3191SE)**

OCT 02 2019

Name (Printed/Typed) JEREMY HAASS

Title REGULATORY SPECIALIST

RECEIVED

Signature (Electronic Submission)

Date 09/04/2019

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By <i>James R. Carr</i>	Title <i>SECRET</i>	Date <i>9.21-19</i>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <i>PCO</i>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\****7*

**Additional data for EC transaction #481712 that would not fit on the form**

**32. Additional remarks, continued**

Spot a 33 SX (168 ft) CLS H cement plug 6641 ft - 6809 ft. WOC & Tag Plug. This will plug the Wolfcamp.

Spot a 37 SX (186 ft) CLS H cement plug 6325 ft - 6511 ft. WOC & Tag Plug. This will plug the DV Tool and 3rd Bone Spring.

Spot a 25 SX (142 ft) CLS C cement plug 2915 ft - 3057 ft. WOC & Tag Plug. This will plug the 2nd Bone Springs.

Spot a 25 SX (142 ft) CLS C cement plug 2803 ft - 2945 ft. WOC & Tag Plug. This will plug the Bone Springs.

Spot a 25 SX (142 ft) CLS C cement plug 2077 ft - 2219 ft. WOC & Tag Plug. This will plug the Glorieta.

Perforate at 1551 ft. Attempt to establish Circulation. Spot a 25 SX (142 ft) CLS C cement plug 1409 ft - 1551 ft. WOC & Tag Plug. This will plug the 9.625 inch casing shoe.

Spot a 25 SX (142 ft) CLS C cement plug 556 ft - 698 ft. WOC & Tag Plug. This will plug the San Aders.

Spot a 10 SX (57 ft) CLS C cement plug 0 ft - 57 ft. WOC & Tag Plug. This will plug the Top.

8. RDMO Workover Rig

9. PXA Marker


9.1. Cut off wellhead and weld on dry hole marker. Clean location as per regulation.

*Handwritten notes:*  
SPOT 25 OK  
SPOT 10 OK  
J. Hunt

# Smith Federal Gas Com #4

9/3/2019

COMMENTS



## CASING DETAIL

#	HOLE SIZE	SIZE	WGHT	GRADE	Top	Bottom	Sx Cmt	Circ/TOC	TOC Method
A	14 3/4	9 5/8	36	J-55	0	1,501	2225	0	1" circ
B	8 3/4	7	11.75	J-55	0	8,000	1175	0	circ

## FORMATION TOPS

FORMATION	TOP
San Andres	648
Glorieta	2169
Bone Springs	2895
2nd Bone Springs	3007
3rd Bone Springs	6439
Wolfcamp	6759
Canyon	7468

## TUBING DETAIL

#	Joints	Description	Length	OD	ID	Grade	Wt (lb/ft)	Top (ftKB)	Blm (ftKB)
1		2 7/8" TBG	7235.00	2.78					

DV tool 6461'

Perforations 7480 - 7712'

Perforations 7730'

Plugged

PBTD: MD

TD: 8,000 MD

Prepared by: MJM

# Smith Federal Gas Com #4

COMMENTS

Plug

9

8

7

6

5

4

3

2

1

A

B

PBTD: MD  
TD: 8,000 MD

DV tool 6461'

Perforations 7480 - 7712'

Perforations 7730'  
Plugged

## Proposed

### CASING DETAIL

#	HOLE SIZE	SIZE	WGHT	GRADE	Top	Bottom	Sx Cmt	Circ/TOC	TOC Method
A	14 3/4	9 5/8	36	J-55	0	1,501	2225	0	1" circ
B	8 3/4	7			0	8,000	1175	0	circ

### FORMATION TOPS

	FORMATION	TOP							
	San Andres	648							
	Glorieta	2169							
	Bone Springs	2885							
	2nd Bone Springs	3007							
	3rd Bone Springs	6439							
	Wolfcamp	6759							
	Canyon	7468							

### Plugs

#	
1	Set CIBP at 7430 ft with 35 ft of CLS H on top.
2	Spot a 33 SX (168 ft) CLS H cement plug 6641 ft - 6809 ft. WOC & Tag Plug. This will plug the Wolfcamp.
3	Spot a 37 SX (186 ft) CLS H cement plug 6325 ft - 6511 ft. WOC & Tag Plug. This will plug the DV Tool and 3rd Bone Spring.
4	Spot a 25 SX (142 ft) CLS C cement plug 2915 ft - 3057 ft. WOC & Tag Plug. This will plug the 2nd Bone Springs.
5	Spot a 25 SX (142 ft) CLS C cement plug 2803 ft - 2945 ft. WOC & Tag Plug. This will plug the Bone Springs.
6	Spot a 25 SX (142 ft) CLS C cement plug 2077 ft - 2219 ft. WOC & Tag Plug. This will plug the Glorieta.
7	Perforate at 1551 ft. Attempt to establish Circulation. Spot a 25 SX (142 ft) CLS C cement plug 1409 ft - 1551 ft. WOC & Tag Plug. This will plug the 9.625 inch casing shoe.
8	Spot a 25 SX (142 ft) CLS C cement plug 556 ft - 698 ft. WOC & Tag Plug. This will plug the San Aders.
9	Spot a 10 SX (57 ft) CLS C cement plug 0 ft - 57 ft. WOC & Tag Plug. This will plug the Top.

Prepared by: MJM

BUREAU OF LAND MANAGEMENT  
Carlsbad Field Office  
620 East Greene Street  
Carlsbad, New Mexico 88220  
575-234-5972

Permanent Abandonment of Federal Wells  
Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. Blowout Preventers: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. Mud Requirement: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:

From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted