Form 3160-5 (June 2015)

1. Type of Well

☑ Oil Well ☐ Gas Well ☐ Other 2. Name of Operator
CIMAREX ENERGY COMPANY

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

Contact: E-Mail: acrawford@cimarex.com FORM APPROVED

	OMB NO. 1004-0137 Expires: January 31, 2018							
	5. Lease Serial No. NMNM132062							
	6. If Indian, Allottee or Tribe Name							
	7. If Unit or CA/Agreement, Name and/or No.							
	8. Well Name and No. BLACK RIVER 25 FED COM 2H							
	9. API Well No. 30-015-43377-00-X1							
	Field and Pool or Exploratory Area WILDCAT							
	11. County or Parish, State							
	EDDY COUNTY, NM							
ΓICE,	REPORT, OR OTH	ER DATA						
ON								
roduct	ion (Start/Resume)	■ Water Shut-Off						
eclamation		■ Well Integrity						
ecomplete emporarily Abandon		☑ Other Change to Original A PD						
/ater Disposal								
of any proposed work and approximate duration thereof.								

3b. Phone No. (include area code) Address 600 N MARIENFELD STE 600 Ph: 432-620-1909 MIDLAND, TX 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 25 T24S R26E SESW 192FSL 2167FWL 12. CHECK-THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOT TYPE OF SUBMISSION TYPE OF ACTI □ P: ☐ Acidize Deepen Notice of Intent ☐ Alter Casing ☐ Hydraulic Fracturing \square R ☐ Subsequent Report □ Casing Repair ■ New Construction □ R ☐ Final Abandonment Notice □ Change Plans □ Plug and Abandon Convert to Injection ☐ Plug Back 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

AMITHY E CRAWFORD

Cimarex Respectfully requests permission to use a spudder rig to spud, set and cement surface casing on the Black River 25 Federal Com 2H. Procedure as follows:

Rig up spudder rig (Notify BLM 24 hours in advance)

Drill 17-1/2" hole to 400",+/- 1 joint

determined that the site is ready for final inspection.

Run 13-3/8" 48# J-55 ST&C casing and cement per below:

LEAD: 78 sks, 14.8#, 1.34 yield, Class C + LCM TAIL: 195 sks, 14.8#, 1.34 yield, Class C + LCM

Carlshad Field Conce OCD Artesia

SEE ATTACHED FOR CONDITIONS OF APPROVAL

	ne foregoing is true and correct. Electronic Submission #473477 verifie For CIMAREX ENERGY COM Committed to AFMSS for processing by PRI AMITHY E CRAWFORD	d by the IPANY, SCILLA Title	BLM Well Information sent to the Carlsbad PEREZ on 07/16/2019 (REGULATORY ANA	(19PP2808SE)	OIL CONSERVA ARTESIA DISTRICT AUG 2 1 2019	
Signature	(Electronic Submission)	Date	07/16/2019	. '`	RECEIVED	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE US	SE		
Approved By JEROMY PORTER Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			PETROLEUM ENGINE	ER	Date 07/1	3/2019
	1 and Title 43 U.S.C. Section 1212, make it a crime for any poor fraudulent statements or representations as to any matter w			ke to any departn	nent or agency of the Unite	1

BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Enploring

Additional data for EC transaction #473477 that would not fit on the form

32. Additional remarks, continued

On plug bump, perform casing integrity test to 1,500 psi for 30 min.

WOC for 8 hours prior to cut off.

Cut off casing and weld on 13-3/8" SOW and test weld to 500 psi and not to exceed 70% of Collapse.

Install blind pressure gauge and test to 1500 psi for 10 min.

Install pressure gauge on blind flange.

RDMO spudder rig

Notify BLM of start of move in with 2nd rig and give 24 hour notice of spud with 2nd rig.

Revisions to Operator-Submitted EC Data for Sundry Notice #473477

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

APDCH

Lease:

NMNM132062

APDCH NOI

NMNM132062

Agreement:

Operator:

CIMAREX ENERGY CO. 600 N. MARIENFELD SUITE 600 MIDLAND, TX 79701 Ph: 432-620-1909

CIMAREX ENERGY COMPANY 600 N MARIENFELD STE 600 MIDLAND, TX 79701 Ph: 432.620.1936 Fx: 918.749.8059

Admin Contact:

AMITHY E CRAWFORD REGULATORY ANALYST

E-Mail: acrawford@cimarex.com

Ph: 432-620-1909

AMITHY E CRAWFORD REGULATORY ANALYST

Tech Contact:

AMITHY E CRAWFORD

REGULATORY ANALYST

E-Mail: acrawford@cimarex.com

Ph: 432-620-1909

Ph: 432-620-1909

AMITHY E CRAWFORD REGULATORY ANALYST E-Mail: acrawford@cimarex.com

E-Mail: acrawford@cimarex.com

Ph: 432-620-1909

Location:

State: County: NM **EDDY**

PURPLE SAGE WOLFCAMP

NM EDDY

WILDCAT

Well/Facility:

Field/Pool:

CIMAREX ENERGY CO. 2H Sec 25 T24S R26E 192FSL 2167FWL

BLACK RIVER 25 FED COM 2H Sec 25 T24S R26E SESW 192FSL 2167FWL

Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.

- a. In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).
- b. When the operator proposes to set surface casing with Spudder Rig
- Notify the BLM when moving in and removing the Spudder Rig.
- Notify the BLM when moving in the 2nd Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
- BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as 2nd Rig is rigged up on well.