

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-015-10474
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-4109
7. Lease Name or Unit Agreement Name Aoudad State
8. Well No. 7
9. Pool name or Wildcat Maljamar GB SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS).	
1. Type Of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	
4. Well Location Unit Letter <u>A</u> : <u>330</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>17S</u> Range <u>31E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3859' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set CIBP @ 3900' (+)(-) w/35' cement cap. *Perf csq @ 2093' - place 100' of cmt inside & outside of csq*
3. Set 35 sx plug from 2043-1943', base of salt. *1993'-2093' - TAG*
4. Set 35 sx plug from 1090-990', 50' above and below 8 5/8 casing shoe. *Perf csq @ 1090' place 200' of cmt inside & outside of csq. 890'-1090' - TAG*
5. Set 10 sx plug from 60-0'.
6. Install dry hole marker. *Perf Both csq. strings @ 60' - place 60' of cmt inside & outside of both csq. strings 0'-60' - WOC 24 HRS TAG*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Salt gel mud consisting of 10# Brine W/25# of gel per bbl DATE 6/2/2003
Product completed between each plug

TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO. 748-1288

(This space for State Use)

APPROVED BY [Signature] TITLE Field Lp II DATE 6-9-03

CONDITIONS OF APPROVAL, IF ANY:

OPERATOR: Mack Energy		API#	30-015-10474
WELL: Aoudad State # 7		LOCATION:	A-36-17-31
SURFACE CSG-HOLE SIZE "	CSG. SIZE 8 5/8"	SET @ 1040'	SX. CMT. TOC. 391'
LONG STRING- HOLE SIZE "	CSG. SIZE 4 1/2"	SET @ 4029'	SX. CMT. TOC. 3866'
OTHER-			

