

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
 CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

RECEIVED
 MAY 2003
 OCD - ARTESIA

Form C-103
 Revised March 25, 1999

WELL API NO.
30-015-32144

5. Indicate Type of Lease
 STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
V-5021

7. Lease Name or Unit Agreement Name:
Saragossa "19" State Com

8. Well No.
1

9. Pool name or Wildcat
Undesg. Carlsbad Morrow, S.

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Dominion Oklahoma Texas E&P, Inc.

3. Address of Operator
14000 Quail Springs Parkway, Suite 600, Oklahoma City, OK 73134

4. Well Location
 Unit Letter **C** : **660** feet from the **North** line and **1600** feet from the **West** line
 Section **19** Township **23-S** Range **26-E** NMPM **Eddy** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3531.4 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

04/23/03 Notified OCD, Mike Bratcher. MIRU Triple N rig #23 and plugging equipment. NU BOP. Set 7" CIBP @ 3,375'. Circulated hole w/ mud. Pumped 25 sx C cmt 3,375 - 3,275'. POOH. SDFN.

04/24/03 Notified OCD, Mike Bratcher. Cut 7" csg, POOH w/ 7" csg, tally 1,745.60'. RIH w/ tbg and tested csg to 200 psi, held. Pumped 120 sx C cmt @ 1,775'. WOC and tagged cmt @ 1,492'. Pumped 40 sx C cmt @ 1,200'. POOH, SDFN.

04/25/03 Notified OCD Mike Bratcher. Tagged cmt @ 1,075'. Pumped 40 sx C cmt @ 735'. WOC and tagged cmt @ 605'. Pumped 40 sx C cmt @ 350'. POOH and WOC. Tagged cmt @ 221'. POOH. ND BOP. Pumped 20 sx C cmt 50' to surface. RDMO.

05/07/03 Cut off wellhead and anchors, installed dry hole marker. Covered pit and cellar.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Engineer DATE 05/05/03

Type or print name James F. Newman, P.E. Telephone No. 432-687-1994

(This space for State use)

APPROVED BY  TITLE Field Rep DATE APPROVED JUL 3 2003

Conditions of approval, if any: