Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CHMDDV	NOTICES	AND	REPORTS	ON	WELL	c
SUNDRY	NUTICES	AND	REPURIS	ON	WELL	.3

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

5. Lease Serial No.

N	MI	∠C0	287	31B
---	----	-----	-----	-----

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.				6. If Indian, Al	llottee or Tribe Name		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No. NMNM111789X				
1. Type of Well Oil Well Gas Well Other 2. Name of Operator Marbob Energy Corporation 3a. Address 3b. Phone No. (include area code)			8. Well Name and No.				
2. Name of Operator Marbob Ener	rgy Corporation	YU	2006	9. API Well 1	eral Unit #19 No.		
3a. Address PO Box 227, Artesia, NM 882	11-0227	3b. Phone No. (include area code) 505-748-3303		30-015-20028 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec.,		<u></u>		Grbg Jackson SR Q Grbg SA			
660 FSL 660 FEL, Sec. 10-T17	'S-R29E, Unit P				11. County or Parish, State		
				Eddy Co., NM			
12. CHECK AF	PPROPRIATE BOX(ES) TO	INDICATE NAT	URE OF NOTICE,	REPORT, OR O	THER DATA		
TYPE OF SUBMISSION		Т	YPE OF ACTION				
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (S	tart/Resume)	Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon		L. Abandon	Other		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa				
following completion of the investing has been completed. Fir determined that the site is ready Plug and abandon as follow Notify BLM 24 hours before 1. POOH w/ pkr & tbg. 2. Shoot 4 sqz holes @ 880. 3. Set CIBP on tbg @ 240 per 100 bbs of salt gel (app 4. Pull tbg to 730'. Pump WOC a couple of hours & 5. Shoot 4 sqz holes @ 542 to fill the well from 542' to 6. Cut wellhead & csg off above ground level. 7. Cut off anchors & rectains the site of the site of the same state of t	ws: ore starting plugging operation starting starting plugging operation ore starting plugging operation starting starting plugging operation ore starting plugging operation starting starting plugging operation ore starting plugging operation ore starting plugging operation starting plugging operation ore starting plugging plugging ore starting plugging ore starting plugging ore starting plugging ore starting pluggi	results in a multiple co filed only after all requ t. cmt on top of CIBP to the end of the tbg 2'). Pump 170 sx Cl	mpletion or recompletion irements, including reclar SEE ACONDITIO Pull up to 2100' & c. (placing cmt inside & lass "C" + 2% CaCl2	in a new interval, a mation, have been control of the matter of the matt	Form 3160-4 shall be filed once ompleted, and the operator has DFOR PPROVAL of 9 ppg brine mixed w/ 25 sx TOOH w/ tbg, load csg. & up 8 5/8" x 5 1/2" annulus		
14. I hereby certify that the fore Name (Printed/Typed)	going is true and correct				MMOCA () -		
Diana J. Briggs	\	Title	Production Analyst		/		
Signature	Ducas	Date		06/13/2006			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by ORIG. S	GO. ALEXIS C. SWO	BODA	FTROLEUM I	ENGINEEA Date	JUN 1 9 2006		
Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to	or equitable title to those rights in		Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.