

Submit 3 Copies To Appropriate District  
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30-005-10003

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
V 131

7. Lease Name or Unit Agreement Name:

Sinclair State

8. Well No.  
1

9. Pool name or Wildcat  
Acme San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Slayton Resources, Inc.

3. Address of Operator  
P. O. Box 2035, Roswell, NM 88202-2035

4. Well Location

Unit Letter E : 1650 feet from the North line and 990 feet from the West line

Section 5 Township 8S Range 27E NMPM County Chaves

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE  
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND  
ABANDONMENT ☒

CASING TEST AND ☐  
CEMENT JOB

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

This well was plugged and abandoned as of May 11, 2006.

The Cement Report is attached that shows the details.

RECEIVED

MAY 19 2006

ODD-ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE April Denise Allison TITLE Agent DATE 05-18-06

Type or print name April Denise Allison Gerry Guay Telephone No. 505-623-7184

(This space for State use)

APPROVED BY [Signature] TITLE Deputy Field Inspector DATE JUL 14 2006

Conditions of approval, if any: District II - Artesia

MAYO MARRS CASING PULLING INC.  
BOX 863  
KERMIT, TEXAS 79745

SLAYTON RESOURCES, INC.

Lease: SINCLAIR STATE # 1

Project: P & A - CEMENTING REPORT

---

05-10-06 - SPOT 25 SXS @ 1865'-1660' & TAG

05-10-06 - PERFORATE @ 290' - SQUEEZE 25 SXS @ 290'-275' & TAG


05-10-06 - PERFORATE @ 274' - TEST CASING TO 600#

05-10-06 - SPOT 11 SXS @ 275'-156'

05-11-06 - PERFORATE @ 154' - SQUEEZE 40 SXS @ 154' TO SURFACE LEAVING  
CASING FULL

INSTALL DRY HOLE MARKER

CIRCULATE 10# MUD

 05-18-06

April Denise Allison



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**  
Governor

**Joanna Prukop**  
Cabinet Secretary  
Acting Director  
Oil Conservation Division

RECEIVED

JUN 21 2006

NEW MEXICO

23 May 2006

Slayton Resources, Inc.  
P. O. Box 2035  
Roswell, New Mexico 88202-2035

Form C-103 Report of Plugging for you're Sinclair State # 1 E-5-8-27 API 30-005-10003  
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been closed as per Rule 50.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

*A. D. Allison*

Name A.D. Allison

Vice President

Title

*Vair Barton*

Vair Barton  
Field Rep. II