	State of New			n C-103
Office District I	Energy, Minerals and N	latural Resources		27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO. 30-015-34479	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		1	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NI	M 87505	STATE FEE 🗷	
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR, USE "APPLICA"		EN OR PLUG BACK TO A	7. Lease Name or Unit Agreement	Name:
PROPOSALS.)		,	San Saba A 12 Fee	
1. Type of Well:		DEOEN	8. Well Number	
Oil Well Gas Well	Other	RECEIVED	2н	
2. Name of Operator		JUL - 3 2006	9. OGRID Number	
EOG Resources Inc.			7377	
3. Address of Operator		OCH-WITCOM	10. Pool name or Wildcat	
P.O. Box 2267 Midland, Texa 4. Well Location	s 79702		Cottonwood Creek; WC, West	
Unit Letter <u>H</u> : 1	feet from the	North line and	660 feet from the East	line
Section 12	Township 168	Range 24E	NMPM County	Eddy
	11. Elevation (Show whet	her DR, RKB, RT, GR, et		Park to the
Pit or Below-grade Tank Application	or Closure	3533' GR		
Pit type Depth to Groundwater _		fresh water well Die	stance from nearest surface water	
Pit Liner Thickness: mil		umebbls; Construction		
Fit Liner Thickness: hin	below-Grade Tank: Vol	umebois; Construction	on Material	
12. Check A ₁				
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	REMEDIAL WORK COMMENCE DRILL CASING TEST AND	ABANDONME	
NOTICE OF INTERPORT REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	NTION TO: PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB	ING OPNS. PLUG AND ABANDONME	
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER:	ALTERING CA	ENT
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 6/15/06 Ran 21 jts 7", 23: Cemented w/ 200 ss 12.4 ppg, 2.04 yid Ran temperature ss wcc 18 hrs.	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state all SEE RULE 1103. For Multiple 1103. For Multiple 1103.	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Il pertinent details, and give litiple Completions: Attach Dio'. Dippg, 1.53 yield; 100 14.8 ppg, 1.34 yield; act 4 squeeze holes @	ALTERING CAND ABANDONME To pertinent dates, including estimated in wellbore diagram of proposed complete. D sax Halliburton Light Prem Plus.	date letion
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 6/15/06 Ran 21 jts 7", 23: Cemented w/ 200 ss 12.4 ppg, 2.04 yid Ran temperature ss wcc 18 hrs.	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Multiple 1103.	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Il pertinent details, and giviliple Completions: Attach 10'. ppg, 1.53 yield; 100 14.8 ppg, 1.34 yield oct 4 squeeze holes @ Test good. the best of my knowledge	ALTERING CAND ABANDONME To pertinent dates, including estimated in wellbore diagram of proposed complete. 185'. Circulated 15 sx to so see and belief. I further certify that any pit.	date letion
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 6/15/06 Ran 21 jts 7", 23: Cemented w/ 200 ss 12.4 ppg, 2.04 yie Ran temperature ss WCC 18 hrs. 6/16/06 Tested casing to :	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Multiple, 14.0 eld; 200 sx Prem Plus, arvey, TOC @ 241'. Sho	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Il pertinent details, and give liple Completions: Attach 10'. 10'. 11.53 yield; 100 14.8 ppg, 1.34 yield; 15 tot 4 squeeze holes 6 Test good. Test good.	ALTERING CAND ABANDONME To pertinent dates, including estimated in wellbore diagram of proposed complete wellbore diagram of proposed complete. 185'. Circulated 15 sx to such a such	date letion
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 6/15/06 Ran 21 jts 7", 23: Cemented w/ 200 starting any proposed work). 12.4 ppg, 2.04 yie Ran temperature starting any proposed work. 6/16/06 Tested casing to 2.01 its and temperature starting	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Multiple, 14.0 eld; 200 sx Prem Plus, arvey, TOC @ 241'. Sho	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Il pertinent details, and give liple Completions: Attach 10'. 10'. 11.53 yield; 100 14.8 ppg, 1.34 yield; 15 tot 4 squeeze holes 6 Test good. Test good.	ALTERING CAND ABANDONME To pertinent dates, including estimated in wellbore diagram of proposed complete wellbore diagram of proposed complete. 185'. Circulated 15 sx to such a such	date letion ls, or below-ved plan
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 6/15/06 Ran 21 jts 7", 23: Cemented w/ 200 ss 12.4 ppg, 2.04 yid Ran temperature ss woc 18 hrs. 6/16/06 Tested casing to : I hereby certify that the information ab grade tank has been/will/se constructed or cle SIGNATURE Type or print name Stan Wagner	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Multiple, 14.0 eld; 200 sx Prem Plus, arvey, TOC @ 241'. Sho	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Il pertinent details, and give litiple Completions: Attach 10'. ppg, 1.53 yield; 100 14.8 ppg, 1.34 yield oot 4 squeeze holes @ Test good. the best of my knowledge letines, a general permit TITLE	ALTERING CAND ABANDONME The pertinent dates, including estimated in wellbore diagram of proposed complete wellbore diagram of proposed complete. Desk Halliburton Light Prem Plusion. 185'. Circulated 15 sx to so the proposed complete. The proposed complete in the prem Plusion and the premium of the pre	date letion 15, 17face. 07 below-ved plan 28/06 86 3689
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 6/15/06 Ran 21 jts 7", 23: Cemented w/ 200 starting any proposed work). 12.4 ppg, 2.04 yie Ran temperature start word 18 hrs. 6/16/06 Tested casing to a start was been/will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will the constructed or clearly grade tank has been will be constructed or clearly grade t	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Operations. (Clearly state all SEE RULE 1103. For Multiple, 14.0 eld; 200 sx Prem Plus, arvey, TOC @ 241'. Sho	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Il pertinent details, and give litiple Completions: Attach 10'. ppg, 1.53 yield; 100 14.8 ppg, 1.34 yield oot 4 squeeze holes @ Test good. the best of my knowledge letines, a general permit TITLE	ALTERING CAND ABANDONME To pertinent dates, including estimated in wellbore diagram of proposed complete wellbore diagram of proposed complete. 185'. Circulated 15 sx to so see and belief. I further certify that any pit or an (attached) alternative OCD-approxy Analyst DATE 6/2	date letion 15, 17face. 07 below-ved plan 28/06 86 3689

Conditions of Approval, if any: