

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUL 21 2006

OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 TH STREET		Telephone No. 505.748.1471
Facility Name MIMOSA AHS FEDERAL 3-Y	API Number 30 015 29123	Facility Type BATTERY
Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No.

LOCATION OF RELEASE

Unit Letter P	Section 4	Township 20S	Range 24E	Feet from the 635	North/South Line SOUTH	Feet from the 330	East/West Line EAST	County EDDY
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.59732 Longitude 104.58540

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 1000 B/W	Volume Recovered 515 B/W
Source of Release POWER FAILURE	Date and Hour of Occurrence 11/7/04	Date and Hour of Discovery 11/7/04 1400 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER, ARTESIA OCD BECKY HUNT, BLM	
By Whom? DAN DOLAN	Date and Hour 11/8/04 0800	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 10 BBL WATER	
If a Watercourse was Impacted, Describe Fully.* WATER RAN DOWN ROAD AND CONTINUED DOWN HILL TO A DRAW.		
Describe Cause of Problem and Remedial Action Taken.* POWER FAILURE CAUSED THE TANKS TO OVERFLOW, AND CAUSED THE BERM TO BREAK.		
Describe Area Affected and Cleanup Action Taken.* TEST OF THE WATER SHOWED IT TO BE UNDER THE LIMIT FOR THE OCD, THE WATER CARRIED A SMALL AMOUNT OF IRON SULFIDE INTO THE DRAW, AND WAS MICRO-BLAZED TO ELIMINATE AND POSSIBLE THP, THE RANKING IS AS FOLLOWS, DEPTH TO GROUND WATER-O, WELLHEAD PROTECTION AREA-O, DISTANCE TO SURFACE WATER BODY-10.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Sherry Bonham	Approved by District Supervisor: TIM GUM by MB 	
Title: Environmental Regulatory Agent	Approval Date: 8/17/06	Expiration Date:
E-mail Address: sherryb@ypcnm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: July 21, 2006	Phone: 505.748.1471	

* Attach Additional Sheets If Necessary