Submit 3 Copies 10 Appropriate District Office	State of New Me		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natur	ral Resources WELL A	May 27, 2004 API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-015-34354
District III	1220 South St. Fran	icis Dr.	ate Type of Lease TATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	Santa Fe, NM-87	50592022 6. State	Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	1220 South St. Fran Santa Fe, NM 87	122	
(DO NOT USE THIS FORM FOR PROP	TICES AND REPORTS OXCWELLS POSALS TO DRILL OR TO DEFEND OR PLI	7. Lease	Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APP PROPOSALS.)	LICATION FOR PERMIT" (FORM C-199) PO	PRI PRI S Well	PARATION H FEE Number
1. Type of Well: Oil Well 2. Name of Operator	Gas Well X Other	"//FO. 57/1	1D Number
MARBOB ENERGY CORPOR	ATION		14049
3. Address of Operator	34,	10. Poo	l name or Wildcat
PO BOX 227, ARTESIA	NM 88211-0227	FOUR	MILE DRAW; MORROW
4. Well Location	1000 for from the COU	mm 1: 000	FACE I
Unit Letter I Section 1	: 1980 feet from the SOU Township 19S Ra		feet from the <u>EAST</u> line
Section 1	11. Elevation (Show whether DR,		County EDDY
The second secon	3272' GL		
Pit or Below-grade Tank Application			
	lwaterDistance from nearest fresh w		
	nil Below-Grade Tank: Volume	bbls; Construction !	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON [CHANGE PLANS	COMMENCE DRILLING OF	PNS. PANDA 🖫
PULL OR ALTER CASING [MULTIPLE COMPL	CASING/CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or cor of starting any proposed or recompletion.	npleted operations. (Clearly state all pwork). SEE RULE 1103. For Multiple	pertinent details, and give pertile Completions: Attach wellb	tinent dates, including estimated date ore diagram of proposed completion
PLUGGED & ABANDON	NED AS FOLLOWS:		
5 1/2" (R + 35' CMT @ 1050'. SHO CSG & CIRC UP 9 5/8" CSG F LL DRY HOLE MARKER.	T 4 SQZ HOLES @ 240 FROM 240' TO SURFACE	. PUMP CMT DOWN . CUT OFF WELLHEAD
•			
I hereby certify that the informatio	n above is true and complete to the be or closed according to NMOCD guidelines	st of my knowledge and belie	f. I further certify that any pit or below-
SIGNATURE	1)1. 400/	PRODUCTION ANALYST	DATE8/17/06_
••	J. BRIGGS E-mail add	dressPRODUCTION@MARBOE	3.COMTelephone No. (505) 748-3303
For State Use Only	R RECORDS ONLY		AUG 2 2 2006
APPROVED BY:	TITLE		DATE
Conditions of Approval (if any):			