

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop Cabinet Secretary Lori Wrotenbery

Director

Oil Conservation Division

20-Aug-03

DENNIS LANGLITZ 1425 SO COUNTRY CLUB CIRC CARLSBAD NM 88220-0000

NOTICE OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

erene des char Cratagranique Boudeus et Drawking Weiss

Land Wincome Zilonic.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

SALADAR UNIT 004				30-015-02446-00-00
•		Active Injection - (All Types)		K-33-20S-28E
Test Date:	8/19/2003 7:43:14 AM	Permitted Injection PSI:	Actual PSI:	and the second
Test Reason:	Annual IMIT	Test Result:	Repair Due:	9/22/2003
Test Type:	Bradenhead Test	FAIL TYPE: Other External Failure	FAIL CAUSE:	1000
Comments on	MIT: No company representat	ive on location. Unable to test (Second attempt),		San San
SALADAR UNIT 006				30-015-02448-00-00
		Active Injection - (All Types)		K-33-20S-28E
Test Date:	8/19/2003 7:42:20 AM	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result: F	Repair Due:	9/22/2003
Test Type:	Bradenhead Test	FAIL TYPE: Other External Failure	FAIL CAUSE:	
Comments on	MIT: No company representat	ive on location. Unable to test (Second attempt).		
SALADAR UNIT 008				30-015-02449-00-00
		Active Injection - (All Types)		N-33-20S-28E
Test Date:	8/19/2003 7:39:21 AM	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result: F	Repair Due:	9/22/2003
Test Type:	Bradenhead Test	FAIL TYPE: Other External Failure	FAIL CAUSE:	
Comments on !	MIT: No company representat	ive on location. Unable to test (Second attempt).		

SALADAR UNIT 002

30-015-02450-00-00

Active Injection - (All Types)

L-33-20S-28E

Test Date:

8/19/2003 7:40:18 AM

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

Test Type:

Comments on MIT:

Bradenhead Test

FAIL TYPE: Other External Failure

FAIL CAUSE:

SALADAR UNIT 007

No company representative on location. Unable to test (Second attempt).

30-015-10468-00-00

Active Injection - (All Types)

N-33-20S-28E

Test Date:

8/19/2003 7:38:18 AM

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

9/22/2003

9/22/2003

Test Type:

Bradenhead Test

FAIL TYPE: Other External Failure

FAIL CAUSE:

No company representative on location. Unable to test (Second attempt). Comments on MIT:

SALADAR UNIT 012

Active Injection - (All Types)

30-015-24179-00-00 K-33-20S-28E

Test Date:

8/19/2003 7:41:21 AM

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

9/22/2003

Test Type:

FAIL TYPE: Other External Failure

FAIL CAUSE:

Bradenhead Test

Comments on MIT: No company representative on location. Unable to test (Second attempt).

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are onot to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.