

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-015-20406

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
Skelly Unit

8. Well No.

108

9. Pool name or Wildcat

Grayburg Jackson

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Forest Oil Corporation

3. Address of Operator

707 17th Street, Suite 3600, Dever, CO 80202

4. Well Location

Unit Letter **A** : **660** feet from the **North** line and **660** feet from the **East** line

Section **15**

Township **17S**

Range **31E**

NMPM

County **Eddy**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

7/21/06 MIRU Rig and cementing equipment.

7/25/06 RU pulling unit, NDWH. NU BOP. WIH w/ tbg.. Tagged CICB @ 3281'. Load hole, Spot 125 sx cement @ 3281 to 2077'. Cug out cellar. (hole in surface casing). Spot 125 sx. cement @ 2077 to 873'. POH w/ tbg. CWI. WOC over night.

7/26/06 Tagged plug @ 1125'. Circ. hole w/ 160 sx cement @ 1125' to surface. POH w/ tbg. ND BOP Dug out cellar. Cut off WH. Install Dry hole markder. Rig down equipment. Cut off anchors.

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration, environmental remediation and final inspection is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE RD Ragland TITLE Senior Production Foreman DATE 8/12/06

Type or print name RD Ragland Telephone No. 505 392-9797
(This space for State use)

APPROVED BY Gerry Guye TITLE Deputy Field Inspector DATE SEP 21 2006
Conditions of approval, if any: District II - Artesia