Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised May 08, 2003 WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-03835	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	
District IV	Santa Fe, NIVI 8/303		6. State Oil & Gas Lease No.	
1220 S. St. Francis, Santa Fe, NM 87505			Fed LC 060398B	
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	CES AND REPORTS (19) WALS TO DRILL OR TO DESPEN OF THE TOTAL OR TO DESPEN (1) TO DESPE	DIVILUG BACK TO AS	7. Lease Name of West Henshaw	or Unit Agreement Name Premier Unit Tract 2
PROPOSALS.) 1. Type of Well:	232	AUGUNEON SON RECEIVED ARTESIA	8. Well Number	
		2		
2. Name of Operator	Name of Operator Saga Petroleum LLC		9. OGRID Number 148967	
3. Address of Operator 415 W. Wall, Suite 1900 Midland, TX 79701		271 91 21 A1 C1	10. Pool name or Wildcat	
4. Well Location		HENSHAW GRAYBURG		
Unit Letter K : 3329 feet from the N line and 1980 feet from the W line				
Section 3	Township 16S	Range 30E	NMPM	County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	ppropriate Box to Indic	· ·	•	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING REMEDIAL WORK ALTERING CASING REMEDIAL WORK REME				
PERFORM REMEDIAL WORK	PLOG AND ABANDON [REMEDIAL WOF	(K	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS[]	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE [COMPLETION	CASING TEST A CEMENT JOBS	ND	ADANDONWENT
OTHER:		OTHER: MIT for	TA status	[X]
13. Describe proposed or completion of starting and proposed we or recompletion.	eted operations. (Clearly stark). SEE RULE 1103. For N	te all pertinent details, ar fultiple Completions: Att	d give pertinent da ach wellbore diagra	ites, including estimated date am of proposed completion
8-25-03 Press up to 500 psi - held	I for 30 mins - good test wit	ness by OCD's gave - orig	ginal chart to Artes	ia OCD
8-25-03 Press up to 500 psi - held for 30 mins - good test witness by OCD's guye - original chart to Artesia OCD				
		F AN		
Femporary Abandoned Status coproved with 8-25-05				
		000		
I hereby certify that the information a	above is true and complete t	o the best of my knowled	ge and belief.	
SIGNATURE Bonnie S	Justanol TIT	LE Production Analyst		DATE 08/27/2003
Type or print name Bonnie Husba	and		Telep	hone No. (432)684-4293
(This space for State use)	000	A -111	775	
APPROVED BY	ン(ノ	SINVA W.	O APP	DOVED ALC DO 201
THI THOUGH I	TIT	LE COOL	U & AFF	KUNED AUG 4 8 20

