Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 30-015-22548 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Kennedy JQ Com PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Month - Year 2. Name of Operator 9. OGRID Number MAR - 8 2007 Yates Petroleum Corporation 025575 OCD - ARTESIA NIM 10. Pool name or Wildcat 3. Address of Operator 105 S. 4th Street, Artesia, NM 88210 Kennedy Farms Upper Penn 4. Well Location Unit Letter 2510 feet from the North line and 660 feet from the East line Section 33 Township 17S Range 26E **NMPM** Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3339'GR Pit or Below-grade Tank Application or Closure _ Depth to Groundwater ___ _ Distance from nearest fresh water well _ __ Distance from nearest surface water _ Pit Liner Thickness: Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON □ REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDON **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB П OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 2/21/07 - Set a 4-1/2" CIBP at 7031'. 2/22/07 - Tagged CIBP. Circulated plugging mud. Spotted 40 sx cement. 2/25/07 - Tagged at 6520'. 2/26/07 - Perforated at 5610'. Pumped 50 sx cement. WOC. Tagged at 4863'. 2/27/07 - Perforated at 4390'. 2/28/07 - Pumped 40 sx cement at 4448'. WOC. Tagged at 3920'. Perforated at 3450'. Pumped 50 sx cement and WOC. 3/1/07 - Tagged at 2250'. Perforated at 1493'. Pumped 50 sx cement and WOC. Tagged at 1242'. Perforated at 479'. Pumped 50 sx cement and WOC. 3/4/07 - Tagged at 208'. Perforated at 150'. Pumped 48 sx cement circulating to surface. Cut off wellhead. Installed dry hole marker. WELL IS PLUGGED AND ABANDONED. FINAL REPORT. Plugging of the well bore. Liability under bond is retained until surface restoration, environmental remediation and final inspection is remoleted I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines ____, a general permit _____ or an (attached) alternative OCD-approved plan _____. SIGNATURE (TITLE Regulatory Compliance Supervisor DATE March 7, 2007. Type or print name ___ Tina Huerta E-mail address: <u>tinah@ypcnm.com</u> Telephone No. <u>505-748-1471</u> 2007 For State Use Only MAR 8 APPROVED BY: TITLE Deputy Field Inspector Conditions of Apprøval (if any):