FORM APROVED UNITED STATES Form 3160-5 (August 1999) DEPARTMENT OF THE INTERIOR ALCUATE OMB NO. 1004-0135 **BUREAU OF LAND MANAGEMENT** EXPIRES: NOVEMBER 30, 2000 SUNDRY NOTICES AND REPORTS ON WELLS 5. Lease Serial No. Month - Year Do not use this form for proposals to drill or to re-enter an NM-110352 MAR 1 9 2007 abandoned well. Use Form 3160-3 (APD) for such proposals 6. If Indian, Allottee or Tribe Name OCD - ARTESIA, NM SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. 1a. Type of Well Oil Well Gas Well Other 8 Well Name and No. 2. Name of Operator **Bison Wallow Unit 1 DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No. 3. Address and Telephone No. 30-015-23112 10. Field and Pool, or Exploratory 20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-4615 4. Location of Well (Report location clearly and in accordance with Federal requirements)* Brushy Draw; Delaware, Nash 12. County or Parish 13. State 1980 FNL 660 FEL H 34 T25S R29E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deeper Production (Start/Resume) Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing ✓ Subsequent Report New Construction Recomplete Other Casing Repair Change Plans Plug and Abando Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal mpleted Operations (Clearly state all pertinent detail deepen directionally or recomplete horizontally, give subsurface location and measure and true vertical depths of an pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) 01/12/07 - 2/15/07

NM

MIRU. RIH w/ tubing and circulated hole with 9 ppg mud. Spot 45 Sx cement plug at 3100'. WOC. Tagged TOC at 2944'. Covers13-3/8" casing shoe at 3010'. Cut 9-5/8" casing at 2762'. POOH and lay down casing. TIH to 2810 and spot 55 Sx cement for stub plug. Tagged TOC at 2710'. Spot 65 Sx cement at 413'. Tagged TOC at 295'. Covers 20" casing shoe at 363'. Spot 40 Sx cement for 60' surface plug. Cut off well head and set dry hole marker. Plugged and Abandoned on 2/15/07.

Signed Round Slack	Name Title	Ronnie Slack Engineering Technician	Date	ACCEPTED FOR RECORD
(This space for Federal or State Office use) Approved by Conditions of approval, if any:	Title_		Date	MAR 1 5 2007 WESLEY W. INGRAM

