

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BP America Production Company

3a. Address

P.O. Box 1089 Eunice NM 88231

3b. Phone No. (include area code)

505.394.1600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL H, 1980' ENL & 560' FEL
Section 9, T18S, R27E

5. Lease Serial No.

NM025604

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement. Name and/or No.

NM 70945X - BM

8. Well Name and No.

Empire Abo Unit 801

"N"

9. API Well No.

30.015.00843

10. Field and Pool, or Exploratory Area

Empire Abo

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☒ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

ID: 5700' PSID: 5669' PERFS: 5210'-5220', 5260'-5270', 5280'-5300', 5320'-5330', 5360'-5400',
5460'-5475', 5485'-5520'

Drill out CIBP, perf upper Abo, and convert to rod pump, to return well to production, per attached Operations Summary report.

RTP 01/01/07

24 hr. well test: 01/03/07 - 30 bbl. oil, 15 bbls. water, 173 mcf gas.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Vicki Owens

Title

Administrative Assistant

Date 02/13/07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

MAR

Date
1 2007

FREDERICK WRIGHT
PETROLEUM ENGINEER

3/6/07

Operations Summary Report

Legal Well Name : EMPIRE ABO UNIT N #801

Common Well Name : EMPIRE ABO UNIT N #801

Event Name : WELL SERVICING

Contractor Name : KEY

Rig Name :

Start: 12/7/2006

Spud Date: 5/11/1959

End: 12/20/2006

Rig Release:

Rig Number: 174

Date	From - To	Hours	Task	Code	NPT	Phase	Description of Operations
12/7/2006	09:00 - 09:30	0.50		P		LOWER1	ROAD RIG
	09:30 - 10:30	1.00		P		LOWER1	RIG UP. SET IN RACKS, ETC.
	10:30 - 11:30	1.00		P		LOWER1	RIG UP. SET IN RACKS, ETC. NDWH. NUBOP. CHANGE WELLHEAD VALVES.
	11:30 - 15:00	3.50		N		LOWER1	WAIT ON TBG DELIVERY
	15:00 - 16:00	1.00		P		LOWER1	UNLOAD TBG
12/8/2006	16:00 - 17:30	1.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
12/11/2006	08:00 - 09:00	1.00		P		LOWER1	TALLY PIPE
	09:00 - 11:00	2.00		P		LOWER1	PU 100 JTS TBG
	11:00 - 11:30	0.50		P		LOWER1	TALLY PIPE
	11:30 - 12:30	1.00		P		LOWER1	TOH TO DERRICK W/ TBG
	12:30 - 14:00	1.50		P		LOWER1	TRAVEL TO HOBBS
	14:00 - 16:30	2.50		P		LOWER1	WAIT TIME DUE TO CHRISTMAS PARTY (BP)
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 09:00	1.00		P		LOWER1	PU COLLARS AND BIT
	09:00 - 10:30	1.50		P		LOWER1	PU TBGPU TBG AND TAG CIBP @ 5418'
	10:30 - 12:00	1.50		P		LOWER1	RU SWIVEL, STANDPIPE, AND DRILL LINE
	12:00 - 12:30	0.50		P		LOWER1	CREW LUNCH
	12:30 - 13:30	1.00		P		LOWER1	DRILL OUT CIBP
12/12/2006	13:30 - 14:45	1.25		P		LOWER1	TOH
	14:45 - 15:30	0.75		P		LOWER1	LAY DOWN SWIVEL, DRILL COLLARS, AND BIT
	15:30 - 16:00	0.50		P		LOWER1	RIH W/ KILL STRING
	16:00 - 17:30	1.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:30	1.25		P		LOWER1	JSA'S- PERFORATING
	08:30 - 09:30	1.00		P		LOWER1	TOH W/ KILL STRING
	09:30 - 11:00	1.50		N	WAIT	LOWER1	WAIT ON WIRELINE (THEY WERE RUNNING TBG PUNCH ON ADJACENT WELL)
	11:00 - 11:45	0.75		P		LOWER1	RU WIRELINE. HAD TO DRAG RACKS AROUND AND CLEAR LOCATION TO FIT
	11:45 - 16:00	4.25		P		LOWER1	PERFORATE. 2 JSPF- INCLUSIVE 5210-20, 5260-70, 5280-5300, 5320-30, 5360-5400, 5460-75, 5485-5520' 3 1/8 SLICK GUNS .42" ENTRY HOLES 36.7" PENETRATION
	16:00 - 16:30	0.50		P		LOWER1	RD WIRELINE
	16:30 - 17:30	1.00		P		LOWER1	RIH W/ KILL STRING
	17:30 - 19:00	1.50		P		LOWER1	TRAVEL TO HOBBS
12/13/2006	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 09:30	1.50		P		LOWER1	TOH W/ KILL STRING- SITP 350 PSI

Operations Summary Report

Legal Well Name : EMPIRE ABO UNIT N #801

Common Well Name : EMPIRE ABO UNIT N #801

Event Name : WELL SERVICING

Contractor Name : KEY

Rig Name :

Start: 12/7/2006 Spud Date: 5/11/1959

End: 12/20/2006

Rig Release:

Rig Number: 174

Date	From - To	Hours	Task	Code	NPT	Phase	Description of Operations
12/13/2006	09:30 - 11:00	1.50		P		LOWER1	SET RBP @ 5531' SET PKR @ 5129'
	11:00 - 12:30	1.50		P		LOWER1	DROP STD VALVE. TEST TBG STRING TO 3500 PSI W/ BACKSIDE LOADED AND PRESSURED TO 500 PSI.
	12:30 - 13:00	0.50		P		LOWER1	FISH STANDING VALVE
	13:00 - 13:45	0.75		P		LOWER1	SAFETY MEETING W/ ACID CREWS
	13:45 - 14:30	0.75		P		LOWER1	RIG UP ACID TRUCKS
	14:30 - 15:30	1.00		P		LOWER1	PUMP 6000 GALS 15% ANTI SLUDGE ACID. 6BPM AVG. 2950 PSI AVG. GOOD BALL ACTION AND BREAKS.
	15:30 - 16:30	1.00		P		LOWER1	RIG DOWN ACID TRUCKS AND CLEAR AND CLEAN LOCATION
12/14/2006	16:30 - 17:30	1.00		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO OFFICE
	06:30 - 07:00	0.50		P		LOWER1	SAFETY MEETING
	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 08:30	0.50		P		LOWER1	RU SWAB SITP 350 PSI
	08:30 - 14:00	5.50		P		LOWER1	SWAB 6 RUNS 42 BBLs 25-30% OIL CUT AND GAS FLOWING
12/15/2006	14:00 - 15:30	1.50		N	WAIT	LOWER1	WAIT ON ROUSTABOUTS TO HOOK UP FLOWLINE AT BATTERY AND BRING FLOWLINE INTO LOCATION. WIND DIRECTION CHANGES SET OFF H2S ALARMS. UNABLE TO SWAB TO PIT DUE TO SAFETY REASONS. WELL PRESSURED UP 125 PSI DURING 1.5 HOUR SHUT IN PERIOD.
	15:30 - 16:30	1.00		P		LOWER1	SWAB 1 RUN 3 BBLs. INITIAL FL 4400'. ENDING FL 4400'. INTERPHASE @ 4100'.
	06:30 - 18:00	11.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 07:00	1.50		P		LOWER1	TRAVEL TO LOCATION
	07:00 - 07:30	0.50		P		LOWER1	JSA
	07:30 - 15:30	8.00		P		LOWER1	SWAB 17 RUNS. INITIAL FL @ 4100' ENDING FL @ 3800'-STARTED COMING UP AFTER 12 RUNS (46 BBLs)
	15:30 - 16:00	0.50		N	WAIT	LOWER1	GAS TO TESTER FLOWING 55 MCF 20% OIL CUT
12/18/2006	16:00 - 17:30	1.50		P		LOWER1	WAIT ON ELECTRIC COMPANY- CHANGING HIGHLINE WIRES. SHUT DOWN TO KEEP GAS AWAY FROM THEM
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO HOBBS
	06:30 - 07:00	0.50		P		LOWER1	TRAVEL TO OFFICE
	07:00 - 07:15	0.25		P		LOWER1	SAFETY MEETING
	07:15 - 08:00	0.75		P		LOWER1	TRAVEL TO LOCATION
	08:00 - 08:30	0.50		P		LOWER1	JSA'S
	08:30 - 09:00	0.50		P		LOWER1	KILL WELL
12/19/2006	09:00 - 09:30	0.50		P		LOWER1	UNSET PKR
	09:30 - 10:00	0.50		P		LOWER1	PU TBG TO CATCH RBP
	10:00 - 12:00	2.00		P		LOWER1	LATCH ON AND RELEASE RBP
	12:00 - 12:30	0.50		P		LOWER1	TOH W/ TBG
	12:30 - 13:00	0.50		P		LOWER1	CREW LUNCH
	13:00 - 15:00	2.00		P		LOWER1	PU BHA AND TACLD PKR AND RBP. PU BHA AND TAC
	15:00 - 16:00	1.00		P		LOWER1	TIH W/ TBG. SET TAC.
12/19/2006	16:00 - 17:30	1.50		P		LOWER1	NDBOP NUWH
	05:30 - 06:30	1.00		P		LOWER1	TRAVEL TO HOBBS
	06:30 - 07:00	0.50		P		LOWER1	TRAVEL TO OFFICE
				P		LOWER1	SAFETY MEETING

Operations Summary Report

Legal Well Name : EMPIRE ABO UNIT N #801

Common Well Name : EMPIRE ABO UNIT N #801

Event Name : WELL SERVICING

Contractor Name : KEY

Rig Name :

Start: 12/7/2006 Spud Date: 5/11/1959
End: 12/20/2006

Rig Release:

Rig Number: 174

Date	From - To	Hours	Task	Code	NPT	Phase	Description of Operations
12/19/2006	07:00 - 07:15	0.25		P		LOWER1	TRAVEL TO LOCATION
	07:15 - 08:00	0.75		P		LOWER1	JSA'S
	08:00 - 09:00	1.00		N	WAIT	LOWER1	RAIN SLOWING DOWN PROCESSES, PROCEEDING SLOWLY DUE TO MUD AND SLIPPERY CONDITIONS, AND DECREASED VISIBILITY. SLOWED PROCESSES THROUGHOUT THE DAY.
	09:00 - 12:00	3.00		P		LOWER1	PU RODS AND PUMP AND TIH
	12:00 - 12:30	0.50		P		LOWER1	CREW LUNCH
	12:30 - 14:00	1.50		P		LOWER1	PU RODS AND PUMP AND TIH
	14:00 - 16:00	2.00		N	WAIT	LOWER1	WAIT FOR ELECTRICITY TO ROLL UNIT. NEED TO CHECK PUMP ACTION, SPACE WELL, AND ALSO NEED UNIT IN DOWNSTROKE POSITION TO BE ABLE TO RIG DOWN
12/20/2006	16:00 - 17:30	1.50		P		LOWER1	TRAVEL TO HOBBS
	05:30 - 07:30	2.00		P		LOWER1	TRAVEL TO LOCATION-WEATHER SLOWED THE TRIP
	07:30 - 08:00	0.50		P		LOWER1	JSA'S
	08:00 - 10:00	2.00		N	WAIT	LOWER1	WAIT ON ELECTRICIANS
	10:00 - 10:30	0.50		P		LOWER1	CHECK PUMP ACTION, SPACE OUT
	10:30 - 12:00	1.50		P		LOWER1	RIG DOWN