

N.M. Oil Cons. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

Form 3160-5
(February 2005)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator **NEW MEXICO INSTITUTE OF MINING & TECHNOLOGY**

3a. Address **D.Cox, SNL MS 0778, Box 5800, Albuquerque, NM 87185-0778**
3b. Phone No. (include area code) **505-284-3871**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FNL 660 FEL U/L A SEC 24 T15S R29E

5. Lease Serial No.

LC069/280-C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SULIMAR QUEEN UNIT

8. Well Name and No.

SULIMAR QUEEN UNIT TR 3 #1

9. API Well No.

30-005-60042

10. Field and Pool, or Exploratory Area

SULIMAR QUEEN

11. County or Parish, State

CHAVES COUNTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

SEE ATTACHMENT

Accepted for record
NMOCD

APPROVED AS TO PLUGGING OF THIS
WELL BORE. LIABILITY UNDER BOND
IS RETAINED UNTIL SURFACE RESTORATION
IS COMPLETED

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

JACK B. TILLMAN

Title

SNL Field Representative

Signature

Jack B. Tillman

Date

03/16/07

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by **/S/ DAVID R. GLASS**

PETROLEUM ENGINEER

Date

MAR 20 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

NEW MEXICO INSTITUTE OF MINING & TECHNOLOGY

Lease: SULIMAR QUEEN UNIT TR 3 # 1

Project: P & A - CEMENTING REPORT

API # 30-005-60042

03-17-06 - SPOT 25 SXS @ 1984'-1918' TAGGED
03-17-06 - CUT @ 1350' - TEST TO 500#
03-17-06 - SPOT 65 SXS @ 1417'-988' & TAG
03-20-06 - CUT @ 504' - TEST TO 500#
03-20-06 - SPOT 25 SXS @ 567'-440' & TAG
03-20-06 - SPOT 10 SXS @ 440'-400'
03-20-06 - PERFORATE @ 180' - TEST TO 1000#
03-20-06 - SPOT 45 SXS @ 220'-15' & TAG
03-21-06 - SPOT 5 SXS @ 15' TO SURFACE

INSTALL DRY HOLE MARKER
CIRCULATE 10# MUD