Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

APR 1 5 7004

FORM APPROVED

OMB No. 1004-0135-Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No.

Do not use this form for proposals to drill or re enter an OCD-AHIESIA abandoned well. Use Form 3160-3 (APD) for such proposals.					NM-100831		
					6. If Indian, Allottee or Tribe Name N/A		
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Oil Well Gas Well Other					8. Well Name and No.		
2. Name of Operator					BAT ARO FEDERAL #1		
Yates Petroleum Corporation					9. API Well No.		
3a. Address 3b. Phone No. (include area code)					30-015-25874	ļ	
105 S. 4th Str., Artesia, NM 88	505-748-1471			10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)					CROOKED CRE	EK UPPER PENN	
					11. County or Parish, State		
Section 34-T23S-R24E 2,210' FNL & 660' FWL Unit: E					EDDY COUNTY, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE					PORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
	Acidize	Deepen	[Production (S	tart/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat Reclamatio			Well Integrity		
	Casing Repair	New Cor	struction	Recomplete	Ī	Other	
Subsequent Report	X Plug and	-	=	erarily Abandon			
		7	=				
Final Abandonment Notice	Convert to Injection	Plug Back	·	Water Dispos	ai		
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 3/26-28/04 - Pumped 100 bbls brine to kill well. ND wellhead. NU BOP. Released packer. POOH w/ 20 joints. SI. SD. 3/29/04 - Opened well. Killed well. POOH w/ 244 joints 2-7/8" tubing and packer. RIH w/ on/off tools and 60 joints. SI. SD. 3/30/04 - Opened well. RIH w/ on/off tool. Latched onto plug. Worked plug loose. POOH w/ tubing & packer plug. RIH w/ 60 joints tubing for kill string. SI. SD. 3/31/04 - POOH w/ 60 joints kill string. RU WL. RIH w/ 5-1/2" CIBP. Set at 8,555'. POOH w/ WL. Made 2 dump bailer runs on top of CIBP. TOC at 8,520'. POOH w/ bailer. Re-dress setting tool. RIH w/ 5-1/2" CIBP, set at 7,986'. POOH w/ WL. RD WL. RIH w/ 60 joints 2-7/8" tubing. SI. SD. 4/1/04 - Opened well. RIH w/ tubing. Tagged CIBP at 7,986'. Circulated hole w/ mud laden fluid. Spotted 25 sx Class C Neat cement at 7,986' to 7,733'. PUH to 5,433'. Loaded hole w/ mud. Spotted 25 sx Class C Neat cement at 5,433'-5,180'. PUH to 2,651'. SI. SD.							
See attached sheet: 4. I hereby certify that the foregoing is true and correct Name (Printed/Typed)							
 I hereby certify that the foregoing is true and c Name (Printed/Typed) 	prect	la scor					
Su'Ann Rogers	Moreon	Title	Regulator	y Complian	ce Tech.		
Signature Si An Rogula Date April 13, 2004							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by			Title		Date	1	
Conditions of approval, if any, are attached. Appropriately that the applicant holds legal or equitable which would entitle the applicant to conduct operat	title to those rights in the		Office		<u>.</u>		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Yates Petroleum Corporation Bat ARO Federal #1 34-23S-24E Eddy County, New Mexico

Form C-103 Continued:

- 4/2-4/04 Opened well. Loaded hole w/ mud. Spotted 25 sx Class C Neat cement at 2,651'. POOH w/ tubing. WOC 4 hrs. RIH w/ tubing. Tagged plug at 2,328'. Pulled up to 491'. Circulated 50 sx Class C Neat cement at 491' to surface. POOH w/ tubing. ND BOP. SD.
- 4/7/04 Dug out cellar. Cut off wellhead. Installed dry hole marker as per regulations. RD. Well Plugged & Abandoned on 4/7/04. PLUGGED & ABANDONED. FINAL REPORT.

Please notify Jim Krogman (505-365-8340) 3 days prior to BLM inspection, so we have the opportunity to meet with the inspector on location to confirm all reclamation requirements before receiving the notice of written order.