Description Page	Submit 3 Copies To Appropriate District Sta	ate of New Mexico		Form C-103	
APPROVED BY: Approximation	Office District I Energy, Mi	nerals and Natural Resou	rcesJUN 1 4 2007	May 27, 2004	
DOR NOT USE THE FROM STATE	TICOS N. F. and Dr. Habba ND (0024)		WELL API N	Э.	
DOR NOT USE THE FROM STATE	JDistrict II 1301 W Grand Ave Artesia NM 88210 OIL CON	SERVATION DIVISION	OQCD-ARTESIA	30-015-30703	
South Brack Rd, Amer, NMS-210 South Fe, NM 87505 South Fe, NM 8750		South St. Francis Dr.	5. Indicate Ty	pe of Lease	
12.0 S. Francis Dr., Sania Fr. R. M. 1.2 St. Francis Dr., Sania Francis Dr., Sa	1000 Rio Brazos Rd., Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS TOD NOT USE THIS FORM FOR PROVISAL STO DRILL OR TO DEPEN OR PLIG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PREMIT (FORM-CHI) FOR SUCH I. Type of Well: Oil Well Gas Well Other B. Well Number 16 2. Name of Operator 9. OGRID Number 104/021 3. Address of Operator 9. OGRID Number 104/021 4. Well Location 17. Township 21-S Range 24-E NMPM County Eddy 4. Well Location 18. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,914' GR 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,914' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 13. Describe proposed or completed operations. Clearly state all pertinent detail. Liapitity Ministra Special Statement of Statement of Statement of Statement Statement of Statement Sta	~ 1001 V 1	illa PC, INIVI 67505	6. State Oil &	I	
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFERNOR PLUG BACK TO A DISPERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS		١		E-/43/	
Indian Hills Unit NM-70964-B	SUNDRY NOTICES AND REPORT	RTS ON WELLS	7. Lease Nam	e or Unit Agreement Name	
RROPOSALS Type of Well: Oil Well Gas Well Other S. Well Number 16			OA		
1. Type of Well: Oil Well Gas Well Other S. Well Number 10		I" (FORM C-101) FOR SUCH	Indian Hil	Indian Hills Unit NM-70964-B	
2. Name of Operator Marathon Oil Company ATTN: Charles E. Kendrix 9. OGRID Number 1021 3. Address of Operator P.O. Box 3487 Houston, Texas 77253-3487 4. Well Location Unit Letter E 2,200 feet from the Porth line and 660 feet from the West line Section 17 Township 21-S Range 24-E NMPM County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914* GR Pit Upe_STEEL Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water _N/A Pit Liner Thickness: STEEL Im Pepth to Groundwater Distance from nearest fresh water well StEEL StEEL Township 21-S Range 24-E NMPM County Eddy 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK Q-LUG AND ABANDON CHANGE PLANS COMMENCE PRILLING OPPS P AND A LTERING CASING CASING CEMPT COMMENCE PRILLING OPPS P AND A LTERING CASING COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT COMMENCE DRILLING OPPS P AND A LTERING CASING CASING/CEMPT CASING CASING CASING/CEMPT CASING CASING CASING CASING CASING CASING/CEMPT CASING C		her	8. Well Numb	8. Well Number 16	
Marathon Oil Company ATTN: Charles E. Kendrix 10. Pool name or Wildcat Indian Basin (Morrow)			9 OGRID Nu	ımher	
3. Address of Operator 10. Pool name or Wildest 1. Molan Basin (Morrow) 1. Well Location 1. Well Location 1. Well Location 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 ° GR 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3.914 °		TTN: Charles E. Kendrix			
4. Well Location P.O. Box 3487 Houston, Texas 77253-3487 Indian Basin (Morrow) 4. Well Location Unit Letter E 2,200 feet from the North line and 660 feet from the West line Section 17					
Well Location	1	xas 77253-3487			
Unit Letter E : 2,200 feet from the North line and 660 feet from the West line Section 17 Township 21-S Range 24-E NMPM County Eddy II. Elevation (Show whether DR, RKB, RT, GR, etc.)			<u></u>		
Section 17 Township 21-S Range 24-E NMPM County Eddy 11. Elevation (Norw whether DR, RKB, RT, GR, etc.) 3.914' GR Pit or Below-grade Tank Application or Cleasure Distance from nearest surface water N/A Pit time Thickness: STEEL Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water N/A Pit Liner Thickness: STEEL mill Below-Grade Tank: Volume 180 bbls; Construction Material STEEL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS PAND A PULL OR ALTER CASING MULTIPLE COMPL OTHER:		the North line	and 660 fact fro	m the West line	
II. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,914' GR					
Section Sect				County Eddy	
Pit type_STEEL Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water _N/A			GR, etc.)	100	
Pit type_STEELDepth to Groundwater					
Pit Liner Thickness: STEEL mil Below-Grade Tank: Volume 180 bbls; Construction Material STEEL	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPINS PAND A P	Pit type_STEEL Depth to Groundwater Dis	tance from nearest fresh water v	well Distance fron	ı nearest surface waterN/A	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS ALTERING CASING PLUL OR ALTERING CASING PLUL OR ALTERING CASING PULL OR ALTERING CASING COMMENCE DRILLING OPPNS PAND A CASING/CEMENT JOING OF PAND A CASING OF PAND A CASIN	Pit Liner Thickness: STEEL mil Below-Grade	Tank: Volume180	_bbls; Construction Materi	alSTEEL	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS ALTERING CASING PLUL OR ALTERING CASING PLUL OR ALTERING CASING PULL OR ALTERING CASING COMMENCE DRILLING OPPNS PAND A CASING/CEMENT JOING OF PAND A CASING OF PAND A CASIN	12 Check Appropriate Box	to Indicate Nature of	Notice Report or Oth	ier Data	
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OR OTHER: THER. PAND A PAND A PAND A CASING/CEMENT OR OTHER: THER. PAND A P	12. Check rippropriate Box	to majoute ratare or	r voltee, resport or our	ior Bata	
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OR OTHER: THER. PAND A PAND A PAND A CASING/CEMENT OR OTHER: THER. PAND A P	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMPLINGING of the well bore. 13. Describe proposed or completed operations. (Clearly state all pertinent details, in bill, muthat apply in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the state of starting any proposed work). SEE RULE 1103. For Multiple Completions in the starting any proposed work). SEE RULE 1103. For Multiple Completions in the starting and starting any proposed work). SEE RULE 1103. For Multiple Completions in the starting any proposed completion or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAGRAM 06/04 - 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300". POOH w/ tubing. Cut casing at 6,033", not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ two packer. BLH w/ two packer. SDFN. 06/08/07 RIH w/ two packer. RIH w/ w/ packer. SDFN. 06/08/07 RIH w/ two packer. RIH w/ two packer. SDFN. 06/08/07 RIH w/ two packer. SDFN. 06/08/07 RIH w/ two packer. RIH w/ two packer. SDFN. 06/08/07 RIH w/ two packer. RIH w/ two packer. SDFN. 06/08/07 RIH w/ two packer. RIH w/ two packer. SDFN. 06/08/07 RIH w/ two packer. RIH w/ two packer. SDFN. 06/08/07 RIH w/ two packer. RIH w/ two packer					
13. Describe proposed or completed operations. (Clearly state all pertinent details, the way talked all assistating any proposed work). SEE RULE 1103. For Multiple Completions United Success (Section 1974) Proposed completion or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAGRAM 06/04 - 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300". Circulated hole w/ mud. SDFN. 06/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 - 8,930". POOH w/ tubing. Cut casing at 6,033", not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109" and pumped 25 sx C cmt @ 6,109". WOC & tagged cmt @ 5,740". Cut casing @ 4,458". Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519". RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519". POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332". Pumped 40 sx C cmt 3,210 - 3,068". Pumped 50 sx C cmt w/ 2% Cacl ₂ @ 2,462". POOH w/ tubing and WOC. Tagged cmt @ 2,303". Pumped 40 sx C cmt 848 - 730". Pumped 20 sx C cmt 60" to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or clored/sccording to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye DATE	-				
13. Describe proposed or completed operations. (Clearly state all pertinent details, the way talked all assistating any proposed work). SEE RULE 1103. For Multiple Completions United Success (Section 1974) Proposed completion or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAGRAM 06/04 - 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300". Circulated hole w/ mud. SDFN. 06/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 - 8,930". POOH w/ tubing. Cut casing at 6,033", not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109" and pumped 25 sx C cmt @ 6,109". WOC & tagged cmt @ 5,740". Cut casing @ 4,458". Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519". RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519". POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332". Pumped 40 sx C cmt 3,210 - 3,068". Pumped 50 sx C cmt w/ 2% Cacl ₂ @ 2,462". POOH w/ tubing and WOC. Tagged cmt @ 2,303". Pumped 40 sx C cmt 848 - 730". Pumped 20 sx C cmt 60" to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or clored/sccording to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye DATE	PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB CASING				
13. Describe proposed or completed operations. (Clearly state all pertinent details, the way talked all assistating any proposed work). SEE RULE 1103. For Multiple Completions United Success (Section 1974) Proposed completion or recompletion. SEE ATTACHED PLUGGED WELLBORE DIAGRAM 06/04 - 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300". Circulated hole w/ mud. SDFN. 06/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 - 8,930". POOH w/ tubing. Cut casing at 6,033", not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109" and pumped 25 sx C cmt @ 6,109". WOC & tagged cmt @ 5,740". Cut casing @ 4,458". Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519". RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519". POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332". Pumped 40 sx C cmt 3,210 - 3,068". Pumped 50 sx C cmt w/ 2% Cacl ₂ @ 2,462". POOH w/ tubing and WOC. Tagged cmt @ 2,303". Pumped 40 sx C cmt 848 - 730". Pumped 20 sx C cmt 60" to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or clored/sccording to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye DATE	OTHER: OTHER: OTHER: OTHER:				
of starting any proposed work). SEE RULE 1103. For Multiple Completions. Interest to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be mastrycted or class dates. SEE ATTACHED PLUGGED WELLBORE DIAGRAM 06/04 - 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300'. Circulated hole w/ mud. SDFN. 06/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 - 8,930'. POOH w/ tubing. Cut casing at 6,033', not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5,740'. Cut casing @ 4,458'. Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519'. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 - 3,068'. Pumped 50 sx C cmt w/ 2% CaCl ₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 - 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be unsattrycted or class for the control of the coordinate of the coordinat	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
environmental remediation and final inspection (secompleted.) SEE ATTACHED PLUGGED WELLBORE DIAGRAM 06/04 - 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300'. Circulated hole w/ mud. SDFN. 06/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 - 8,930'. POOH w/ tubing. Cut casing at 6,033', not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5,740'. Cut casing @ 4,458'. Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519'. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 - 3,068'. Pumped 50 sx C cmt w/ 2% CaCl ₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 - 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or classificoording to NMOCD guidelines \(\mathbb{\overline{1}\), a general permit \(\mathbb{\overline{1}\) or an (attached) alternative OCD-approved plan \(\mathbb{\overline{1}\). SIGNATURE TITLE \(\mathbb{James F. Newman, P.E. (Triple N Services) DATE \(\mathbb{\overline{1}\) 06/13/07 Type or print name Fe-mail address: \(\mathbb{jim_approved plan \) \(\mathbb{\overline{1}\) DATE OATE	of starting any proposed work). SEE RULE 1103. For Multiple Completions Interest and Completion				
96/04 – 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300°. Circulated hole w/ mud. SDFN. 96/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 – 8,930°. POOH w/ tubing. Cut casing at 6,033°, not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 96/08/07 RIH w/ tubing to 6,109° and pumped 25 sx C cmt @ 6,109°. WOC & tagged cmt @ 5,740°. Cut casing @ 4,458°. Casing free. SD for weekend. 96/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519°. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519°. POOH w/ tubing and SDFN. 96/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332°. Pumped 40 sx C cmt 3,210 − 3,068°. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462°. POOH w/ tubing and WOC. Tagged cmt @ 2,303°. Pumped 40 sx C cmt 848 − 730°. Pumped 20 sx C cmt 60° to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be observed plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 96/13/07 Type or print name E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye JUN 1 5 2007 DATE	or recompletion. environmental remediation and				
96/04 – 06/06/07 Notified NMOCD. MIRU Triple N rig #24 & plugging equipment. NU BOP. POOH w/ tubing & packer. RIH w/ 4½" CIBP. Set CIBP @ 9,300°. Circulated hole w/ mud. SDFN. 96/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 – 8,930°. POOH w/ tubing. Cut casing at 6,033°, not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 96/08/07 RIH w/ tubing to 6,109° and pumped 25 sx C cmt @ 6,109°. WOC & tagged cmt @ 5,740°. Cut casing @ 4,458°. Casing free. SD for weekend. 96/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519°. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519°. POOH w/ tubing and SDFN. 96/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332°. Pumped 40 sx C cmt 3,210 − 3,068°. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462°. POOH w/ tubing and WOC. Tagged cmt @ 2,303°. Pumped 40 sx C cmt 848 − 730°. Pumped 20 sx C cmt 60° to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be observed plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 96/13/07 Type or print name E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye JUN 1 5 2007 DATE	final inspection is completed.				
4½" CIBP. Set CIBP @ 9,300'. Circulated hole w/ mud. SDFN. 06/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 − 8,930'. POOH w/ tubing. Cut casing at 6,033', not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5,740'. Cut casing @ 4,458'. Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519'. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 − 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 − 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye TITLE Deputy Field inspector	SEE ATTACHED PLUGGED WELLBORE DIAG	RAM		•	
4½" CIBP. Set CIBP @ 9,300'. Circulated hole w/ mud. SDFN. 06/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 − 8,930'. POOH w/ tubing. Cut casing at 6,033', not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5,740'. Cut casing @ 4,458'. Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519'. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 − 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 − 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye TITLE Deputy Field inspector					
O6/07/07 NMOCD, Phil Hawkins on location. Pumped 25 sx C cmt 9,300 – 8,930'. POOH w/ tubing. Cut casing at 6,033', not free. RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. O6/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5,740'. Cut casing @ 4,458'. Casing free. SD for weekend. O6/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519'. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519'. POOH w/ tubing and SDFN. O6/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 − 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 − 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Genry Guye JUN 1 5 2007 DATE			ent. NU BOP. POOH w	tubing & packer. RIH w/	
RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN. 06/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5,740'. Cut casing @ 4,458'. Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519'. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 – 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 – 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed/secording to NMOCD guidelines \(\times \), a general permit \(\times \) or an (attached) alternative OCD-approved plan \(\times \). SIGNATURE TITLE \(\times \) Ageneral permit \(\times \) or an (attached) alternative OCD-approved plan \(\times \). E-mail address: \(\times \) jim@triplenservices.com \(\times \) Telephone No. 432-687-1994 \(\times \) Gerry Guye JUN 15 2007 DATE	4½" CIBP. Set CIBP @ 9,300'. Circulated hole w/ mi	id. SDFN.			
06/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5,740'. Cut casing @ 4,458'. Casing free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½' casing. RIH w/ tubing to 4,519'. RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 − 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 − 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE			0'. POOH w/ tubing. Cu	t casing at 6,033', not free.	
free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519". RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519". POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332". Pumped 40 sx C cmt 3,210 – 3,068". Pumped 50 sx C cmt w/ 2% CaCl2 @ 2,462". POOH w/ tubing and WOC. Tagged cmt @ 2,303". Pumped 40 sx C cmt 848 – 730". Pumped 20 sx C cmt 60" to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed/according to NMOCD guidelines \(\text{\sigma}\), a general permit \(\text{\sigma}\) or an (attached) alternative OCD-approved plan \(\text{\sigma}\). SIGNATURE TITLE \(\text{James F. Newman, P.E. (Triple N Services)}\) DATE \(\text{\sigma}\) DATE 6erry Guye JUN 1 5 2007 DATE	RIH w/ packer, no rate @ 1,650 psi. POOH w/ packer. SDFN.				
free. SD for weekend. 06/11/07 RU casing tools and POOH w/ 4½" casing. RIH w/ tubing to 4,519". RU cementer, loaded hole w/ mud, and pumped 70 sx C cmt @ 4,519". POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332". Pumped 40 sx C cmt 3,210 – 3,068". Pumped 50 sx C cmt w/ 2% CaCl2 @ 2,462". POOH w/ tubing and WOC. Tagged cmt @ 2,303". Pumped 40 sx C cmt 848 – 730". Pumped 20 sx C cmt 60" to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed/according to NMOCD guidelines \(\text{\sigma}\), a general permit \(\text{\sigma}\) or an (attached) alternative OCD-approved plan \(\text{\sigma}\). SIGNATURE TITLE \(\text{James F. Newman, P.E. (Triple N Services)}\) DATE \(\text{\sigma}\) DATE 6erry Guye JUN 1 5 2007 DATE	06/08/07 RIH w/ tubing to 6,109' and pumped 25 sx C cmt @ 6,109'. WOC & tagged cmt @ 5.740'. Cut casing @ 4.458'. Casing				
cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 − 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 − 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name For State Use Only Genry Guye JUN 1 5 2007 DATE	* · ·		(3 + 7, + 1 + + + + + + + + + + + + + + + + +	g	
cmt @ 4,519'. POOH w/ tubing and SDFN. 06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 − 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 − 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name For State Use Only Genry Guye JUN 1 5 2007 DATE	06/11/07 PH casing tools and POOH w/ 41/2 casing	PILL w/ tubing to 4 510' D	II comenter leaded heles	w/mud and numned 70 av C	
06/12/07 NMOCD Ron Harvey on location. Tagged cmt @ 4,332'. Pumped 40 sx C cmt 3,210 – 3,068'. Pumped 50 sx C cmt w/ 2% CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 – 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name Fe-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Gerry Guye JUN 1 5 2007 DATE		XIII w/ tubing to 4,319. K	o cementer, loaded note	w/ mud, and pumped /0 sx C	
CaCl₂ @ 2,462'. POOH w/ tubing and WOC. Tagged cmt @ 2,303'. Pumped 40 sx C cmt 848 – 730'. Pumped 20 sx C cmt 60' to surface. POOH w/ tubing. ND BOP, RDMO. Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name For State Use Only APPROVED BY: TITLE Deputy Field Inspector DATE		. O . 1.0001 P 1.40	G (2010 0000)	D 150 G . /00/	
SIGNATURE Title James F. Newman, P.E. (Triple N Services) E-mail address: jim@triplenservices.com Title Deputy Field Inspector Title Deputy Field Inspector DATE DATE					
Cut wellhead and anchors, installed dry hole marker, backfilled cellar. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Gerry Guye JUN 1 5 2007 DATE DATE		cmt @ 2,303°. Pumped 40) sx C cmt 848 – /30°. Pu	imped 20 sx C cmt 60° to	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ⋈, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name For State Use Only APPROVED BY: TITLE Deputy Field Inspector DATE DATE	surface. FOOH w/ tubling. ND BOF, KDMO.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ⋈, a general permit □ or an (attached) alternative OCD-approved plan □. SIGNATURE TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name For State Use Only APPROVED BY: TITLE Deputy Field Inspector DATE DATE	Cut wellhead and anchors installed dry hole marker by	ackfilled cellar			
grade tank has been/will be constructed or closed/according to NMOCD guidelines ⊠, a general permit ☐ or an (attached) alternative OCD-approved plan ☐. SIGNATURE	Cut weimead and anemors, instance dry note marker, be	terrined certair.			
TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name For State Use Only APPROVED BY: TITLE Deputy Field Inspector DATE	I hereby certify that the information above intrue and c	omplete to the best of my k	nowledge and belief I for	erther cartify that any nit or below	
TITLE James F. Newman, P.E. (Triple N Services) DATE 06/13/07 Type or print name For State Use Only APPROVED BY: TITLE Deputy Field Inspector DATE DATE					
Type or print name For State Use Only APPROVED BY: E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Gerry Guye TITLE Deputy Field Inspector DATE	And I	· - / 0	` /	–	
Type or print name For State Use Only APPROVED BY: E-mail address: jim@triplenservices.com Telephone No. 432-687-1994 Gerry Guye TITLE Deputy Field Inspector DATE	SIGNATURE / 9	TITLE James F. Ne	ewman, P.E. (Triple N S	ervices) DATE <u>06/13/07</u>	
APPROVED BY: Gerry Guye TITLE Deputy Field Inspector DATE					
APPROVED BY: Conditions of Approval (if any): Gerry Guye Deputy Field Inspector District II - Artesia		E-mail address: jin	n@triplenservices.com	Telephone No. 432-687-1994	
APPROVED BY: Conditions of Approval (if any): TITLE Deputy Field Inspector District II - Artesia	For State Use Only	Ca	arry Guve	HIN = = 2007	
APPROVED BY: / TITLE DATE Conditions of Approval (if any): Date:	Muy on				
Conditions of Approval (if any):	APPROVED BY:			DATE	
	Conditions of Approval (if any):	₩	*		

GL Elev:3914'

Indian Hills Unit NM-70964-B #2

County: Eddy

State: New Mexico

Location: 2200' FNL & 660' FWL

Section17, T-21-S, R-24-E UL "E" API#: 30-015-30703

Spud Date: TD:12,503'

Diagram Date: 6/12/2007

40 sx C cmt @ 848 - 730'

20 sx C cmt 60' to surface

TOC @ surface

9-5/8" 36# /ft J-55 casing @ 2,408', cmt'd w/ 1,660 sks

50 sx 2,462 - 2,303' (surface casing shoe plug) TAGGED

40 sx C cmt @ 3,210 -3,068' cut & pull 4,458' 41/2" csg

70 sx C cmt @ 4,519 -4,332' TAGGED

25 sx C cmt @ 6,109 - 5,740' TAGGED cut casing @ 6,003'. Unable to pull csg or squeeze @ 1,650 psi

25 sx C cmt @ 9,300- 8,930' Set CIBP @ 9,300'

9,324 -9,357 (Atoka)

CIBP set @ 9,550' w/ 35 sx cmt

9,626 - 9,707' (Morrow)

4-1/2" 11.6#/ft n-80 casing @ 9,868' cmt'd w/ 974 sx cmt PBTD: 9,821' TD: 9,875'